		PARK CERTI	FICATION			
PARK: Joshua Ci	ity Park and Bal	field		DATE:7/25/2025		TOTAL % SCORE
				START/FINISH TIME	E: 9am-11am	
INSPECTED BY:	Steven Gill/ M	ichael Rickard				88.1%
				RATING		00.170
CAMICAND	<b>N</b> Y/ 4	Added TVING CTUANS AND CALLED			CONDITION	
CHECKED	N/A	***** TURF STANDARDS *****		LOW (1-5) HIGH	COMMENTS	
<b>~</b>		Irrigated turf uniform green in color during growing season.		4		
~		2. No large accumulations of grass clippings. No thatch build-up.		5		
~		3. No visible litter on turf area.		5		
$\overline{V}$	- i	4. Turf area 90% free of fire ant infestation.		5		
$\overline{\mathbf{v}}$	- i	5. Turf crisply edged.		5		
<u> </u>	- F	6. Turf trimmed around fence lines and trees.		5		
<u> </u>		7. Turf 90% free of weeds.		3	Open spaces at the park have a substantial amoun	of weeds.
$\overline{v}$		8. No large areas of standing water.		5		
<b>V</b>	- i	9. No large bare spots in irrigated turf areas.		3	prior construction zones have bare spots. The grass is gr	owing back slowly
		10. Turf free of holes and other tripping hazards.		3	The crew has been filling the holes and low spots.	
10	0		SUB-TOTALS	43	POSSIBLE SCORE:	
COMMENTS:					TOSSIBLE SCORE.	30
CONTINENT					% AVERAGE:	86.0%
CHECKED	N/A	***** TREE STANDARDS *****		LOW (1-5) HIGH	COMMENTS	
<b>✓</b>		Pruned to appropriate size and shape with suckers and water sprouts removed.		4		
<b>~</b>		2. Limbed to safe height (8ft minimum) and away from buildings.		4		
<b>~</b>		3. No low limbs over parking lots, trails, picnic sites, or roadways.		5		
<b>~</b>		4. No signs of disease or pest damage.		4		
<b>~</b>		5. Dead or dying branches removed. All dead trees removed.		3	Some trees at the park have dead branches. Sched	uled for maintenance
	<b>✓</b>	6. Tree wells contain a maximum of 3" of mulch.		0		
	<b>~</b>	7. Trees staked properly if required.		0		
5	2		SUB-TOTALS	20	POSSIBLE SCORE:	25
COMMENTS:				20	POSSIBLE SCORE.	23
COMMENTS					% AVERAGE:	80.0%
						1
CHECKED	N/A	***** PIAYGROUND STANDARDS *****		LOW (1-5) HIGH	COMMENTS	
~		1. swings, seats, and chains (cut, cracked, missing, twisted, worn, broken)		5		
<b>✓</b>		2. hardware. (loose or missing ect)		5		
<b>~</b>		3. slides		5		
<b>✓</b>		4. components, handrails, guardrails. (secured and undamaged)		5		
<b>✓</b>		5. Surfacing material (free of rocks, tripping hazards, cracks, holes, standing water, etc.)		5		
<b>✓</b>		6. walkways and platforms. (broken, loose, gaps, ect)		5		
<b>✓</b>		7. vandalism		5		
7	0		SUB-TOTALS	35	POSSIBLE SCORE:	35
COMMENTS:					1 OSSIDEE SCORE.	33
					% AVERAGE:	100.0%

CHECKED	N/A	***** IRRIGATION STANDARDS *****	LOW (1-5) HIGH	COMMENTS	
~		1. Irrigation heads/boxes level to grade.	4		
<b>✓</b>		2. Irrigation heads/valves operational.	4		
<b>✓</b>		3. Irrigation heads adjusted for adequate coverage.	2	Not all areas have been audited for repairs and adjus	tments
<b>✓</b>		4. Valve boxes secure and at grade with no visible pests.	3	A few boxes are missing lids. scheduled for maintena	nce
~		5. Irrigation clock mounted securely and programmed for the appropriate season.	5		
<b>✓</b>		6. All irrigation problems identified/flagged and scheduled for repair.	2	Not all areas have been audited for repairs and adjust	tments
6	0	SUB-TOTALS	20		
			20	POSSIBLE SCORE:	30
COMMENTS:				Of ANIED ACE.	(( 70
				% AVERAGE:	66.7%
CHECKED	N/A	***** WALKS, DRIVES AND FENCES STANDARDS *****	LOW (1-5) HIGH	COMMENTS	
~		1. Paved surfaces (walks and lots) free of weeds, broken glass and dirt.	4		
<u> </u>		2. Expansion joints cleaned and free of weeds.	4		
~		3. No broken edges, cracked cement, or trip hazards on sidewalks and trails.	3	The path at the park has several broken joints that ne	•
~		4. Parking lots, trails and driveways free of pot holes, striping and fire lanes easily seen.	2	entry drive to ballfield has broken concrete and holes	
<u> </u>		5. No visible trash in area.	5		
<u> </u>		6. Signage: proper placement and perpendicular to surface.	5		
<b>✓</b>		7. Signage: posts painted and clean; free of chipped and faded paint.	5		
<u> </u>		8. Benches are secure, properly maintained and free of vandalism.	5		
<b>✓</b>		9. Concrete, wood, metal fencing secure and free of damage.	5		
9	0	SUB-TOTALS	38		
GOLD WINDS			30	POSSIBLE SCORE:	45
COMMENTS:	i ne waiking pat	hs are on the schedule for maintenance. The driveway will be a more extensive repair, will have to be scheduled with PW		% AVERAGE:	84.4%
				// ITTERIOE.	04.470
CHECKED	N/A	***** LIGHTING STANDARDS *****	LOW (1-5) HIGH	COMMENTS	
CILICILLE	17712		Low (1-3) Indi	00////22/12	
~		Base of poles secure. Poles are perpendicular to surface.	5		
~	i i	2.Light poles painted and clean; free of rust, chipped and faded paint.	5		
~	- i	3. Face plate secure. No exposed wires.	5		
~	i i	4. lights are all coming on and working.	4		
~	- F	5. Fixtures are free of debris.	5		
~	i i	6. Timers are working and set correctly.	5		
6	0	SUB-TOTALS			
	•		29	POSSIBLE SCORE:	30
COMMENTS:					
				% AVERAGE:	96.7%
CHECKED	N/A	***** MOWING AND WEED CONTROL *****	LOW (1-5) HIGH	COMMENTS	
~		1. PARK AREAS MOWED: City Park, Ballfields,	5		
~		2. MUNICIPAL AREAS MOWED: City hall, Police Dept, Animal Control, Parks Dept.	5		
~		3. Weed control applied to Park/Ballfied turf areas	5		

		4. Weed control applied to municipal turf areas	5	
		5. Park turf areas fertilized	5	
	=	6. Municipal turf areas fertilized	1	weeds were treated in Jul, scheduled to be fertilized in Aug
	=	7. All areas treated for ants or pests.	5	weeds were treated in our, sorreduced to be retained in rag
	= -	8. Pond treated for aquatic weeds	5	
	0	SUB-TOTALS	3	
0	U	SUPTOTALS	36	POSSIBLE SCORE: 40
COMMENTS:				1 OSSIBLE SCORE. 40
COMMENTS.				% AVERAGE: 90.0%
				70 12 ( 2242 ( 224 )
CHECKED N	N/A	***** PONDS, CREEKS AND WATER AMENITIES STANDARDS *****	LOW (1-5) HIGH	COMMENTS
CHECIES	.,,,,,	10.00) CADING II.O HILLIANIS CITATION	LOW (1-3) IIIGH	
	$\sqcap$	1. Surface area is 90% free of aquatic plant material.	2	Magnolia Fisheries is treating pond for yellow primrose and aquating gr
	= -	2 No visible litter in the water or on the surrounding banks.	4	magnota i totteres is accurring portation yellow primitose and aquating gr
	_	3. Water banks free of erosion; problems have been identified and scheduled for repair.	5	
	0	SUB-TOTALS	3	
3	0	SUPTOTALS	11	POSSIBLE SCORE: 15
COMMENTS: A 1	twont	t plan must be approved by TDWD. A licensed applicator with a		1 OSSIBLE SCORE. 13
fisheries	treatment	t plan must be approved by TPWD. A licensed applicator with aquatic endorsement must perform treatments, per TX law, for a	ii public access	% AVERAGE: 73.3%
TISHET IES				70 11 ( ZZZZZZZZ
CHECKED N	N/A	***** RESTROOM STANDARDS *****	LOW (1-5) HIGH	COMMENTS
CHECKED	. 1/21	ADJANOM STANDA	LOW (1-3) IIIGH	COMMENTS
<b>V</b>	$\neg$	Structure is properly maintained with no signs of deterioration .	4	
		2. 90% of exterior/Interior free of chipped or faded paint.	5	
		Walls 100% void of vandalism/graffiti.	4	there are a few broken bricks around the outside of the buildings
	= -	4. Fixtures are clean, sanitized, and operational.	5	there are a few broken bricks around the outside of the buildings
	= -	-	5	
	= -	Sufficient toilet paper in dispensers.     No visible trash, cobwebs, or dirt.	5	
	J	7. Structure free of foul odors.	4	
	_			
	= -	8. Lights operational. Timers set correctly.	5	
		9. Restroom chase is clean and neat and properly stocked with cleaning supplies.		
	= -	10. Hand dryers are operational and free of damage.	5	
	= -	11. Soap dispensers are are adequately filled.	5	
	= -	12. Toilets and urinals are flushing appropriately.	5	
		13. Sinks are operational and draining properly.	5	
13	0	SUB-TOTALS	(2)	
			62	POSSIBLE SCORE: 65
COMMENTS:				
				Of AMEDACE. OF ACC
				% AVERAGE: 95.4%
				% AVERAGE: 95.4%
CHECKED	N/A	***** DAVILIONS DIONIS SITES AND SENERAL STANDARDS *****	LOW 4 5 WO	
CHECKED N	N/A	***** PAVILIONS, PICNIC SITES AND GENERAL STANDARDS *****	LOW (1-5) HIGH	% AVERAGE: 95.4%  COMMENTS
<b>V</b> [		1. No visible litter in area.	5	
<b>V</b> [		No visible litter in area.     No fire ant infestation.	5 4	
✓ [ ✓ [ ✓ [		1. No visible litter in area. 2. No fire ant infestation. 3. Trash receptacles less than 1/2 full.	5 4 5	
✓ [ ✓ [ ✓ (		1. No visible litter in area.  2. No fire ant infestation.  3. Trash receptacles less than 1/2 full.  4. Trash receptacles clean, neat and free of damage.	5 4 5 5	
V [		1. No visible litter in area.  2. No fire ant infestation.  3. Trash receptacles less than 1/2 full.  4. Trash receptacles clean, neat and free of damage.  5. Structure is properly maintained with no signs of deterioration.	5 4 5 5 4	
✓ [ ✓ [ ✓ [ ✓ [		1. No visible litter in area.  2. No fire ant infestation.  3. Trash receptacles less than 1/2 full.  4. Trash receptacles clean, neat and free of damage.	5 4 5 5	

<u>~</u>		8. No broken edges, cracked cement or trip hazards on pavilion slabs or picnic table pads.	5	
<b>~</b>		9. Drinking fountains: operational, draining properly and free of visible damage.	5	
<b>✓</b>		10. Signage/kiosk: proper placement and maintained with no signs of damage or deterioration.	5	
10	0	SUB-TOTALS		
			48	POSSIBLE SCORE: 50
COMMENTS:				
				% AVERAGE: 96.0%
CHECKED	N/A	***** FACILITIES/STORAGE AREAS, VAULTS, ETC. *****	LOW (1-5) HIGH	COMMENTS
CHECKED	14/14	FACILITIES/STOKAGE AREAS, VACETS, ETC.	LOW (1-3) IIIGII	COMMENTS
<b>✓</b>		First aid kit and fire extinguisher easily accessible.	5	
	H		5	
<u> </u>	<u> </u>	2. Emergency phone numbers clearly posted.		
<u> </u>	닏	3. No flammable liquids are present unless stored in approved container and visibly stored.	5	
<u> </u>		4. Overall appearance is clean-free of dirt, oil, grime and cobwebs.	5	
<u> </u>	닏ᆜ	5. All areas free of litter and debris.	5	
<u> </u>		6. Hoses, lumber, containers, and bagged material properly labeled, stacked, and stored.	5	
<b>~</b>		7. Storage vaults and shed locked.	5	
7	0	SUB-TOTALS		
			35	POSSIBLE SCORE: 35
COMMENTS:				
				% AVERAGE: 100.0%
CHECKED	N/A	***** BASEBALL, SOFTBALL AND FOOTBALL FIELD STANDARDS *****	LOW (1-5) HIGH	COMMENTS
<b>✓</b>		1. Clay is free of grass, weeds and rocks.	5	
	- i	2. Baselines are straight and edged where applicable.	5	
<b>~</b>		Baselines are straight and edged where applicable.      Base hardware is straight and level with grade.	5	
✓ ✓		3.Base hardware is straight and level with grade.	5	
✓ ✓ ✓		3. Base hardware is straight and level with grade.  4. Homeplates are level and free of damage.	5 5	Edges good to be gut down on field 2.3, and more infield dist is peeded.
Y Y Y Y Y		3. Base hardware is straight and level with grade.  4. Homeplates are level and free of damage.  5. Infield lips are level with the playing surface.	5 5 3	Edges need to be cut down on field 2-3 , and more infield dirt is needed
> > >		3. Base hardware is straight and level with grade.  4. Homeplates are level and free of damage.  5. Infield lips are level with the playing surface.  6. Field lights are 90% operational.	5 5 3 5	Edges need to be cut down on field 2-3 , and more infield dirt is needed
> > > > > > > > > > > > > > > > > > >		3. Base hardware is straight and level with grade.  4. Homeplates are level and free of damage.  5. Infield lips are level with the playing surface.  6. Field lights are 90% operational.  8. Foul poles are perpendicular to the ground.	5 5 3 5 5	
> > > > > > > > > > > > > > > > > > >		3. Base hardware is straight and level with grade.  4. Homeplates are level and free of damage.  5. Infield lips are level with the playing surface.  6. Field lights are 90% operational.  8. Foul poles are perpendicular to the ground.  9. Benches are secure, properly maintained and free of vandalism.	5 5 3 5 5 2	Edges need to be cut down on field 2-3, and more infield dirt is needed  The bleachers need to be replaced.
>		3. Base hardware is straight and level with grade.  4. Homeplates are level and free of damage.  5. Infield lips are level with the playing surface.  6. Field lights are 90% operational.  8. Foul poles are perpendicular to the ground.  9. Benches are secure, properly maintained and free of vandalism.  10. Scoreboards are operational.	5 5 3 5 5	
> > > > > > > > > > > > > > > > > > >		3. Base hardware is straight and level with grade.  4. Homeplates are level and free of damage.  5. Infield lips are level with the playing surface.  6. Field lights are 90% operational.  8. Foul poles are perpendicular to the ground.  9. Benches are secure, properly maintained and free of vandalism.	5 5 3 5 5 5 2 5	The bleachers need to be replaced.
Y		3. Base hardware is straight and level with grade.  4. Homeplates are level and free of damage.  5. Infield lips are level with the playing surface.  6. Field lights are 90% operational.  8. Foul poles are perpendicular to the ground.  9. Benches are secure, properly maintained and free of vandalism.  10. Scoreboards are operational.	5 5 3 5 5 2	
\frac{\frac}}}}}}}{\frac}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}{\frac{\frac{\		3. Base hardware is straight and level with grade.  4. Homeplates are level and free of damage.  5. Infield lips are level with the playing surface.  6. Field lights are 90% operational.  8. Foul poles are perpendicular to the ground.  9. Benches are secure, properly maintained and free of vandalism.  10. Scoreboards are operational.	5 5 3 5 5 5 2 5	The bleachers need to be replaced.  POSSIBLE SCORE: 45
\frac{\frac}}}}}}}{\frac}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}{\frac{\frac{\		3. Base hardware is straight and level with grade.  4. Homeplates are level and free of damage.  5. Infield lips are level with the playing surface.  6. Field lights are 90% operational.  8. Foul poles are perpendicular to the ground.  9. Benches are secure, properly maintained and free of vandalism.  10. Scoreboards are operational.	5 5 3 5 5 5 2 5	The bleachers need to be replaced.
\frac{\frac}}}}}}}{\frac}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}{\frac{\frac{\		3. Base hardware is straight and level with grade.  4. Homeplates are level and free of damage.  5. Infield lips are level with the playing surface.  6. Field lights are 90% operational.  8. Foul poles are perpendicular to the ground.  9. Benches are secure, properly maintained and free of vandalism.  10. Scoreboards are operational.	5 5 3 5 5 5 2 5	The bleachers need to be replaced.  POSSIBLE SCORE: 45
\frac{\frac}}}}}}}{\frac}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}{\frac{\frac{\		3. Base hardware is straight and level with grade.  4. Homeplates are level and free of damage.  5. Infield lips are level with the playing surface.  6. Field lights are 90% operational.  8. Foul poles are perpendicular to the ground.  9. Benches are secure, properly maintained and free of vandalism.  10. Scoreboards are operational.	5 5 3 5 5 5 2 5	The bleachers need to be replaced.  POSSIBLE SCORE: 45
>		3. Base hardware is straight and level with grade.  4. Homeplates are level and free of damage.  5. Infield lips are level with the playing surface.  6. Field lights are 90% operational.  8. Foul poles are perpendicular to the ground.  9. Benches are secure, properly maintained and free of vandalism.  10. Scoreboards are operational.	5 5 3 5 5 5 2 5	The bleachers need to be replaced.  POSSIBLE SCORE: 45
\frac{\frac}}}}}}}{\frac}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}{\frac{\frac{\		3. Base hardware is straight and level with grade.  4. Homeplates are level and free of damage.  5. Infield lips are level with the playing surface.  6. Field lights are 90% operational.  8. Foul poles are perpendicular to the ground.  9. Benches are secure, properly maintained and free of vandalism.  10. Scoreboards are operational.	5 5 3 5 5 5 2 5	The bleachers need to be replaced.  POSSIBLE SCORE: 45
\frac{\frac}}}}}}}{\frac}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}{\frac{\frac{\		3. Base hardware is straight and level with grade.  4. Homeplates are level and free of damage.  5. Infield lips are level with the playing surface.  6. Field lights are 90% operational.  8. Foul poles are perpendicular to the ground.  9. Benches are secure, properly maintained and free of vandalism.  10. Scoreboards are operational.	5 5 3 5 5 5 2 5	The bleachers need to be replaced.  POSSIBLE SCORE: 45
\frac{\frac}}}}}}}{\frac}}}}}}}{\frac}}}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}{\frac{\frac{\		3. Base hardware is straight and level with grade.  4. Homeplates are level and free of damage.  5. Infield lips are level with the playing surface.  6. Field lights are 90% operational.  8. Foul poles are perpendicular to the ground.  9. Benches are secure, properly maintained and free of vandalism.  10. Scoreboards are operational.	5 5 3 5 5 5 2 5	The bleachers need to be replaced.  POSSIBLE SCORE: 45
\frac{\frac}}}}}}}{\frac}}}}}}}{\frac}}}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}{\frac{\frac{\		3. Base hardware is straight and level with grade.  4. Homeplates are level and free of damage.  5. Infield lips are level with the playing surface.  6. Field lights are 90% operational.  8. Foul poles are perpendicular to the ground.  9. Benches are secure, properly maintained and free of vandalism.  10. Scoreboards are operational.	5 5 3 5 5 5 2 5	The bleachers need to be replaced.  POSSIBLE SCORE: 45
Y		3. Base hardware is straight and level with grade.  4. Homeplates are level and free of damage.  5. Infield lips are level with the playing surface.  6. Field lights are 90% operational.  8. Foul poles are perpendicular to the ground.  9. Benches are secure, properly maintained and free of vandalism.  10. Scoreboards are operational.	5 5 3 5 5 5 2 5	The bleachers need to be replaced.  POSSIBLE SCORE: 45
Y		3. Base hardware is straight and level with grade.  4. Homeplates are level and free of damage.  5. Infield lips are level with the playing surface.  6. Field lights are 90% operational.  8. Foul poles are perpendicular to the ground.  9. Benches are secure, properly maintained and free of vandalism.  10. Scoreboards are operational.	5 5 3 5 5 5 2 5	The bleachers need to be replaced.  POSSIBLE SCORE: 45
\frac{\frac}}}}}}}{\frac}}}}}}}{\frac}}}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}{\frac{\frac{\		3. Base hardware is straight and level with grade.  4. Homeplates are level and free of damage.  5. Infield lips are level with the playing surface.  6. Field lights are 90% operational.  8. Foul poles are perpendicular to the ground.  9. Benches are secure, properly maintained and free of vandalism.  10. Scoreboards are operational.	5 5 3 5 5 5 2 5	The bleachers need to be replaced.  POSSIBLE SCORE: 45
\frac{\frac{1}{2}}{2}		3. Base hardware is straight and level with grade.  4. Homeplates are level and free of damage.  5. Infield lips are level with the playing surface.  6. Field lights are 90% operational.  8. Foul poles are perpendicular to the ground.  9. Benches are secure, properly maintained and free of vandalism.  10. Scoreboards are operational.	5 5 3 5 5 5 2 5	The bleachers need to be replaced.  POSSIBLE SCORE: 45
\frac{\frac{1}{2}}{2}		3. Base hardware is straight and level with grade.  4. Homeplates are level and free of damage.  5. Infield lips are level with the playing surface.  6. Field lights are 90% operational.  8. Foul poles are perpendicular to the ground.  9. Benches are secure, properly maintained and free of vandalism.  10. Scoreboards are operational.	5 5 3 5 5 5 2 5	The bleachers need to be replaced.  POSSIBLE SCORE: 45
\frac{\frac}}}}}}}{\frac}}}}}}}{\frac}}}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}{\frac{\frac{\		3. Base hardware is straight and level with grade.  4. Homeplates are level and free of damage.  5. Infield lips are level with the playing surface.  6. Field lights are 90% operational.  8. Foul poles are perpendicular to the ground.  9. Benches are secure, properly maintained and free of vandalism.  10. Scoreboards are operational.	5 5 3 5 5 5 2 5	The bleachers need to be replaced.  POSSIBLE SCORE: 45

TOTALS FROM ALL MAINTENANCE STAND	ARD CHECKLISTS
Maintenance Standard	Rating
Turf Standards	86.0%
Tree Standards	80.0%
Playground Standards	100.0%
Irrigation	66.7%
Walks, Drives and Fences	84.4%
Lighting	96.7%
Mowing and Weed Control	90.0%
Ponds, Creeks, and Water Amenities	73.3%
Restrooms	95.4%
Pavilions, Picnic Sites & Genenral Standards	96.0%
Facilities/Storage Areas, Vaults, Etc.	100.0%
Baseball, Softball, and Football Fields	88.9%
	00.46
Park Certification Total Score	88.1%