



Mayflower Island

Douglas Harbor

Savikko Road


Treadwell  
Arena




Mayflower Island










#### ALTERNATE NO. 1 NOTES:

PART NUMBER OF COMPONENTS OF EXISTING BUILDING

PAINT LOCATED ON EXISTING ALUM. LITE & FRAMES CONTAIN LEAD. SPRAYING OR SWABING THESE SURFACES IF UNWHITE PAINT SHIPS AND THESE SURFACES ARE NOT PREPARED FOR PAINTING, ALL OF EXPOSED SURFACES MUST BE SOLICITED, PACKAGED, TRANSPORTED AND DISPOSED OF IN ACCORDANCE WITH SPECIFICATIONS.

#### KEYNOTES

- ① NEW CONCRETE BASE
- ② NEW CONCRETE STAIR
- ③ ALUMINUM PIPE DOWD MATERIAL
- ④ SMOOTH FACE NATURAL COLORED CONCRETE WALL WITH CUT GROOVES. SEE 2/A3.2
- ⑤ PREFINISHED HAMMERT CAP
- ⑥ SQUINTER 4" X 1"
- ⑦ ELEVATOR ENCLOSURE
- ⑧ NEW LIGHT FIXTURE. SEE ELECTRICAL



2 TYPICAL CUT GROOVE  
SCALE: HALF

BLM IRMIC EXPRESS DESIGN  
JUNEAU, ALASKA

UNITED STATES DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
ALASKA STATE OFFICE  
LNG. BLM, BLM, BLM  
ANCHORAGE PLANNING TEAM  
PHONE 202-208-4377 FAX 202-208-4384



UNITED STATES  
DEPARTMENT OF THE INTERIOR



Date Stamped: 4-21-08  
Project Name: SPC  
Rever: MAN CAL  
Checklist: SPC  
Sign: 05/23/2008  
Sheet Comments:  
EXTERIOR ELEVATION

Sheet Number:  
**A3.2**

USDI B.L.M. 7000-000

BLM JRMIC EGRESS DESIGN  
JUNEAU, ALASKA

Project:  
Date:  
Location:



UNITED STATES DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
ALASKA STATE OFFICE  
ANCHORAGE, ALASKA 99501  
PHONE: 404-271-2177 FAX: 404-271-1102




UNITED STATES  
DEPARTMENT OF  
THE INTERIOR



Date Stamped: 03/12/2008  
Project No.: GSH  
Drawn By: RUL  
Checked By: WIL  
Date: 03/12/2008  
Sheet Number: 1  
Drawing Title: DEMS SITE PLAN

Sheet Number:  
**C1.0**  
GSH W.D. 780225



GENERAL NOTES

1. LOCATION OF EXISTING UTILITIES ARE APPROXIMATE. CONTRACTOR SHALL DEMONSTRATE LOCATING ALL EXISTING UTILITIES PRIOR TO START OF DEMOLITION AND EXERCISE CAUTION DURING EXCAVATION.
2. EXISTING TERRAIN SURVEY WAS PERFORMED BY JAH ENGINEERING IN AUGUST 2004. THIS SURVEY WAS MADE BY CONTRACTOR TO FIELD VERIFY FOR COMPLETENESS OR CHANGES SINCE SURVEY.
3. CONTRACTOR TO MONITOR MATURED PROPERTY TO WATCH EXISTING UTILITIES, EXCEPT AS SHOWN OTHERWISE.
4. AN ARCHAEOLOGICAL INVESTIGATION WAS PERFORMED FOR THE HISTORIC PERIOD WHICH HAS OCCURRED OVER AREA FILLED OVER SHALLOW BEDROCK. CONTRACTOR TO FIELD VERIFY.

DEMOS SITE PLAN  
E1.0

GASTINEAU CHANNEL



GRAPHIC SCALE  
SCALE IN FEET