

An aerial photograph of a coastal area. In the upper right, a small island is labeled 'Mayflower Island'. To its left is a large harbor area labeled 'Douglas Harbor', which contains several long piers with many small boats moored along them. A road, labeled 'Savikko Road', runs diagonally from the bottom left towards the harbor. Below the harbor, there is a large, flat, light-colored area labeled 'Treadwell Arena'. The surrounding land shows various buildings, parking lots, and some vegetation. The water is dark and calm.

Mayflower Island

Douglas Harbor

Savikko Road

Treadwell
Arena



Mayflower Island









ALTERNATE NO. 1 NOTES:

1. PAINT EXTERIOR OF COMPONENTS OF EXISTING BUILDING.
2. PAINT LOCATED ON EXTERIOR WALLS, LITE & FRAMES CONTAIN LEAD. GRINDING OR SANDING THESE SURFACES IS PROHIBITED. PAINT CHIPS AND LEADS GENERATED FROM REPAIRS OF EFFECTED SURFACES MUST BE COLLECTED, PACKAGED, TRANSPORTED AND DISPOSED OF IN ACCORDANCE WITH SPECIFICATIONS.

KEYNOTES

1. NEW CONCRETE BASE
2. NEW CONCRETE STAIR
3. ALUMINUM PIPE CORRO. PAINT/MATERIAL
4. SMOOTH FACE NATURAL COLORED CONCRETE WALL WITH CUT GROOVES. SEE 2/A3.2
5. FINISHED HARVEST CAP
6. SCUPPER 4" X 12"
7. ELEVATOR ENCLOSURE
8. NEW LIGHT FIXTURE, SEE ELECTRICAL

2 TYPICAL CUT GROOVE
SCALE: HALF



UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
ALASKA STATE OFFICE
1000 5TH AVE. SUITE 1000
ANCHORAGE, ALASKA 99501
PHONE 907-326-1277 FAX 907-326-4843



USGS
Geological Survey
Land Management

UNITED STATES
DEPARTMENT OF
THE INTERIOR




Drawn/Stamped	Architect
Project Mgr.	CHP
Owner	BLM DCL
Checked	CHP
Date	03/25/2009

Sheet Contents:
EXTERIOR ELEVATION

Sheet Number:

A3.2

USGS B.L.M. 7/20/08



GENERAL NOTES:

- 1) LOCATION OF EXISTING UTILITIES AND APPROXIMATE CONTRACTOR SHALL VERIFY EXISTING UTILITIES LOCATED PRIOR TO START OF CONSTRUCTION AND EXERCISE CAUTION DURING EXCAVATION.
- 2) EXISTING TOPOGRAPHIC SURVEY WAS PERFORMED BY JRMIC ENGINEERING IN AUGUST 2004 AND REPORT IS ATTACHED. CONTRACTOR TO FIELD VERIFY FOR COMPLETENESS OR CHANGES SINCE SURVEY.
- 3) CONTRACTOR TO REMOVE MATERIALS PROPERLY TO MATCH EXISTING CONDITIONS EXCEPT AS SHOWN OTHERWISE.
- 4) NO GEOTECHNICAL INVESTIGATION WAS PERFORMED FOR THIS PROJECT. PROCEED WITH PRELIMINARY ASSESSMENT AND FILL OVER SHALL BE RESPONSIBILITY OF CONTRACTOR TO FIELD VERIFY.

1 DEMO SITE PLAN
(1/1)

GASTINEAU CHANNEL



Date		Weather		Sheet	
Project: BLM JRMIC EGRESS DESIGN JUNEAU, ALASKA					
UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT JUNEAU DISTRICT JUNEAU, ALASKA 99801 PHONE 907-586-1231 FAX 907-586-1110					
UNITED STATES DEPARTMENT OF THE INTERIOR 					
Date Stamped		Initials			
Project Mgr.		JRM			
Drawn		JRM			
Checked		JRM			
Date		03/23/2004			
Sheet: 001 of 01 DEMO SITE PLAN					
Sheet Number: C1.0					
USKH W.D. 760225					