STAFF REPORT REGULAR MEETING

AGENDA DATE: November 19, 2024 DEPARTMENT: Water Utilities

TITLE:

Task Order 3 with JLA Geosciences, Inc. for Surficial Aquifer Water Quality Profile Well and Replacement Monitor Well

SUMMARY:

Task Order 3 with JLA Geosciences, Inc. for Surficial Aquifer Water Quality Profile Well and Replacement Monitor Well for a cost not to exceed \$56,318.

BACKGROUND AND JUSTIFICATION:

The City of Lake Worth Beach requires representative data from Monitoring Well #9 for compliance with our South Florida Water Management District (SFWMD) Consumptive Use Permit. The existing Monitoring Well #9 has been damaged and no longer serves its intended purpose. This Task Order will authorize JLA Geosciences to design a profile well to provide water quality of the surficial aquifer which will inform the design of the replacement Monitoring Well #9, to design the replacement Monitoring Well #9, and to provide construction phase services for the project.

MOTION:

Move to approve/disapprove Task Order 3 with JLA Geosciences, Inc. for Surficial Aquifer Water Quality Profile Well and Replacement Monitor Well

ATTACHMENT(S):

Fiscal Impact Analysis Task Order 3

FISCAL IMPACT ANALYSIS

Five Year Summary of Fiscal Impact:

Fiscal Years Inflows/Revenues	2025	2026	2027	2028	2029
Appropriated (Budgeted)	0	0	0	0	0
Program Income	0	0	0	0	0
Grants	0	0	0	0	0
In Kind	0	0	0	0	0
Outflows/Expenditures					
Appropriated (Budgeted)	\$56,318	0	0	0	0
Operating	0	0	0	0	0
Capital	0	0	0	0	0
Net Fiscal Impact (If not budgeted)	0	0	0	0	0
,	-	-	-	-	
No. of Addn'l Full-Time Employee Positions	0	0	0	0	0

Contract Award - Existing Appropriation (Budgeted)			
	Expenditure		
Department	Water		
Division	Water Production		
GL Description	Improve Other than Build		
GL Account Number	422-7021-533.63-00		
Project Number	AP2502		
Requested Funds	\$56,318		
Remaining Balance	\$143,682		
Source of Revenue (i.e. Paygo. Current Revenue, Bond Money, Grants, etc.)	ARPA		