



APPENDIX A SITE PHOTOGRAPHS

DRAFT



Photo Log
Unlisted address on N Triphammer Road, Ithica, New York
PWGC Project #DRS2404



Photo 1- View of subject property from access road along N Triphammer Road.



Photo 2 – West border of the SW Field, view to the north.



Photo 3 – Representative field conditions throughout the property.



Photos 4 & 5 –

Photo 4 - View of drainpipe and stream in the south-central portion of the property.,
Photo 5 - View of standing water on the southern portion of the property.



Photo 6 - View of the hunting deer stand at west border of the SE portion of the property.



Photo 7 - View of the vegetated area on the east portion of the property.



Photo 8 – View of the central portion of the property.



Photo 9 – View of the solid waste disposal identified in the central portion of the property.



Photo 10 – View of solid waste disposal identified in central portion of the property.



Photo 11 - View of the solid waste disposal identified in the central portion of the property.



Photo 12 – View of the adjacent property to the south improved with one single-family residential dwelling.



Photo 13 – View of residential dwelling north of access road, view to the northwest.



Photo 14- View of N Triphammer road, view to the south.



Photo 15 – View of N Triphammer Road, view to the north.



Photo 16 – View of N Triphammer Road and Landscaping Business, view to the west.

DRAFT