HIGHWAY REPORT July 20, 2022

Water & Sewer

• Repaired water main break at Lansing Central School

Road Maintenance

- Hot mix patch work
- Shoulder repair

Drainage Projects

• Drainage and road cross pipe projects

Tree & Brush Maintenance

- Mulched brush pile
- Tree & brush maintenance along roadside
- Ongoing roadside mowing