



UNSAFE

**DO NOT ENTER OR OCCUPY
(THIS PLACARD IS NOT A DEMOLITION ORDER)**

This structure has been inspected, found to be seriously damaged and is unsafe to occupy, as described below:

- Unsafe Structure
- Inadequate Support

Do not enter, except as specifically authorized in writing by jurisdiction. Entry may result in death or injury.

Facility Name and Address:

313 University Ave.

Date 2-17-2026

Time _____

This facility was inspected under emergency conditions for:

Town of Los Gatos
(Jurisdiction)

Inspector ID/Agency

Robert Gony

CRIF Building Division

Do Not Remove, Alter, or Cover this Placard until Authorized by Governing Authority

02/20/2026 09:31



UNSAFE
 DO NOT ENTER OR OCCUPY
 (THIS PLACARD IS NOT A DEMOLITION ORDER)

This structure has been inspected, found to be severely damaged and is unsafe to occupy, as described below:

- *Unsafe Siding*
 - *Excessive Spacing*

Do not enter, except as specifically authorized in writing by jurisdiction. Entry may result in death or injury.

Inspector Name and Address:
313 University Ave.

Date: *2-17-2026*

This facility was inspected under the authority of:
Tim or Lee Brown

Inspector Signature:
[Signature]

Inspector Title:
Chief Building Inspector

Do Not Remove, Alter, or Cover until Authorized by Government

02/20/2026 09:31



UNSAFE
 DO NOT ENTER OR OCCUPY
 (THIS PLACARD IS NOT A DEMOLITION ORDER)
 Date: 2-18-2026

This structure has been inspected, found to be seriously damaged and is unsafe to occupy, as described below:
Unsafe Spacing
Excessive Support

This facility was inspected under emergency conditions for:
Town of Las Gato

Do not enter, except as specifically authorized in writing by jurisdiction. Entry may result in death or injury.
 Inspect by:
Ramon Lopez
Chief Building Division

Facility Name and Address:
315 University Ave

Do Not Remove, Alter, or Cover this Placard until Authorized by Governing Authority

02/20/2026 09:31

*This Page
Intentionally
Left Blank*