



North/front side of home; all windows shown are existing replacement Andersen windows



North/front of home; all existing replacement Andersen windows



East side of home; both visible windows are existing replacement Andersen windows



Same replacement Andersen window shown in above photo



Rear/South side of home; windows of each of door are existing replacement Andersen windows; windows on left and right wall are original wood windows



West side of home; all existing replacement Andersen windows (in front of side yard fence)



West side of home (behind rear yard fence); furthest window back and small window are existing replacement Andersen windows, closest windows are original wood windows

*This Page  
Intentionally  
Left Blank*