



Before Work



Before Work



Before Work



Current Condition



Current Condition



Current Condition



Current Condition



Current Condition



Current Condition



Current Condition



Current Condition



Current Condition

A close-up photograph of a white-painted wooden door frame and the surrounding wall. The wall is a light beige or off-white color and shows signs of wear, including a small dark hole and a larger, irregular dark stain near the top. The door frame is white and has a decorative, multi-lined profile. The door itself is visible in the lower right, showing vertical stiles. The overall condition appears to be one of age and some minor damage.

Current Condition



Current Condition



Current Condition



Current Condition



Current Condition



Current Condition



Current Condition



Current Condition



Current Condition



Current Condition



Current Condition

*This Page
Intentionally
Left Blank*