

REPLACING ROTTED SIDING

TRIM BOARDS, REPLACING

MISSING SKIRTING AROUND

HOUSE.

11 NEW REPLACEMENT WINDOWS.

USING ALL CEDAR MATERIAL FUR REPLACING SIDING, TRIM BOARDS & SKIRTING

File No. CDa3.0a5.053

Exhibit B

Date 7.a5.a3

Initials P















24x6





## **400 SERIES DOUBLE-HUNG WINDOW**


**LEARN DESIGN IT TECH SPECS** ECEIVE JUL 25 2023 File No. <u>C023.025.053</u> Exhibit\_ Date 7.25.23 Initials INTERIOR EXTERIOR

## Let's get started

Start by choosing your size Clear my choices x Sizing Interior Hardware Grilles Trim Glass Exterior Summary

Size Charts A Custom Sizes A Next →

1 of 7 7/26/2023, 9:12 AM





28×65



Q

## **400 SERIES DOUBLE-HUNG WINDOW**

**LEARN DESIGN IT TECH SPECS** 

Let's get started

Interior

Hardware

Clear my choices x Start by choosing your size Sizing Grilles

INTERIOR

**EXTERIOR** 

Exterior

Trim

Glass

Summary

Size Charts A Custom Sizes A Next →

7/26/2023, 9:12 AM

LARGO

KITCHEN Location

Reference #

Oly

BILL

0326019881302023

HPTEMP X 65.75 E UNIT 8 DEG WHT

22753565

WIIS636144

## LARGO

Location

BDRM 4 aty

Line

Reference #

0326019971302023 AW Parl #

WHT HPTEMP TWI 24.25 X 61.0 E UNIT 8 DEG WHT WOCD WHT

AW Code: 4032601997130202300001940751

W03636144

ship Date 05/17/2023

22753565