



To: Mayor and City Council Members

From: Matt Woodard, Director of Public Works

Date: September 17, 2025

RE: August Monthly Report

Public Works Department

Street and Public, Parks, and Maintenance Department

In August, the Public Parks and Maintenance Department mowed all city facilities, alleys, and right of way. They cleaned and maintained all the city facilities and parks. They performed all maintenance on city vehicles and heavy equipment, and the Street Department repaired streets, curbs, and signs.

Water and Wastewater Department

In August, the Water Department performed daily maintenance on the water system, repaired water mains, set water meters, and tested the water daily. The Wastewater Department performed daily maintenance on the wastewater plant. City crew cleaned up at Clearwell, intermediate area and wells.

Water Usage

Manor Ground Water- 23.684 Manville- 16.056 EPCOR- 38.96

Total: 78.7 Gallons

Population

City of Manor- 21,643

Shadowglen- 6,356

Streets and Parks Monthly Report August 2025

Daily Duties and Projects

Streets Maintenance

Repaired water cuts on Jamie Dr. with asphalt.

Removed, prepped, and poured sidewalk at 12908 Wedding Drive.

We removed the failed wood flooring in the break room at the Miller Building and replaced it with wood flooring.

Pothole repairs at Murray and Caldwell St, Carillon Way, and Johnson Rd.

Crack sealed at N. La Grange St. and N. Burnet St.

We cleaned the drainage ditch on S. San Marcos St. between Burton St. and Brenham St.

Installed lockers in the break room at the Miller Building.

Installed new flashing lights at the golf cart crossing on Lexington St.

Cleaned alley drainage at Bastrop St and W. Boyce St.

Parks/ROW Maintenance

Set up/take down for movies in the park.

Power-washed City Hall twice on the South and East sides of the building.

Weekly irrigation checks.

Playground and playscape monthly safety checks.

Friday afternoons Bulk Drop Off for city residents.

Scheduled weekly Park rounds at park facilities.


Scheduled weekly (ROW) Right of Way mowing.

Weekly vehicle and equipment check and maintenance.

MS4 Storm drain inspections monitored New/Construction under warranty

547 - Inspections done this month.

2- MS4 reports submitted this month as required by TCEQ.



Inspections/Warranties/New subdivision Walkthroughs and Pre-Construction meetings.

Lagos Phase 3 – building

The Lex – building

Manor Heights Phase 2 Section 1B – building

Presidential Storage – building

Manor Heights Phase 2 Section 1B – building

TC ESD – building

TC ESD – building

Manor Heights Phase 3 Section 2 – building

Bojangles- building

Manor Heights Phase 4 – building

Tesla Charging Stations – waiting

Manor Heights Phase 5 – development process

Blue Bonnet Mass Grading – building

Village at Manor Commons Phases 3 & 4
Boyce Street mixed use apartments-building building

Palomino Subdivision – building

Amavi Manor – waiting to build

Las Entradas Section 4 – waiting to build

Gregg Manor GST project – building

Manor OZ – Manor Apartments – building Holley Smith Phase 1A – building

Al Noor Muslim Center – waiting to build Holley Smith Phase 1B – building

Manor Animal Hospital – building Logos Phase 3

Manor Heights Phase 3 Section 2

MiniMax – building

The View at Manor – building

Discount Tire – building

Manor Heights Phase 2 Sections 1B New Haven, Mass, Grading – building

Manor Heights 4A and 4B

University Federal Credit Union – building

Manor Heights Phase 4 City of Refuge Site plan – waiting to build

Manor Heights Phase 5 Holley-Smith Phase 4A – development

Palomino HEB – building

Monarch Ranch Subdivision Improvements – building

Abbott's Frozen Custard – waiting

Monarch Ranch Amenity Center – building Landmark - building

HTeaO – building Las Entradas Phase 4

Manor Mini storage – waiting to build Platinum 973 Business Center – building

Manor Village Center – Church – building

Manor Crossing Multitenant (Lot 2B) – building

Okra Phase 1 – south of Monarch Ranch –
building

St Davids – Las Entradas South – US 290 and Gregg Manor South – building

Busy Bee – Las Entradas – building

Brakes Plus – Las Entradas North – waiting

Tower Road Apartments – off Tower Road –
building

Manor Crossing Lot 7 – "Chipotle"

Cemetery Report

waiting

August 4, 2025 – Coordinated with Riley Gardner Memorial to install a pre-need flat marker for Connie Vasquez Baquera, at her mother's site.

August 4, 2025 – Assisted a Private Investigator in locating a person who was buried without family.

August 7, 2025 – Met Joe Arellano, to repair broken headstone and install new marker.

August 8, 2025 – Marked the grave of Theresa G. McLain for installation of headstone on Monday, 11th.

August 12^{th} , 14^{th} , and 17^{th} , 2025-Monitored the cemetery.

August 18, 2025 – Received a request for a burial site for the Quinonez family. Explained that the city is no longer reserving sites.

August 22, 2025 – Monitored the cemetery.

Manor Heights Ph 6 – site disturbance plans –

August 25, 2025 – Coordinating with Avalon Monuments Georgetown to install a headstone for Margarito Ortega. Scheduled for Wednesday, 27th. Vendor did not show up. Meeting next week.

August 28th and 30th 2025 – Monitored the cemetery.

WATER/WASTEWATER AUGUST MONTHLY REPORT

WASTEWATER	TASK COMPLETED
SERVICE CALLS	5
LIF STATION CALLS	15
SEWER BACKUPS	4
MANHOLES REPAIRED	4
	8116'
CAMERA LINES WW LINES LOCATED	3
	3
CLEANOUT REPAIRS	
JOBSITE CLEANUP AND RESTORATION	6
SCADA TROUBLESHOOTING	2
PUMP AND MOTOR REPAIR	11
JOB CLEANUP AND RESTORATION	6
WATER	TASK COMPLETED
SERVICE CALLS	31
SERVICE LEAKS	1
CUSTOMER LEAKS	11
WATER MAIN LEAKS	2
NEW SERVICE TAPS	2
HYDRANT MAINTENANCE	<u> </u>
HYDRANT FLUSHED	
HYDRANT REPAIR/REPLACED	5
ISOLATION VALVE MAINTENANCE	3
ANGLE STOPS REPLACED	3
LINES LOCATED	4
WHOLESALE DISCOLORED WATER	4
CITY DISCOLORED WATER	2
WATER PRESSURE	6
WATER TURN ON/OFF	5
BAC T SAMPLES	20
JOBSITE CLEANUP AND RESTORATION	20
METER INSTALL	
METER INSTALL	
INSPECTIONS	
SITES INSPECTED	547
ALL DAY INSPECTIONS	
FLOW TEST	
TAPS	
MANDREL TESTED	500'
Pre-Cons	2
DENSITIES	94
WATER SERVICES INSTALLED	3
WATER VALVE INSTALLED	6
MANHOLES TESTED	