City of M		-			Disposition:	Auction	
Vehicle R	eplacem	ent Guidelin	es & Evaluation		leet		
Date of Eval	uation:	8/5/2024			Vehicle Type:	A	
Vehicle #:		<mark>434</mark>			Type A = Sedans / Lig		
Department Year / Make	,	2007	otorpool Chevy Pickup	_	Type B = Medium / He Type C = Off Road Equ	, ,	
Age:			chronological age be	- ainnina with			
-							
In Service D	ate:	5/18/2007	Age in Mor	nths: rs (rounded): 206	Score:	17
Usage:	Type A = 1	point per 10.00	-	-	000 miles; Type C = 1 p		
Usage.	Type A = 1		o miles, Type D = 1	point per 5,	500 miles, type $C = 1$ p	bint per 250 nours used	
	Mileage: Hours:	82,357	(N/A)			Score:	8
Service Ty						<u> </u>	
	Туре А				Ту	pe C	
Points	a	Description	<u>on</u>	Points		<u>Description</u>	
1 2	Standard sedans as Standard vehicles	nd light pickups. with occasional off-road usa	ige.	1 2	Standard duties as equipped. Standard duties when used with attachr	nents (sickle bar, backhoes, rear bushho	gs).
3			ds, continued off-road usage.	3	Multiple duties based on seasons (snow		
4 5	Any vehicle involve	ed in snow removal. escue service vehicles.		4 5	Extreme duties in harmful atmosphere (Heavy construction work including snow		
	Tollee, Tire, and Re	service venicies.		Туре В	ricavy construction work including show		
Points				<u>escription</u>			
1 2			ities, some light duty hauling essors, lights, etc.) including		tandard load hauling, some towing		
3	Standard use with attachments (compressors, lights, etc.) including job site duties, standard load hauling, some towing. Above standard use including job site duties that include idling, standard load hauling, light trailer/equipment towing, leaf collection.						
4 5	Above standard use including job side idling and hauling above standard loads, towing equipment and heavy trailers, light snow removal. Extreme service, high job site idling and duties with attachments, heavy load hauling, heavy trailer/equipment towing, major snow removal duties, refuse collection, etc.						
5			le Dump Truck, Snow Remov		, neavy trailer/equipment towing, i	major show removal duties, refuse	conection, etc.
						Score:	2
Reliability:		Note: Based of	n current conditions.	Preventati	e Maintenance work is r	not included.	
Points 1	In chop () o	vr 1 time within t	he lact 3 months an		<u>ription</u> breakdowns or road calls	_	
2					oad call within the last 3		
3	In shop more than twice within the last month, and no major breakdowns or road calls. In shop more than once within the last month, and 2 or more breakdowns/road calls within the last month.						
4 5						s within the last month. Ins within the last month	
5	in onop mo			o monency -			•
	•	within the last			0		
	•	o within the last : downs (Y or N):			<u> </u>		
		s within the last			0		
		s within the last : monthly within	3 months: the last 3 months (Y	or N).	<u> 0 </u>	Score:	1
		cement Costs:		0. 11):			
Points	Description						
1	Maintenanc	e costs are less	than or equal to 20%		ment cost.		
2 3	Maintenance costs are 21-40% of replacement cost. Maintenance costs are 41-60% of replacement cost.						
4	Maintenance costs are 61-80% of replacement cost.						
5	Maintenanc	e costs are grea	ter than or equal to 8	81% of repl	acement cost.		
Total Mainte	nance Cost	:	\$4,490	as of	8/5/2024		
		e - New Veh. :	\$36,000	as of	8/5/2024		
Est. Resale \ Estimated No			<mark>\$5,000 \$5,000</mark> \$31,000		<u>8/5/2024</u> 8/5/2024		
	•	of Replacement			8/5/2024	Score:	1
Condition:		-		_			
Dalat				Type A	rintion		
<u>Points</u> 1	No visual damage	or rust and a good drive tra	in	Desc	<u>ription</u>		
2	Minor imperfection	s in body and paint, interio	r fair (no rips, tears, burns), and a	a good drive train.			
3 4						is, tears, burns), and a weak or noisy driv	
5					cked dash), major damage from add-on major damage from add-on equipment	equipment, and one drive train compone	ne bau.
Detail				Type B	viation		
<u>Points</u> 1	Description No visual damage or rust, good paint, good interior, no damage from add-on equipment, no body modification, good drive train.						
2	Minor imperfections in body and paint, interior fair (no rips, tears, burns), good drive train, minor body modification.						
3 4	Noticeable imperfections in body and paint surface, some minor rust, fair interior, weak/fair drive train, minor body modification, minor damage from add-on equipment. Previous accident damage, poor paint & body condition, major rust/corrosion, poor interior, damage from add-on equip., moderate body modification evidence, 1 drive train component bad.						
5						lamage from add-on equipment and atta	
Detail	Ту	pe C		Notella	sidente.	(link mussless)	
<u>Points</u> 1	Good condition,	Description fully functional.	Number of Paint / Boo	Notable Aco ly:	cidents: <u>0</u> Fair	(list number) comment	
2	Fair body, functi		Interior:		Poor	comment	
3 4		age, weak operating sy			Fair 3 (pick number	comment	
4 5	Severe damage, Extreme damage	component not function e, inoperable.			3(pick number	from table) Score:	3
Overall:						Total Score:	32
0 - 17	Excellent	D	o not replace.				
18 - 22	Good	Re	e-evaluate for future				
23 - 27 28+	Fair Poor		ualifies for replaceme eeds priority replacer		t dilows.		
Prepared By			Sean P. Ballantine		Date:	8/5/2024	