

#111

**Administrative Data**

John Hiscox  
Intermountain Claims  
Boise Branch  
120 S. Cole Road  
P.O. Box 4367 zip 83711  
Boise ID 83709

Claimant  
Insured Meridian Police #111  
Claim C-21-02114-14151  
Loss Date 08/07/2021  
Loss Type Other  
Policy  
Other

**VINSOURCE Analysis**

VIN 1FM5K8AB9LGC01952  
Decodes as 2020 Ford Explorer Police Intercptr 4WD 4D  
Wagon

Accuracy Decodes Correctly  
History Activity was reported

- o Autosource activity: (NONE).
- o Autotrak activity: (NONE).
- o Sales history activity: (NONE)

**Vehicle Salvage Title Summary**

No Branded title history found for this VIN.

Processed on 08/26/21 12:07 PM. Title History is powered by Experian AutoCheck. The Experian data contained in this report involves the conveyance of information provided to Experian by other sources. Accordingly, neither Experian nor Audatex can, or will, be an insurer or guarantor of the accuracy or reliability of the Experian data.

**Valuation Detail**

	Comparable Vehicle	Your Vehicle	Adjustment
Price	Vinita, Ok		\$28,320
Odometer	21,309 Mi(Actual)	14,500 Mi(Actual)	445
Packages	Charcoal Cloth Bucket Sea		-40
<b>Market Driven Value</b>			<b>\$28,725</b>
General Sales Tax 6.0000%			\$1,723.50
<b>Net Adjusted Market Value</b>			<b>\$30,448.50</b>

<b>Vehicle Description</b>
----------------------------

**VIN: 1FM5K8AB9LGC01952**

2020 Ford Explorer Police Intercptr 4WD 4D Wagon

**14,500 Miles Actual**

6cyl Gasoline 3.3

10 Speed Auto Advantage

Interior	Air Conditioning	Cruise Control	Center Console
	Interior Cargo Tray	Driver Information Sys	Intermittent Wipers
	Lighted Entry System	Floor Mats	Overhead Console
	Pwr Accessory Outlet(s)	Power Door Locks	Power Windows
	Power Adjustable Pedals	Power Drivers Seat	Split Folding Rear Seat
	Velour/Cloth Seats	Power Rear Window	Tachometer
	Trip Computer	Trunk/Cargo Organizer	Tire Pressure Monitor
	Tilt Steering Wheel		
Exterior	Bodyside Cladding	Rear Window Defroster	Black Exterior Trim
	Black Grille	Heated Wiper Park	LED Headlamp(s)
	Heated Rear Window Wiper	Heated W/S Wiper Washers	LED Brake Lights
	Power Mirrors	Rem Trunk-L/Gate Release	Rear Window Wiper/Washer
	Rear Lip Spoiler	Sunvisor	Steel Wheels
Mechanical	Electric Steering	Dual Exhaust System	Heavy Duty Battery
	Power Brakes	Stability Cntrl Suspensn	Full Size Spare Tire
Safety	Dual Airbags	Anti-Lock Brakes	Elect. Stability Control
	Head Airbags	Knee Air Bags	2nd Row Head Airbags
	Rear View Camera	Side Airbags	Traction Control System
Entertainment	1st Row LCD Monitor(s)	MP3 Decoder	AM/FM CD Player
	Strg Wheel Radio Control		

Trim Levels

\*Police Intercptr

\* Indicates your trim level

A detailed description of your vehicle was provided to Autosource by a trained appraiser. Contact Intermountain Claims if revisions are necessary.

<b>Vehicle Condition</b>
--------------------------

<b>Seats</b>	Good
<b>Carpets</b>	Good
<b>Int Trim</b>	Good
<b>Glass</b>	Good
<b>Headliner</b>	Good
<b>Body</b>	Good
<b>Paint</b>	Good
<b>Ext Trim</b>	Good
<b>Engine</b>	Well Maintained

Transmission	Well Maintained
Front Tires	Good
Rear Tires	Good

#### Valuation Notes

- o Loss vehicle description was provided by Intermountain Claims
- o Adjustments of Special Note
  - An odometer adjustment of 6.50 cents per mile/kilometer has been applied. This adjustment is based on the vehicle year, vehicle category and market area. Odometer adjustments are capped at 40% of the vehicle's starting value.
  - Typical miles for this 2020 Ford Explorer in Idaho is 22,437.
  - No special adjustments were made for this vehicle.
  - All values are in U.S. dollars.
- o Autosource Valuation Process
  - Over 8,000,000 vehicles are entered weekly into the database used for researching this value. This database includes dealer inspected, dealer inventory, dealer advertised, phone verified and advertised private party vehicles.
  - The originating search area for this valuation was Meridian, Idaho.
  - The market area expansion was authorized by Specialty Guidelines.
- o Other Adjustments or Comments
  - The tax was calculated based on a date of loss of 08/07/2021 using zip 83642, in Ada County, Idaho. The city may vary from search area to reflect correct tax location.

Area	Taxed	Rate	Total	Tax % of Market Value
Idaho	\$28,725	6.0000%	\$1,723.50	6.0000%
		Total Tax:	\$1,723.50	6.0000%

#### Typical Condition Statement

Odometer, equipment, trim level and condition must all be carefully considered on this vehicle. The vehicle's typical odometer and condition is based on comparison of dealer and private party vehicles of the same year, vehicle type and state/province. The average miles driven for this vehicle is 22,437. Numerous descriptions have been described within each condition sub-category rating and are separated by a period. Each description is meant to be independent, but can also be interpreted as an "and/or" statement.

	Condition	Description
<b>INTERIOR</b>		
Seats	Good	No obvious damage. Very negligible wear visible on close inspection. Soiling removable with cleaning. No fading or discoloration.
Carpets	Good	No obvious damage. Very negligible wear visible on close inspection. Soiling removable with cleaning. No fading or discoloration.
Int Trim	Good	No obvious damage. Very negligible wear visible on close inspection. Soiling removable with cleaning. No fading or discoloration.
Glass	Good	No obvious damage. Numerous small pits. Light scratches visible on close inspection.
Headliner	Good	No damage. Very negligible wear visible on close inspection. Soiling removable with cleaning. No fading or discoloration.
<b>EXTERIOR</b>		
Body	Good	No visible damage. 1-3 small dings possible on close inspection.
Paint	Good	No obvious damage. 1-3 very small chips. 1-3 small scratches, no greater than 1 credit card in size, only noticeable on close inspection that can be polished out. Negligible swirl marks.
Ext Trim	Good	No damage. No dents. No impact damage. Good shine on chrome or bumper covers. Color-keyed sections in good condition. 1-3 slight scratches or marks.
<b>MECHANICAL</b>		



Condition	Description
Engine Well Maintained	Engine compartment generally clean. No obvious leaks. All accessories in good working condition. Recommended maintenance performed. Service records well documented.
Transmission Well Maintained	Transmission housing, transaxle, differential, transfer case areas generally clean. No obvious leaks. Recommended maintenance performed. Service records well documented.
<b>TIRES</b>	
Front Tires Good	Tires are in good condition. 30-79% of tread remains.
Rear Tires Good	Tires are in good condition. 30-79% of tread remains.

Having a clean, well maintained vehicle will add to its market value. Prior body damage, rust, extensive interior damage or mechanical problems will all decrease the market value of this vehicle.

#### Comparable Vehicle Details

The following information provides the details for the vehicle(s) used to calculate the Autosource Value. The selling price may be substantially less than the asking price. Where indicated, the asking price has been adjusted to account for typical negotiation according to each comparables price.

**1 2020 Ford Explorer Police Intercptr 4WD 4D Wagon 1FM5K8AB7LGA19439 \$28,320**

Stock# A19439. 21309 Miles. 6 Cylinder 3.3 Engine, 10 Speed Auto Advantage, Charcoal Cloth Bucket Seat, Anti-Lock Brakes, Air Conditioning, Bodyside Cladding, Black Grille, Black Exterior Trim, Cruise Control, AM/FM CD Player, Center Console, Interior Cargo Tray, Dual Airbags, Dual Exhaust System, Rear Window Defroster, Driver Information Sys, Power Drivers Seat, Elect. Stability Control, Electric Steering, Floor Mats, Full Size Spare Tire, Head Airbags, Heavy Duty Battery, Heated Wiper Park, Heated Rear Window Wiper, Heated W/S Wiper Washers, Intermittent Wipers, Knee Air Bags, 1st Row LCD Monitor(s), LED Brake Lights, LED Headlamp(s), Lighted Entry System, Manual Lumbar Adjustment, MP3 Decoder, Overhead Console, Pwr Accessory Outlet(s), Power Brakes, Power Door Locks, Power Mirrors, Power Rear Window, Power Windows, Power Adjustable Pedals, 2nd Row Head Airbags, Rear Lip Spoiler, Rem Trunk-L/Gate Release, Rear View Camera, Rear Window Wiper/Washer, Side Airbags, Stability Cntrl Suspensn, Split Folding Rear Seat, Steel Wheels, Sunvisor, Strg Wheel Radio Control, Tachometer, Trip Computer, Trunk/Cargo Organizer, Traction Control System, Tire Pressure Monitor, Tilt Steering Wheel, Velour/Cloth Seats, Flex Fuel Option, Power Outlet.

Offered for sale by Dealer in Vinita, OK, (918) 944-3918. Vehicle information by Vast on 09/06/21.

The advertised price of \$29,500 was adjusted to account for typical negotiation (\$ -1,180).

#### Recall Bulletins

Nat'l. Highway Traffic Safety Admin (US) has issued a total of 5 recall bulletins that may apply to this vehicle.

**NHTSA ID Number** 20V693000

Date Issued 11/10/20

Quantity Affected 10,905

**Defect** Ford Motor Company (Ford) is recalling certain 2020 Explorer and Lincoln Aviator vehicles equipped with a 2.0L or 3.3L engine and a 10 Speed Automatic Transmission with the All Wheel Drive package. The drive shaft may fracture along the weld seam.

**Remedy** Ford will notify owners, and dealers will inspect the drive shaft label inspected and replace it as necessary, free of charge. The recall is expected to begin December 14, 2020. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 20S65.

**NHTSA ID Number** 20V730000

Date Issued 11/24/20

Quantity Affected 17

**Defect** Ford Motor Company (Ford) is recalling certain 2020 Explorer vehicles equipped with 2.3L engines and 19 gallon fuel tanks. The fuel tank inlet check valve may not be fully welded to the fuel tank shell.

**Remedy** Ford will notify owners, and dealers will replace the fuel tank shell, free of charge. The recall began December 8, 2020. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 20S68.

**NHTSA ID Number** 20V788000

**Date Issued** 12/17/20

**Quantity Affected** 1,405

**Defect** Ford Motor Company (Ford) is recalling certain 2020-2021 Explorer and Lincoln Aviator vehicles. The right hand motor mount fasteners may have been incorrectly tightened, and may loosen over time.

**Remedy** Ford will notify owners, and dealers will remove and replace the right hand motor mount fasteners, free of charge. The recall is expected to begin February 8, 2021. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 20S72.

**NHTSA ID Number** 21V014000

**Date Issued** 01/15/21

**Quantity Affected** 283

**Defect** Ford Motor Company (Ford) is recalling certain 2020 Ford Explorer Police Interceptor Utility and 2020 Lincoln Aviator vehicles. The affected vehicles contain windshield washer fluid that was contaminated with brake fluid. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 104, "Windshield Wiping and Washing Systems."

**Remedy** Ford will notify owners, and dealers will flush out the washer system, replacing the washer bottle neck, washer pump assembly, fluid level sensor and the front and rear wiper blades. Dealers will also inspect and repair the vehicle's paint and exterior components if affected, free of charge. The recall is expected to begin March 8, 2021. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 21C01.

**NHTSA ID Number** 21V154000

**Date Issued** 03/10/21

**Quantity Affected** 49

**Defect** Ford Motor Company (Ford) is recalling certain 2020 Lincoln Aviator and Ford Explorer vehicles. The rear lower control arm (RLCA) bolts that attach the rear lower control arms to the wheel knuckles may not have been heat-treated, which could cause them to break.

**Remedy** Ford will notify owners, and dealers will replace both RLCA bolts, free of charge. The recall is expected to begin March 29, 2021. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 21S11.

### Original Equipment Guide

Engine Options		Transmission Options	
* 6 Cylinder 3.3 Engine	STD	* 10 Speed Auto Advantage	STD
Other Optional Equipment		Convenience Options	
* Anti-Lock Brakes	STD	Climate Control For A/C	\$610
Auto Emergency Braking		* Air Conditioning	STD
Auxiliary Lighting	\$550	Auto Headlamp Control	\$115
* Bodyside Cladding	STD	* Cruise Control	STD
* Black Grille	STD	* Rear Window Defroster	STD
* Black Exterior Trim	STD	Daytime Running Lights	\$45
Blind Spot Sensor		* Floor Mats	STD
Cargo Lamp	\$395	* Heated W/S Wiper Washers	STD
Carpeting	\$125	Reverse Sensing System	\$275
Cross Traffic Alert		* Rem Trunk-L/Gate Release	STD
* Center Console	STD	* Rear View Camera	STD

* Interior Cargo Tray	STD	* Strg Wheel Radio Control	STD
* Dual Airbags	STD	* Trunk/Cargo Organizer	STD
* Dual Exhaust System	STD	* Tire Pressure Monitor	STD
* Driver Information Sys	STD	* Tilt Steering Wheel	STD
Engine Block Heater	\$90	<b>Power Accessories</b>	
* Elect. Stability Control	STD	Heated Power Mirrors	\$60
Fwd. Collision Alert		* Power Drivers Seat	STD
Fog Lights		Dual Power Seats	\$325
* Head Airbags	STD	* Electric Steering	STD
* Heavy Duty Battery	STD	* Power Brakes	STD
* Heated Wiper Park	STD	* Power Door Locks	STD
* Heated Rear Window Wiper	STD	* Power Mirrors	STD
* Intermittent Wipers	STD	Power Passenger Seat	\$325
* Knee Air Bags	STD	* Power Rear Window	STD
Keyless Entry Keypad	\$340	* Power Windows	STD
Keyless Entry System	\$340	<b>Wheel Options</b>	
* 1st Row LCD Monitor(s)	STD	18 Inch Alloy Wheels	\$475
* LED Brake Lights	STD	* Steel Wheels	STD
* LED Headlamp(s)	STD	Wheel Caps With Crest	\$60
* Lighted Entry System	STD	Wheel Covers	\$60
* Manual Lumbar Adjustment	STD	<b>Radio/Phone/Alarm Options</b>	
* Overhead Console	STD	* AM/FM CD Player	STD
* Pwr Accessory Outlet(s)	STD	* MP3 Decoder	STD
Pedestrian Detection Sys		Perimeter Alarm System	\$120
Privacy Glass	\$120	<b>Seat Options</b>	
* Power Adjustable Pedals	STD	Bucket Seats	\$60
* 2nd Row Head Airbags	STD	* Split Folding Rear Seat	STD
Rear Liftgate		* Velour/Cloth Seats	STD
* Rear Lip Spoiler	STD	<b>Roof Options</b>	
Roof Rails	\$155	Padded Vinyl Roof	\$490
Rear Step Bumper	\$95	<b>Tires</b>	
* Rear Window Wiper/Washer	STD	* Full Size Spare Tire	STD
* Side Airbags	STD		
* Stability Cntrl Suspensn	STD		
* Sunvisor	STD		
* Tachometer	STD		
* Trip Computer	STD		
* Traction Control System	STD		
Tinted Glass	\$120		
Trunk/Cargo Box	\$245		
Wheel Locks	\$60		
<b>Option Packages</b>			
100 Watt Siren/Speaker	\$315		
12.1 Int Computer Screen	\$2,745		
2nd & 3rd Row Solar Tint	\$120		
2nd Row Only Solar Tint	\$85		
AGM Battery 12v	\$110		
Ballistic Door Pnl Lvl IV	\$2,415		

Ballistic Dr Pnl Lvl Iii	\$1,585	
Ballistic Dr Pnls Lvl III	\$3,170	
Ballistic Dr Pnls Lvl IV	\$4,830	
Blind Spot Info System	\$545	Includes Blind Spot Sensor, Cross Traffic Alert
Charcoal Cloth Bucket Sea	\$60	Includes Velour/Cloth Seats
Class III Tow Package	\$80	
Connection Package	\$55	Includes Obd-II Split Connector
Dark Car Feature	\$25	
Driver LED Spot Lamp	\$395	
Driver Side Spot Lamp Kit	\$420	
Driver's Side Spotlamp	\$140	
Dual Side Spot Lamp Kit	\$280	
Dual Spot Assembly Lamp	\$665	
Front Headlamp Solution	\$895	
Front Int Visor Led Bar	\$1,145	
Front Warning Aux Led Lgh	\$550	
Grille Light/Siren Wiring	\$50	
Headlamp Lighting Solution	\$895	
Hidden Door-Lock Plunger	\$160	
Inoperative Rear Locks	\$75	
Interior Upgrade Package	\$390	Includes Carpeting, Floor Mats
Keyed Alike	\$50	
LED Spot Lamps	\$620	
Noise Control System	\$195	
Noise Suppression Bonds	\$100	
Police Eng Idle Feature	\$260	
Police Perimeter Alert	\$675	
Police Wire Harness Front	\$185	
Pre Collision System	\$145	Includes Auto Emergency Braking, Fwd. Collision Alert, Pedestrian Detection Sys
Ready For The Road Pkg.	\$3,595	Includes Rear Lighting, Headlamp Lighting Solution, Tail Lamp Light Solution, Rear Console Mounting Plate
Rear Auxiliary Stop Light	\$395	Includes Rear Liftgate
Rear Camera Package	\$230	
Rear Console Mount Plate	\$45	
Rear Lighting	\$455	
Rear Qtr Glass Marker Lht	\$575	
Rear Spoiler Package	\$1,495	
Side Marker LED Lights	\$290	
Switchable Light In Cargo	\$50	
SYNC	\$295	Includes Voice Activation
Tail Lamp Light Solution	\$430	
Taillamp Police Housing	\$60	
Ultimate Wiring Package	\$560	Includes Siren Speaker And Bracket, Rear Console Mounting Plate
Underbody Deflector	\$335	

Base retail price \$41,860

<b>Loss Vehicle manufacturer's suggested retail price as reported</b>	<b>\$41,860</b>
---	-----------------

Editions available for the same body style (in order of original cost, increasing): \*Police Interceptor



\* Indicates loss vehicle equipment.

### Idaho Regulatory Statement

Any person who knowingly, and with intent to defraud or deceive any insurance company, files a statement containing any false, incomplete or misleading information is guilty of a felony.

### Loss Vehicle Valuation

**Autosource** has been chosen by **Intermountain Claims** to assist in establishing a fair and reasonable market value for your vehicle. We are proud to offer you the most current and comprehensive automotive valuations available today.

Your vehicle was inspected and/or described to Autosource by a trained representative of Intermountain Claims. Autosource has evaluated all aspects of your vehicle provided by Intermountain Claims as well as those features identified by the Vehicle Identification Number (VIN) or known to be standard equipment for your vehicle.

The market value of your vehicle is determined by comparing it to other vehicles in your area of similar make, model, equipment, odometer and condition that have been offered for sale or sold. The sources for this comparison include new and used car dealers, newspapers, traders, specialty journals and the Internet. Our exclusive Dealer Access program provides us with electronic inventories from thousands of affiliated dealers in North America.

Each week, over **8,000,000 vehicles** are listed from these sources, representing over 100,000 dealerships and 3400 publications, making our database the largest in the industry. We utilize the industry's largest electronic network and leading edge technology to provide you with the most current inspected, surveyed or advertised market data. We will find the closest vehicle matches in the area nearest your home.

### About Your Valuation

This report contains proprietary information of Audatex and its partners and shall not be disclosed to any third party (other than the insurer or insured, or their legal representative; or claimant or claimants insurer for purposes of subrogation) without Audatex's prior written consent. If you are the insured or claimant and have questions regarding the description of your vehicle, please contact the insurance company that is handling your claim. Information within VINsource/NICB is provided solely to identify potential duplicative claims activity. User agrees to use such information solely for lawful purposes.

Tax rates contained herein are based on general sales tax data provided by Vertex Inc. Excise, use, registration, licensing and other taxes and fees that may be applicable are not included. Audatex makes no representations or warranties concerning the applicability or accuracy of such tax data.

Report Generated by Audatex, a Solera Company

US Pat. No 7912740B2

US Pat. No 8200513B2

US Pat. No 8468038B2

US Pat. No 8725544

© 2021 Audatex North America, Inc. All Rights Reserved.

