14259 Liberty Street Site Photos







southeast corner of the property)



being replaced with enclosed storage that ties into the breezeway in the photo.



South wall of the detached garage with the hot tub from the previous photo visible. A new exterior staircase is proposed with a door to replace the window shown in the photo.

Southwestern corner of property. New owners would like to extend this fence to the rear of the property. See site plan for current end of fence.





