

# Montgomery Grove Parking Lot Photos



Scraping the old material from the site.





New asphalt millings brought in.

If estimated at 2 inches thick, this equals 144 cubic yards, or 12-14 dump trucks worth of material brought onto the site.

Roughly half of this material was placed in the 100-year floodplain.

