

ENGINEERING OBSERVATION REPORT

DATE November 21, 2024

SUBJECT: Sugar Creek Subdivision – South Detention Basin
Post Construction Observation Site Visit

To: John W. Beyer, Project File

By: Gerald W. Vick, PE

Following a cursory review of the site on the date indicated in this report, representatives of WES Engineers & Surveyors observed the post-construction condition of the south detention pond for the Sugar Creek Subdivision and compared it to the outlet design that I completed on October 29, 2021. The purpose of the special observation is to review the location and state of completion of the drainage detention basin to confirm that the construction is in general conformance with the design concept.

These observations are limited in scope and purpose and are not a detailed inspection which the Client's construction testing lab is responsible for performing. These observations are not intended to uncover any code violations or defects in construction, nor to monitor the contractors' work in detail, nor provide any supervision. This observation does not relieve the contractor of their obligations under the construction contract – particularly for the means and methods and jobsite safety.

This report presents information found during a site visit to observe the location referenced above:

Based on my field review of the pond on November 20, 2024 and the as-build surveying information that has been completed on the project, it is my opinion that the pond as constructed appears to follow the intent of the design and should function as proposed.

Sincerely,
WES Engineers & Surveyors



Gerald W. Vick, PE