

Datecompleted	Equipment	Location	Notes	Task	Taskdesc
7/15/2025	Fire Station 2 Infrared Heater	30359 WT Maple Plain, MN	Everything is looking good.	Inspection	Detailed examination of equipment for defects or abnormalities.
7/15/2025	Parks	30359 WT Maple Plain, MN	Parks look good, new tennis nets at rainbow park. Bathrooms cleaned and stocked daily. New toilet tissue holder installed in the women's restroom at rainbow park. Parks look good, new tennis nets at rainbow park. Bathrooms cleaned and stocked daily. New toilet tissue holder installed in the women's restroom at rainbow park.	Inspection	Detailed examination of equipment for defects or abnormalities.
7/15/2025	Trails	30359 WT Maple Plain, MN	All trails are looking good,	Inspection	Detailed examination of equipment for defects or abnormalities.
7/15/2025	Public works air Compressor 1	30359 WT Maple Plain, MN	Everything looks good and operational. Everything looks good and operational.	Inspection	Detailed examination of equipment for defects or abnormalities.
7/15/2025	Public works air Compressor 2	30359 WT Maple Plain, MN	I'm assuming this is the second compressor that is not operational being it's not wired to power. it is plumbed into the main line, so the tank does serve as an air holding vessel, but it is not operable by its own compressor.	Inspection	Detailed examination of equipment for defects or abnormalities.
7/16/2025	FIRE EXTINGUISHERS	30359 WT Maple Plain, MN	Everything looks good.	Inspection	CONFIRM NO OBSTRUCTIONS TO EXTINGUISHER. CONFIRM PIN IS IN PLACE, GAUGE READS FULL OR IN THE GREEN. REMOVE FROM MOUNT AND TURN UPSIDE DOWN SEVERAL TIMES.
7/16/2025	CATERPILLAR TRACTOR	30359 WT Maple Plain, MN	exercised and topped off fluids. everything looks good.	Monthly PM	Start vehicle and drive to exercise equipment. Check Fluids

7/16/2025	MACK DUMP TRUCK	30359 WT Maple Plain, MN	Exercised and checked fluids. everything is working properly.	Monthly PM	Start vehicle and drive to exercise equipment. check fluids
7/16/2025	FORD F350 1 TON	30359 WT Maple Plain, MN	Exercised and checked fluids. everything is working properly.	Inspection	Detailed examination of equipment for defects or abnormalities.
7/16/2025	F150 Truck	30359 WT Maple Plain, MN	exercised and is still in need of repair on the brakes system.	Inspection	Detailed examination of equipment for defects or abnormalities.
7/16/2025	Kubota B3030	30359 WT Maple Plain, MN	Exercised and checked all fluids. ac is not working and is to be scheduled for repair.	Inspection	Detailed examination of equipment for defects or abnormalities.
7/16/2025	Kubota ZD326	30359 WT Maple Plain, MN	Exercised and is working order.	Inspection	Detailed examination of equipment for defects or abnormalities.
7/16/2025	ToolCat Bobcat UW56	30359 WT Maple Plain, MN	Everything is working properly.	Inspection	Detailed examination of equipment for defects or abnormalities.
7/21/2025	MAIN LIFT STATION	30359 WW Maple Plain, MN	Everything is working as it should.	LS Monthly PM	<ol style="list-style-type: none"> 1. Test power fail and high level alarm and verify communication equipment will reach emergency contact for your project. 2. Inspect and clean floats. 3. If level indicator verify operating properly. 4. Inspect overall condition of lift station.
7/21/2025	Main Lift Station Generator	30359 WW Maple Plain, MN	Checked fluids everything is looking good.	Inspection	CHECK OIL. DOCUMENT ON THIS WORK ORDER WHERE AND WHEN THIS EQUIPMENT WAS USED THIS MONTH. IF NOT USED NO DOCUMENTATION IS NEEDED.
7/21/2025	HIGH SERVICE PUMP 1	30359 WT Maple Plain, MN	Greased and checked oil levels. everything looks good.	Inspection	CHECK OIL LEVEL, ADD IF NEEDED. INSPECT UNIT FOR ABNORMAL WEAR AND NOISES.
7/21/2025	HIGH SERVICE PUMP 2	30359 WT Maple Plain, MN	Greased and checked oil levels. everything looks good.	Inspection	CHECK OIL LEVEL, ADD IF NEEDED. INSPECT UNIT FOR ABNORMAL WEAR AND NOISES.

7/21/2025	AIR COMPRESSOR	30359 WT Maple Plain, MN	Everything looks good.	Inspection	CHECK OIL LEVELS AND BELT CONDITION. INSPECT FOR OIL LEAKS OR EBNORMAL WEAR. DOCUMENT HOUR METERS. CONFIRM WATER DRAIN IS WORKING.
7/21/2025	DEHUMIDIFIERS	30359 WT Maple Plain, MN	Everything looks good.	Inspection	CHECK AIR FILTER AND REPLACE IF NEEDED, MAKE SURE DRAIN TUBE IS DRAINING PROPERLY.
7/21/2025	MIXER NO 1	30359 WT Maple Plain, MN	Everything looks good	Inspection	CHECK OIL LEVEL AND TOP OFF IF NEEDED. INSPECT UNIT FOR ABNORMAL WEAR OR NOISES. ADD ONE OR TWO SQUIRTS OF GREASE TO GREASE ZERTS.
7/21/2025	WELL 3	30359 WT Maple Plain, MN	Greased and checked fluids. everything is looking good.	Inspection	CHECK OIL LEVEL AND TOP OFF IF NEEDED. INSPECT FOR ABNORMAL WEAR AND NOISES.
7/21/2025	EMERGENCY GENERATOR	30359 WT Maple Plain, MN	Checked fluids, everything looks good and exercised.	Inspection	1. CHECK ALL FLUIDS INCLUDING FUEL 2. DOCUMENT HOUR METER AND CONFIRM EXERCISING UNDER LOAD AT LEAST ONCE A WEEK. 3. INSPECT UNIT FOR UNUSUAL WEAR. 4. IF DURING COLD WEATHER CONFIRM HEATING BLOCK IS WORKING.
7/24/2025	Fire Station 2 AC Units	30359 WT Maple Plain, MN	Service was performed last month and now in proper working order. Changed air filters.	Inspection	Detailed examination of equipment for defects or abnormalities.
7/31/2025	MAIN LIFT STATION	30359 WW Maple Plain, MN	Quality flow is scheduled to do annual inspection 8-11-25 they historically have been doing amp draws. In the process of locating PPE to perform this task in the future.	LS Quarterly PM	TAKE AMP READING FROM EACH PUMP. ARC FLASH PPE REQUIRED