

Datecompleted	Equipment	Location	Notes	Task	Taskdesc
6/18/2026	Public works air Compressor 1	30359 WT Maple Plain, MN	looks good in operating condition	Inspection	Detailed examination of equipment for defects or abnormalities.
6/18/2026	Public works air Compressor 2	30359 WT Maple Plain, MN	Compressor in good operating condition.	Inspection	Detailed examination of equipment for defects or abnormalities.
6/22/2026	Fire Station 2 AC Units	30359 WT Maple Plain, MN	in good operating condition	Inspection	Detailed examination of equipment for defects or abnormalities.
6/22/2026	Fire Station 2 Infrared Heater	30359 WT Maple Plain, MN	All tasks completed on work order	Inspection	Detailed examination of equipment for defects or abnormalities.
6/23/2026	AIR COMPRESSOR	30359 WT Maple Plain, MN	Everything looks good.	Inspection	CHECK OIL LEVELS AND BELT CONDITION. INSPECT FOR OIL LEAKS OR EBNORMAL WEAR. DOCUMENT HOUR METERS. CONFIRM WATER DRAIN IS WORKING.
6/23/2026	DEHUMIDIFIERS	30359 WT Maple Plain, MN	Everything looks good.	Inspection	CHECK AIR FILTER AND REPLACE IF NEEDED, MAKE SURE DRAIN TUBE IS DRAINING PROPERLY.
6/23/2026	FIRE EXTINGUISHERS	30359 WT Maple Plain, MN	Everything looks good.	Inspection	CONFIRM NO OBSTRUCTIONS TO EXTINGUISHER. CONFIRM PIN IS IN PLACE, GAUGE READS FULL OR IN THE GREEN. REMOVE FROM MOUNT AND TURN UPSIDE DOWN SEVERAL TIMES.
6/23/2026	MACK DUMP TRUCK	30359 WT Maple Plain, MN	Truck was just serviced last month. Oil change/full inspection. Everything was normal.	Monthly PM	Start vehicle and drive to exercise equipment. check fluids
6/23/2026	F150 Truck	30359 WT Maple Plain, MN	No longer have the truck.	Inspection	Detailed examination of equipment for defects or abnormalities.
6/23/2026	Parks	30359 WT Maple Plain, MN	Everything looks good.	Inspection	Detailed examination of equipment for defects or abnormalities.
6/23/2026	Trails	30359 WT Maple Plain, MN	Everything is normal.	Inspection	Detailed examination of equipment for defects or abnormalities.

6/24/2026	MAIN LIFT STATION	30359 WW Maple Plain, MN	Quality flow completed annual inspection on 6/13/2025	LS Monthly PM	1. Test power fail and high level alarm and verify communication equipment will reach emergency contact for your project. 2. Inspect and clean floats. 3. If level indicator verify operating properly. 4. Inspect overall condition of lift station.
6/24/2026	MAIN LIFT STATION	30359 WW Maple Plain, MN	Quality flow completed annual inspection on 6/13/2025	LS Quarterly PM	TAKE AMP READING FROM EACH PUMP. ARC FLASH PPE REQUIRED
6/24/2026	MAIN LIFT STATION	30359 WW Maple Plain, MN	Quality flow completed annual inspection on 6/13/2025	LS Annual PM	1. Check electrical condition of insulation on power cable and on all phases of motor windings (resistance check) 2. Check for any loose or faulty electrical connections within the control panel(s). 3. Check voltage supply between all phases on the line side of the electrical control panel with pump(s) off. 4. Check voltage supply between all phases on the load side of the electrical control panel with pump(s) off. 5. Check conditions and operation of motor thermal protectors (if so equipped). 6. Check amperage draws on all phases of pump(s) motor(s). 7. Remove pump from lift station for physical inspection. 8. Check conditions of upper shaft seal. 9. Check conditions and operation of leakage detector (if so equipped). 10. Check for correct shaft rotation. 11. Change oil (if required). 12. Check for worn or loose impeller. 13. Check all impeller wear rings. 14. Check for noisy upper and lower bearings. 15. Check physically for damaged or cut pump cable

6/24/2026	Main Lift Station Generator	30359 WW Maple Plain, MN	Everything looks good.	Inspection	CHECK OIL. DOCUMENT ON THIS WORK ORDER WHERE AND WHEN THIS EQUIPMENT WAS USED THIS MONTH. IF NOT USED NO DOCUMENTATION IS NEEDED.
6/24/2026	HIGH SERVICE PUMP 1	30359 WT Maple Plain, MN	Everything looks good. 20439 hrs.	Inspection	CHECK OIL LEVEL, ADD IF NEEDED. INSPECT UNIT FOR ABNORMAL WEAR AND NOISES.
6/24/2026	HIGH SERVICE PUMP 2	30359 WT Maple Plain, MN	Everything looks good, Greased.	Inspection	CHECK OIL LEVEL, ADD IF NEEDED. INSPECT UNIT FOR ABNORMAL WEAR AND NOISES.
6/24/2026	CHLORINE BOOSTER PUMP NO 2	30359 WT Maple Plain, MN	Everything in good condition. 39341.9 hrs.	Inspection	INSPECT PUMPS FOR ABNORMAL WEAR AND NOISES, CLEAN FAN VENT ON TOP OF MOTOR.
6/24/2026	MIXER NO 1	30359 WT Maple Plain, MN	Everything looks good. 60565.5 hrs	Inspection	CHECK OIL LEVEL AND TOP OFF IF NEEDED. INSPECT UNIT FOR ABNORMAL WEAR OR NOISES. ADD ONE OR TWO SQUIRTS OF GREASE TO GREASE ZERTS.
6/24/2026	WELL 3	30359 WT Maple Plain, MN	Everything looks good. 28241.7 hrs	Inspection	CHECK OIL LEVEL AND TOP OFF IF NEEDED. INSPECT FOR ABNORMAL WEAR AND NOISES.
6/24/2026	EMERGENCY GENERATOR	30359 WT Maple Plain, MN	Everything looks good, exercised weekly.	Inspection	1. CHECK ALL FLUIDS INCLUDING FUEL 2. DOCUMENT HOUR METER AND CONFIRM EXERCISING UNDER LOAD AT LEAST ONCE A WEEK. 3. INSPECT UNIT FOR UNUSUAL WEAR. 4. IF DURING COLD WEATHER CONFIRM HEATING BLOCK IS WORKING.
6/24/2026	CATERPILLAR TRACTOR	30359 WT Maple Plain, MN	everything in good condition	Monthly PM	Start vehicle and drive to exercise equipment. Check Fluids
6/24/2026	FORD F350 1 TON	30359 WT Maple Plain, MN	Everything looks good and in operating condition.	Inspection	Detailed examination of equipment for defects or abnormalities.
6/24/2026	Kubota B3030	30359 WT Maple Plain, MN	everything in good condition. 1700.5 hrs	Inspection	Detailed examination of equipment for defects or abnormalities.
6/24/2026	Kubota ZD326	30359 WT Maple Plain, MN	everything looks good.	Inspection	Detailed examination of equipment for defects or abnormalities.
6/24/2026	ToolCat Bobcat UW56	30359 WT Maple Plain, MN	Everything looks good, 264.5 hrs	Inspection	Detailed examination of equipment for defects or abnormalities.