



Reliable Pump, Inc.
P.O. Box 31115
Las Vegas, NV 89173
Ph: 702-243-5116 Fax: 702-240-9319

Estimate

Date	Estimate #
10/6/2025	20652

Name / Address
City of Needles 817 Third Street Needles, CA 92363

Ship To
City of Needles 817 Third Street Needles, CA 92363 USA

P.O. No.	Terms	Ship Via	FOB	Rep
	Net 30	Will Call	Factory, FFA	BB(I)
Item	Description	Qty	Price	Total
	Estimate to repair one Hydromatic Model S12LXP4000FA, 40 HP, 460 V, 3 PH, 60 HZ, 870 RPM, 61.00 FLA, 14.13 IMP DIA, SN: 10652740, Date Code: 06/20, Premium Efficient Pump.			
	During evaluation our technician found that the motor is shorted to ground, the upper and lower chambers oil is dirty, the impeller is severely worn due to apparent cavitation, replace bearings and seals, power/control cable has heat damage under cord cap. Pump requires a full rebuild.			
	Estimate below for a full rebuild of pump.			
Diagnostic Fee	Shop labor to inspect and diagnose only. If repair is not approved, or a new replacement is not ordered within 30 days of receipt of estimate this amount will be billed and pump/motor will be subject to disposal.	1	420.00	420.00
Shop	Shop Labor to rebuild pump	1	1,680.00	1,680.00
Stator rewind labor	Labor to rewind stator	1	2,022.16	2,022.16
Stator Rewind Ma...	Materials for Stator Rewind	1	866.64	866.64
Cord cap rebuild ...	Materials needed to rebuild cord cap, (6/4, 18/5, 35 Foot Cord.)	1	709.16	709.16
Bearing 6309 C3	Bearing - Open	1	130.56	130.56

Notice: Due to a global spike in demand, combined with material and labor shortages, we are experiencing shipping delays with some of our manufactures. Any quoted lead times cannot be guaranteed.

Subtotal

Sales Tax (0.0%)

Total

Upon approval, sign at bottom and fax to 702-240-9319.
Estimate expires within 30 days from date shown above. Any alteration or deviation from above specifications, involving extra costs will be executed and become an extra charge over and above the Estimate.

Signature: _____

Date: _____



Reliable Pump, Inc.
P.O. Box 31115
Las Vegas, NV 89173
Ph: 702-243-5116 Fax: 702-240-9319

Estimate

Date	Estimate #
10/6/2025	20652

Name / Address
City of Needles 817 Third Street Needles, CA 92363

Ship To
City of Needles 817 Third Street Needles, CA 92363 USA

P.O. No.	Terms	Ship Via	FOB	Rep
	Net 30	Will Call	Factory, FFA	BB(I)
Item	Description	Qty	Price	Total
3315AC3	SKF Ball bearing, lower double row	1	591.94	591.94
03718-300-1	SEAL-SHAFT 3.0 TYPE2100 B/CA/SC	1	910.00	910.00
27996A000	SEAL-SHAFT Silcar/Carbon Nitrile	1	1,189.50	1,189.50
10901-001-1	PROBE-SEAL FAILURE TERMINAL-HERMETIC 2.1	2	84.50	169.00
01945-001-3	Washer, Impeller Retainer	1	234.00	234.00
03879-002-1	Screw, Cap (Socket Head), 3/4-16	1	149.50	149.50
25458D000	WEAR RING, S12L(X)P	1	1,287.00	1,287.00
25456E551	IMP DIA 14.13"	1	7,143.50	7,143.50
Powder Coat	Powder Coat Impeller. In most cases this more than double the life of the impeller. The powder we use is Abrasion, Corrosion & Chemical resistant.	1	289.00	289.00
Parts & Materials	O-Rings, as required	1	15.00	15.00
Supplies Income	Misc. Shop Supplies: Oil (11 Gallons), oil disposal, paint, hardware, connectors, etc.	1	275.00	275.00
Insulation Test	Motor insulation test, performed with Crown Model 2109 insulation tester, S/N 020724, 115V 60Hz 6A. Cal. 2-21-25	1	0.00	0.00
	Estimated lead time is 4 weeks upon receipt of approval. No installation is included on this estimate.			

Notice: Due to a global spike in demand, combined with material and labor shortages, we are experiencing shipping delays with some of our manufactures. Any quoted lead times cannot be guaranteed.

Subtotal \$18,081.96

Sales Tax (0.0%) \$0.00

Total \$18,081.96

Upon approval, sign at bottom and fax to 702-240-9319.
Estimate expires within 30 days from date shown above. Any alteration or deviation from above specifications, involving extra costs will be executed and become an extra charge over and above the Estimate.

Signature: _____

Date: _____