



**NOTES**

1. Bearings and distances are record per referenced plat unless otherwise noted.
2. Not all monumentation for this survey may be shown on this document.
3. Excepting for gross negligence, the liability for this survey shall not exceed the cost of preparing this survey.
4. No Recorded Documents were found for Glacier Creek Road.



**Farpoint Land Services, LLC**

SURVEYING, MAPPING, LAND PLANNING, GIS

1131 E. 76th Ave., Suite 101 Anchorage, Alaska 99518  
 FarpointAK.com • (907) 522-7770 • survey@farpointak.com

**LEGEND**

- Found Rebar
- Reference Point
- Power Pole
- Guy Wire

EXHIBIT OF:  
**Portion of Five Corner Placer,  
 Nome, Alaska (MS 1249)**

SURVEY CERTIFICATION: FARPOINT has conducted a physical survey of the subject property, the improvements situated thereon are within the property lines as shown.

EXCLUSION NOTES: It is the owners responsibility to determine the existence of any easements, covenants, or restrictions which do not appear on the Plat used for this survey. NOTE: Under no circumstances should any data hereon be used for construction or for the establishing of property lines.

PREPARED FOR:  
 STG

WORK ORDER No:	DATE:	SCALE:	ZONING:
<b>24212</b>	Feb 26, 2024	1"=100'	N/A
DRAWN:	CHECKED:	GRID No:	FB BOOK/PAGE:
CB	RL	N/A	161/31