

HISTORIC PRESERVATION SURVEY INVENTORY FORM

TYPE ALL ENTRIES.

1. PROPERTY NAME: NORMAN, OKLAHOMA
2. RESOURCE NAME: _____
3. ADDRESS: 727 S. Chautauqua
4. CITY: NORMAN
5. VICINITY: YES (yes or no)
6. COUNTY: CLEVELAND
7. BLOCK: 2
8. LOT: 33, 34
9. PLAT NAME: Reed's Addition
10. SECTION: N/A
11. TOWNSHIP: N/A
12. RANGE: N/A

-
13. RESOURCE TYPE: B Building
 14. HISTORIC FUNCTION: 01A Single Dwelling
 15. CURRENT FUNCTION: 01A Single Dwelling
 16. AREA(S) OF SIGNIFICANCE: _____
 17. SIGNIFICANCE: Noncontributing to Chautauqua District because
of age.
 18. DOCUMENTATION SOURCES: Not mapped by Sanborn Insurance Co.

-
19. NAME OF PREPARER: MEACHAM WEISIGER ASSOCIATES
709 Chautauqua, Norman, Ok. 73069
405 - 321 - 6221
 20. SURVEY PROJECT: CITY OF NORMAN, OKLAHOMA
 21. DATE OF PREPARATION: AUGUST, 1988
 22. PHOTOGRAPHS: YES YEAR 1988

BUILDING CONSTRUCTION DESCRIPTION:

23. ARCHITECT/BUILDER: _____

24. YEAR BUILT: Ca. 1950

25. ORIGINAL SITE? Yes DATE MOVED _____ FROM WHERE _____

26. ACCESSIBLE? Yes

27. ARCHITECTURAL STYLE: Ranch (80)

28. FOUNDATION MATERIAL: Concrete - Poured (65)

29. ROOF MATERIAL: Asphalt (63)

30. WALL MATERIAL: Board (21)

31. WINDOW TYPE: Casement

32. WINDOW MATERIAL: Metal (50)

33. DOOR TYPE: Panel

34. DOOR MATERIAL: Wood (20)

35. EXTERIOR FEATURES: Garage

36. INTERIOR FEATURES: N/A

37. DECORATIVE DETAILS: _____

38. CONDITION OF RESOURCE: Fair

39. DESCRIPTION OF RESOURCE: Present and historic: _____

Roof - gabled intersect. 1 story. Brick chimney,
west end. Entry porch. Original wood columns - square.

Alterations: none

40. COMMENTS: _____

42. PLACEMENT:

