

WINDOWS 1 and 2 on Elevation Sheet

**Proposed Replacement With Divided Lite Casements to Match
Original Window Appearance**



WINDOW 3 On Elevation Sheet

**Proposed Replacement With Single Hung Windows
Single Horizontal Divider at Middle**

Window Location Behind Existing Fence - Exterior Exposure in Back Yard



WINDOWS 4, 5, 6, 7, and 8 on Elevation Sheet


**Proposed Replacement With Single Hung
Single Horizontal Divider at Middle**



Exterior Door to Bedroom to Be Eliminated

WINDOWS 8 and 9 on Elevation Sheet

**Proposed Replacement With Single Hung Window
Single Horizontal Divider at Middle**



**WINDOWS 10, 11, and 12 on Elevation Sheet
Not Visible From Exterior**

**Proposed Replacement With Single Hung Window
Single Horizontal Divider at Middle**

**Photo Showing North Side Yard of Property From The Rear
Looking West**



WINDOWS 13, and 14 on Elevation Sheet

**Proposed Replacement With Single Hung Window
Single Horizontal Divider at Middle**

