

Don Thornton Certified Collision Center

Workfile ID: Federal ID:

78e57dcc 73-0264700

3973 S.Memorial Dr, Tulsa, OK 74145 Phone: (918) 669-8457

Final Bill

Felicia Tannehill)

RO Number: 18019853

Customer:

Fullerton, Ron

Insurance:

CUSTOMER PAY

Adjuster:

Phone:

Claim: Loss Date:

Deductible:

Estimator: Create Date: Felicia Tannehill

2/19/2025

2021 LEXU GX 460 Premium 4WD 4D UTV 8-4.6L Gasoline Sequential MPI Gold

VIN: License: 279764

Interior Color: Exterior Color:

Gold

Mileage In: Mileage Out: 97,318

Vehicle Out:

State:

OK

Production Date:

11/2020

Condition:

Good

Job #:

JEREMY

Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor	Туре	Paint
1	E01		**This is a Preliminary Estimate ONLY NOTE: Once the vehicle is in for repair additional damage.	** 's there is a o	chance of findir	ng			
			We are a Lexus Certified facility that is do not use aftermarket parts.	required to	use OEM parts	only. We			
			Estimate is not finalized until all work have been received.	has been con	npleted and all	invoices			
2	E01								
3	E01		FRONT BUMPER						
4	E01	Remove/Replace	O/H front bumper				3.2	Body	
5	E01	Remove/Replace	Bumper cover w/lamp washer, w/parking aid w/o sport pkg	1	495.36T	OEM		Body	3.2
6	E01		Add for Clear Coat						1.3
7	E01	Remove/Replace	Add for h'lamp washer				0.7	Body	1.5
8	E01	Remove/Replace	Add for park sensor					Body	
9	E01	Remove/Replace	Absorber	1	45.01T	OEM		Body	
10	S01	Remove/Replace	RT Bracket	1	95.42T	OEM		Body	0.3
11	S01		Add for Clear Coat					,	0.1
12	\$02	Remove/Replace	RT Fog lamp bezel	1	44.22T	OEM	0.0	Body	0.1
13	S01	Remove/Replace	RT Bumper cover screw	1	1.67T	OEM		,	
14	S01	Repair	Impact bar NOTE: Fix mount bracket for bumper,	not sold sepa	arately from im	pact bar.	1.0	Body	
15	S01	Remove/Replace	Wire harness w/back sonar, w/o surround view	1	254.86T	OEM	0.0	Body	
16	S02	Remove/Replace	Park sensor outer titanium	1	267.78T	OEM	0.1	Body	0.2
17	E01		Add for Clear Coat				312	-547	0.2
18	S02	Remove/Replace	Valance panel NOTE: Did not come in painted.	1	512.66T	OEM	0.0	Body	1.4

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

RO Number: 18019853

2021 LEXU GX 460 Premium 4WD 4D UTV 8-4.6L Gasoline Sequential MPI Gold

			5 5 1 5 1102 Gusonine Sequendai PiF1 Gu	iu					
19	S02		Add for Clear Coat						0.3
20	E01	Remove/Replace	RT Bumper cover pad	1	10.43T	OEM			
21	E01	Remove/Replace	LT Bumper cover pad	1	10.43T	OEM			
22	S01	Remove/Replace	RT Bumper cover clip	4	20.56T	OEM			
23	E01	Remove/Replace	RT Bumper cover retainer	6	41.22T	OEM			
24	S01	Remove/Replace	RT Bumper cover bolt	1	3.42T	OEM			
25	E01	Remove/Replace	RT Side support	1	56.02T	OEM	0.1	Body	
26	E01	Remove/Replace	Lower grille w/parking aid	1	202.75T	OEM	0.0	Body	
27	E01	Remove/Replace	Park sensor reatiner NOTE: Part not reusable, does not co	2 ome with new l	21.20T bumper.	OEM			
28	S01	Remove/Install	Center support				0.0	Body	
29	S01	Remove/Replace	Valance panel retainer	2	5.52T	OEM		,	
30	E01		GRILLE						
31	E01	Remove/Replace	Grille w/o surround view	1	813.03T	OEM	0.8	Body	
32	E01	Remove/Replace	Seal	1	38.41T	OEM		Body	
33	S01	Remove/Replace	Grille fastener	2	2.12T	OEM			
34	E01		FRONT LAMPS						
35	E01	Remove/Replace	RT Headlamp	1	3,293.60T	OEM	0.6	Body	
36	E01	Remove/Replace	Aim headlamps					Body	
37	S02	Remove/Replace	RT Washer nozzle gray	1	13.23T	OEM		Body	0.2
38	E01		Add for Clear Coat					/	0.1
39	E01	Remove/Replace	RT Actuator	1	120.81T	OEM	0.1	Body	0.1
40	E01	Remove/Replace	RT Fog lamp	1	959.58T	OEM		Body	
41	E01	Remove/Replace	Aim fog lamps					Body	
42	S01	Remove/Replace	RT Fog lamp bolt	4	6.56T	OEM		,	
43	S02	Remove/Replace	RT Signal lamp bulb	1	5.69T	OEM			
44	S02	Remove/Replace	RT Lens & housing	1	286.80T	OEM			
45	S 02	Remove/Replace	RT Socket	1	13.79T	OEM			
46	S02	Remove/Replace	Washer nozzle clamp	1	4.65T	OEM			
47	E01		RADIATOR SUPPORT						
48	E01	Remove/Install	Sight shield				0.2	Body	
49	S01	Repair	RT Side panel					Body	0.5
50	S01	Remove/Replace	RT Air deflector	1	73.21T	OEM		Body	0.5
51	S01	Repair	Upper tie bar					Body	0.5
52	S01		Overlap Minor Panel				0	Dody	(0.2)
53	S01	Repair	Set Up				1 በ	Body	(0.2)
54	S01	Repair	Pull					Body	
55	S01	Remove/Replace	RT Deflector shield	1	174.19T	OEM		Body	
56	E01		HOOD					2007	
57	E01	Remove/Install	Insulator				0.2	Body	
58	E01	Repair	Hood					Body	2.8
			NOTE: PARTS: Part has related compreinstalled; washer nozzle.	onent that car	nnot be reused	I /	0.0	body	2.0
59	E01		Add for Clear Coat						1.1
60	S01	Repair	Hood underside				2.0	Body	0.7
								,	0.7

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Aliowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

RO Number: 18019853

2021 LEXU GX 460 Premium 4WD 4D UTV 8-4.6L Gasoline Sequential MPI Gold

			2 0 11 0 1102 dasonile sequential PIF1 doid						
61	S01		Add for Clear Coat						0.1
62	S01	Repair	Prime/block repaired panel to restore to new condition				1.0	Body	
63	S01		Remove PPF				4.0	Body	
64	S02	Remove/Replace	Paint Protection Film - HOOD (front)	1	275.00	Other		,,,,,,	
65	E01		FENDER						
66	S01	Repair	RT Apron assy				4.0	Body	1.5
67	S01		Overlap Minor Panel					,	(0.2)
68	S01	Repair	RT Fender (HSS)				3.0	Body	2.2
69	E01		Overlap Major Adj. Panel					•	(0.4)
70	E01		Add for Clear Coat						0.4
71	S01		Remove PPF				1.0	Body	,
72	S02	Remove/Replace	Paint Protection Film - FENDER (front)	1	75.00	Other		•	
73	S01	Repair	Prime/block repaired panel to restore to new condition				0.5	Body	
74	E01	Remove/Replace	RT Fender liner	1	135.15T	OEM	0.3	Body	
75	S01	Remove/Replace	RT Fender liner grommet	15	25.05T	OEM		,	
76	E01	Remove/Install	RT Rear seal				0.2	Body	
77	S01	Remove/Replace	RT Pad	1	58.57T	OEM		,	
78	S01	Remove/Replace	RT Liner Screw	3	4.56T	OEM			
79	S01	Remove/Replace	RT Liner Grommet	3	20.61T	OEM			
80	E01		ELECTRICAL						
81	E01	Remove/Install	D&R Battery			OEM	0.5	Mech	
82	E01		PILLARS, ROCKER & FLOOR						
83	E01	Remove/Install	RT R&I running board as an assy				1.1	Body	
84	E01		VEHICLE DIAGNOSTICS						
85	S01	Remove/Replace	Pre-repair scan	1	40.00	Other	0.5	Mech	
86	E01		Drive Time to Road Test				1.0	Body	
87	S02		Calibrations-pending invoice	1	433.29	Other		-	
88	E01		Drive Time to vendor				1.0	Body	
89	E01		MISCELLANEOUS OPERATIONS					ŕ	
90	E01	Remove/Replace	Cover car/bag	1	10.00T	OEM	0.2	Body	
91	E01	Remove/Replace	Cover Connectors for Contamination	1	3.00T	Non OEM	0.3	Body	
92	E01	Remove/Replace	Corrosion Protection SXA1031	1	15.00T	Non OEM		Body	
93	E01	Remove/Replace	Flex additive	1	10.00T	Non OEM		•	
94	E01	Repair	Nib/ buff & polish to restore OEM finish				1.0	Body	
95	E01		Hazardous Waste	1	5.00T	Other		•	
96	E01	Remove/Replace	Mask for overspray	1	10.00T	Non OEM	0.2	Body	
97	E01	Remove/Replace	Second Cover car/bag for priming	1	10.00T	Non OEM		Body	
98	E01	Refinish	Tint color and spray test panels						0.5

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Parts					8,201.14
Labor, Body			70.00	44.1	3,087.00
Labor, Refinish			70.00	16.7	1,169.00

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like KInd Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Final Bill

RO Number: 18019853

2021 LEXU GX 460 Premium 4WD 4D UTV 8-4.6L Gasoline Sequential MPI Gold

Net Total			15,111.28
Grand Total			15,111.28
Sales Tax			772.45
Α.			14,338.83
Subtotal			823.29
Miscellaneous			868.40
Labor, Mechanical Material, Paint	190.00	1.0	190.00

Estimate Version	Total \$
Original	12,618.90
Supplement S01	2,332.87
Supplement S02	159.51
Insurance Total \$:	0.00
Received from Insurance \$:	0.00
Balance due from Insurance \$:	0.00
Customer Total \$:	15,111.28
Received from Customer \$:	0.00
Balance due from Customer \$:	15,111.28

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural