



DATE: August 5, 2020
 TO: Jeanne Snider, Assistant City Attorney II
 FROM: Dennis W. Davis, Traffic Control Supervisor *D.W.D.*
 SUBJECT: Damage Cost Report – 36th Avenue SE and Alameda Street

office memorandum

On July 1, 2020, repairs were made to a STOP sign installation that was damaged at 36th Avenue SE and Alameda Street. A responsible party has been identified on the attached collision report #2020-00042950. Listed below are the costs associated with the necessary services that were performed.

Replacement Parts Cost Breakdown

1 – ea 12 ft sign post	@	\$ 20.00	\$ 20.00
Miscellaneous Parts			\$ 10.00
Total Replacement Cost			\$ 30.00

Labor Cost Breakdown

R. Gourley	2.00 hr/s OT	@	\$ 27.60	\$ 55.20
(A) Subtotal			\$ 55.20	

Supervision/Miscellaneous Time Costs

D. Davis	0.5 hr/s reg.	@	\$ 41.02	\$ 20.51
D. Riesland	0.5 hr/s reg.	@	\$ 59.00	\$ 29.50
M. Rudder	0.5 hr/s reg.	@	\$ 24.79	\$ 12.39
(B) Subtotal			\$ 62.40	

Total Labor Costs (A) + (B) \$117.60

Equipment Time Cost Breakdown

Unit 641 Utility Truck	1.00 hrs	@	\$20.00	\$20.00
Total Equipment Time Costs			\$ 20.00	
TOTAL CHARGES			\$167.60	

If reimbursement funds are received please have them deposited into Account No. 10550223-43213. Should additional information be desired, please advise.

DWD/mr

cc: David Riesland, Traffic Engineer
 Angelo Lombardo, Transportation Engineer
 Shawn O’Leary, Director of Public Works
 Barbara Andros, Customer Service Rep II