



DATE: June 16, 2021
TO: Jeanne Snider, Assistant City Attorney II
FROM: Brian McNabb, Traffic Signal Supervisor *BM*
SUBJECT: Damage Cost Report – Lindsey Street and George Avenue

On June 14, 2021, a pedestrian pedestal pole located on the southwest corner of Lindsey Street and George Avenue was damaged in a vehicle accident. A responsible party has been identified on the attached collision report #2021-00035047. Listed below are the costs associated with the necessary repairs that were performed.

Material Cost

1 – ea square base assembly	@	\$ 132.25	\$ 132.25
2 – ea pedestrian signal head	@	\$ 166.00	\$ 332.00
1 – ea pedestrian signal indication	@	\$ 130.00	\$ 130.00
Total Replacement Cost			\$ 594.25

Labor Cost Breakdown

J. Hartley	2.00 hr/s reg.	@	\$ 28.07	\$ 56.14
N. Hemesley	2.25 hr/s reg.	@	\$ 23.79	\$ 53.53
B. Holdaway	0.50 hr/s reg.	@	\$ 26.72	\$ 13.36
(A) Subtotal			\$ 123.03	

Supervision/Miscellaneous Time Cost

K. Coffin	1.00 hr/s reg.	@	\$ 18.72	\$ 18.72
B. McNabb	1.50 hr/s reg.	@	\$ 40.22	\$ 60.33
J. Short	1.00 hr/s reg.	@	\$ 44.84	\$ 44.84
(B) Subtotal			\$ 123.89	
Total Labor Costs (A) + (B)			\$ 246.92	

Equipment Time Cost Breakdown

Unit 626	1.50 hr/s	@	\$ 15.00	\$ 22.50
Total Equipment Time Costs			\$ 22.50	
TOTAL CHARGES			\$ 863.67	

If reimbursement funds are received, please have them deposited in Account No. 10550223-43212. Should additional information be desired, please advise.

BM/kc

Cc: Shawn O'Leary, Director of Public Works
David Riesland, Transportation Engineer
Jami Short, Traffic Engineer
Barbara Andros, Revenue Collection Supervisor

office memorandum

Lindsey Street and George Avenue

Case # 2021-00035047

Prepared June 16, 2021

Brian McNabb

06-14-2021: Norman PD reported that a pedestrian crosswalk sign had been damaged.

06-15-2021: Found that the pedestrian pedestal pole had been damaged on the southwest corner. Took photos of damaged equipment, secured exposed wiring, picked up equipment for repairs. Replaced one square base assembly, two pedestrian signal heads, one pedestrian signal indication and reinstalled assembly at the intersection.

Josh Hartley	2.00 hours / reg
Nick Hemesley	2.25 hours / reg
Bob Holdaway	0.50 hours / reg
Unit 626	1.50 hours

06-16-2021: Compiled information and prepared damage cost report.

Brian McNabb	1.50 hours / reg
--------------	------------------

Materials Cost:

1 each Square Base Assembly	\$ 132.25
2 each Pedestrian Signal Head @ \$166.00 each	\$ 332.00
1 each Pedestrian Signal Indication	\$ 130.00

Total \$ 594.25