# <u>Aerial Views of the Subject Property and Neighboring Properties – PortlandMaps.com</u> Used as the Base Map for the Site Reconnaissance



Photo 1-A: Aerial View of the Subject Property Used as Base Map for Site Reconnaissance..




Photo 1-B: Aerial View of the Subject Property and Neighboring Properties.



22820 NE Sandy Blvd Fairview. OR 97024

### APPENDIX Q: SITE RECONNAISSANCE - PHOTO LOG 1 OF 5

## Site Features – Log 2 of 5



Photo 2-A: Aerial View of **Ramp** on the Subject Property Provided by Occupant.



Photo 2-B: View of Southeast Side of **Ramp** with Steel Retaining Walls.



Photo 2-C: View from Top of **Ramp** Center looking Northeast onto the Subject Property Yard.



Photo 2-D: **Mobile Trailer Type Building**Used as an Office on the Subject Property.



Photo 2-E: Small Maintenance **Supply Shed** (Petroleum Products Storage).



Photo 2-F: <u>Semi-Trailer on Wheels</u> Used as a General Mechanics Shop and Storage.



22820 NE Sandy Blvd Fairview, OR 97024

#### APPENDIX Q: SITE RECONNAISSANCE - PHOTO LOG 2 OF 5

### Site Features - Log 3 of 5



Photo 3-A: Mobile Trailer Type Building on Subject Property.



Photo 3-B: Mobile Trailer Type Building on Subject Property.



Photo 3-C: Mobile Trailer Type Building and Display Shed on Subject Property.



Photo 3-D: Interior Office Space on the Subject Property.



Photo 3-E: SW Catch Basin and Septic Holding Tank (blue).



Photo 3-F: Below Mobile Trailer Type Building on Subject Property.

# ENVIRONMENTAL WORKS

22820 NE Sandy Blvd Fairview, OR 97024

### APPENDIX Q: SITE RECONNAISSANCE - PHOTO LOG 3 OF 5

#### Site Features - Log 4 of 5



Photo 4-A: Maintenance Supply Shed on Subject Property.



Photo 4-B: Enclosed Base of Maintenance Supply Shed on Subject Property.



Photo 4-C: Petroleum Products inside Maintenance Supply Shed on Subject Property.



Photo 4-D: Petroleum Products inside Maintenance Supply Shed on Subject Property.



Photo 4-E: Semi-Trailer on Wheels Used as a General Mechanical Work Shop.



Photo 4-F: Chemicals inside the Semi-Trailer on Wheels Used as a General Mechanical Work Shop.



22820 NE Sandy Blvd Fairview, OR 97024

#### APPENDIX Q: SITE RECONNAISSANCE - PHOTO LOG 4 OF 5

#### Site Features – Log 5 of 5



Photo 5-A: Stormwater Swales on Southwest Adjoining Property.



Photo 5-B: Stormwater Ditch Along Washington St on Subject Property.



Photo 5-C: Outfall into Ditch Along Washington St on Subject Property.



Photo 5-D: Stormwater Ditch Along Washington St on Subject Property.



Photo 5-E: Flush Mount Monument for Soil Gas Samples Monitoring Wells Along Gravel Access Road Right-of Way.



Photo 5-F: Flush Mount Monument for Groundwater Samples Monitoring Well Along Gravel Access Road Right-of Way.

# ENVIRONMENTAL WORKS

22820 NE Sandy Blvd Fairview, OR 97024

#### APPENDIX Q: SITE RECONNAISSANCE - PHOTO LOG 5 OF 5