



Topics

- Storm Water
- Pedestrian Safety

Storm Water

- Site Slopes Southwest to Basin
- No Flood Hazard Area on Site
- Maintain Current Pattern
- Major Development from NJDEP Stormwater Management
- Comply with NJDEP and Best Management Practices
- Improvements to Basin
 - Bio Retention Basins
 - Infiltration
 - Structural Devices
 - Porous Pavement
- Route 31/Delaware Avenue Study


Pedestrian Safety

- Improvements to Basin
 - School Hours Negligible Increase
- High Visibility Sidewalks
- Pedestrian Improvement at Rte 31 Intersection
- Improved Routing to Rte 31 Intersection

PT.31 12.0. W DEDICATION peop. E. O.WK EAST. CROSS WALES PROP SIDEWALL WHELENINGE INE REDESTRIAN IMPROJENT

Pedestrian Safety

- Improvements to Basin
 - School Hours Negligible Increase
- High Visibility Sidewalks
- Pedestrian Improvement at Rte 31 Intersection
- Improved Routing to Rte 31 Intersection





East View Elevation