

# Port Lavaca Port Commission Monthly Inspection

Month: 27 MAY, 2021 Location: Harbor of Refuge

# Gangway

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

## 2. Railspur

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

#### 3. Main Frame & Floats

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

#### 4. Environmental

Condition: Satisfactory Unsatisfactory Not Applicable
Comments: 3 MARCH 2021 CRG TEXAS CONDUCTED A PHASE I ESA
AND TOOK 5 SURFACE SAMPLES IN TRACK 17 & 17A. 22 APRIL 2021
CRG TEXAS CONDUCTED A LIMITED PHASE II ESA INCLUDED
4 SURFACE SOIL BORINGS IN TRACK 17 & 17A.

# 5. Water Lines, Valves, Etc.

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

# 6. Electrical & Lights

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

#### 7. PERMIT

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

#### 8. Rub Rails & Fenders

Condition: Satisfactory Unsatisfactory Not Applicable

Comments: 5 APRIL 2021 FOUND SOME DAMMAGE TO THE VERTICAL

TIMBER AT THE OFFSET IN BULKHEAD.

#### Cleats & Kevels

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

#### 10. Gates & Locks

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

# 11. Railing

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

#### 12. Cement Cap

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

#### 13. Bulkhead

Condition: Satisfactory Unsatisfactory Not Applicable

Harbor Master: 45 Must

# Port Lavaca Port Commission Monthly Building Inspection

Month: 27 May, 2021 Location: NLB

#### 1. Doors:

Condition: Satisfactory Unsatisfactory Not Applicable Comments: 16 April 2021 ordered three doors, six side lights and Three transom windows. Victor Fredrickson is going to write a scope of work to go out for bids.

# 2. Decking:

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

# 3. Flooring:

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

#### 4. Windows:

Condition: Satisfactory Unsatisfactory Not Applicable

Comments: 6 metal window frames front south end of building need to have the rust descaled prime and painted. 24 MAY 2021 BAREFOOT

CONSTRUCTION COMPLETED REFURBISHING METAL WINDOW FRAMES.

#### 5. Water Lines, Valves, Etc.

Condition: Satisfactory Unsatisfactory Not Applicable

# 6. Electrical & Lights

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

# 7. HVAC & Refrigeration:

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

#### 8. Roof:

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

# 9. Parking:

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

# 10. Fire Extinguishers:

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

# 11. Hand Railing:

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

# 12. Stairs & Steps

Condition: Satisfactory Unsatisfactory Not Applicable

Harbor Master:

# Port Lavaca Port Commission Monthly Inspection

Month: 27 May, 2021 Location: NLM / Smith Harbor

# 1. Gangway

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

# 2. Decking

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

# 3. Main Frame & Floats

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

#### 4. Dock Boxes

Condition: Satisfactory Unsatisfactory Not Applicable

Comments: Dock A there are six dock boxes with broken hinges and

Three boxes missing.

# 5. Water Lines, Valves, Etc.

Condition: Satisfactory Unsatisfactory Not Applicable

### 6. Electrical & Lights

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

# 7. Pilings, Guides & Rollers

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

#### 8. Rub Rails & Fenders

Condition: Satisfactory Unsatisfactory Not Applicable

Comments: Dock A there are two 6' sections of rub rail damaged.

#### Cleats & Kevels

Condition: Satisfactory Unsatisfactory Not Applicable

Comments: Dock A 15 broken cleats, Dock B 2 broken cleats.

#### 10. Gates & Locks

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

# 11. Dredging

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

DERRECK CONSTRUCTION WAS AWARDED BID BY CITY COUNCIL.

#### 12. Cement Cap

Condition: Satisfactory Unsatisfactory Not Applicable

# 13. Bulkhead

Condition: Satisfactory Unsatisfactory Not Applicable

Com

Harbor Master: 25 Mut

# Port Lavaca Port Commission Monthly Inspection

Month: 27 MAY, 2021 Location: City Harbor

## 1. Bilge Reclamation Site

Condition: Satisfactory Unsatisfactory Not Applicable

Comments: 1APRIL 2021 SPOKE WITH RUSTY MOON WITH TGLO

WAS TOLD THEY HAVE AWARDED A CONTRACT BUT HE WOULD HAVE NO

FURTHER INFORMATION UNTIL IT WAS SIGNED.

# 2. Decking

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

#### 3. Main Frame & Floats

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

#### Dock Boxes

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

#### 5. Water Lines, Valves, Etc.

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

#### 6. Electrical & Lights

Condition: Satisfactory Unsatisfactory Not Applicable

#### Comments:

# 7. Pilings, Guides & Rollers

Condition: Satisfactory Unsatisfactory Not Applicable Comments: Shirley & Son will replace bad pilings when they start Work at City Harbor. 12 January 2021 Shirly & Sons Started work.

5 MAY 2021 HANDRAIL INSTALED ON BULKHEAD AT SCULLYS PROJECT COMPLETED.

#### 8. Rub Rails & Fenders

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

#### 9. Cleats & Kevels

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

#### 10. Gates & Locks

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

#### 11. Railing

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

#### 12. Cement Cap

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

#### 13. Bulkhead

Satisfactory Unsatisfactory Not Applicable Comments: 9 December 2020 J&S Construction arrived to start Repairs to the low dock. NEED TO FILL IN WASHED AREAS BEHIND BULKHEAD ON EAST SIDE CITY HARBOR. Had Gonzales Construction look at

Condition:

Washed out areas 14 January 2021.

23 M ARCH 2021 J&S COMPLETED ALL CEMENT WORK ON LOW DOCK INCLUDING REPAIRING BULKHEAD AT THE RAMP AREA. WILL COME BACK IN ABOUT 30 DAYS TO LET CEMENT CURE TO INSTALE KEVELS. 26 APRIL 2021 DID FINAL INSPECTION ON LOW DOCK NEED TO FILL LOW SPOT WITH CRUSHED CEMENT WEST END, REPAIR BULKHEAD IN THAT SAME AREA.

ALSO NEED REPAIR BULKHEAD AND FILL WASHOUT EAST OF BIGBEAR. 13 APRIL 2021 J&S MADE REPAIRS TO BULKHEAD AND BACKFILLED. 12 MAY 2021 J&S COMPLETED ALL WORK AT THE LOW DOCK.

Harbor Master:

.