

From: [Jotform](#)
To: [Joe Villalon](#); [Lorena Perez-Diaz](#); [Wayne Shaffer](#); [Edward Tyler](#); [Kellie Perez](#)
Subject: Re: Playground Safety Checklist - Joe Villalon
Date: Monday, October 19, 2026 11:43:27 AM
Attachments: [6682373504789569901_signature_13.png](#)



Playground Safety Checklist

Inspection ID 0227

Name of Park LaBelle at the Bayfront

Inspection Date 10-19-2026 09:00 AM

General Inspection		In Good Condition	Needs Improvement	Notes
	Playground are is free of litter and debris	☐		
	Playground area is free of anthills/hazardous insects or toxic plants.	☐		
	Playground area is free of holes and other tripping hazards.	☐		
	Proper signage with rules, hours, and age-appropriate use is posted.	☐		
	Playground area is properly fenced			N/A
	Self latching gate works as designed			N/A

In Good Condition Needs Improvement Notes

Surfacing	Approved surfacing material is used (i.e. solid rubber, artificial graass or turf, play sand, pea gravel, wood chips, rubber mulch)	☐		
	Surfacing material under and around equipment is adequate depth (6-12 inches)	☐		
	Surfacing material is free of glass, debris, or other foreign objects.	☐		
	Surfacing material is not compacting or deteriorating.	☐		
	Rubber wear mats are used under high-traffic-use areas and covered by sufficient depth of surfacing material.			N/A
	Proper drainage prevents water from forming puddles.	☐		
		In Good Condition	Needs Improvement	Notes

Equipment Hazards

Equipment is not damaged or vandalized.	☐
Equipment is free from sharp points, corners, or edges.	☐
Protective caps or plugs are not missing or damaged.	☐
Equipment is free of potential clothing entanglement hazards.	☐
Equipment is free of pinch and crush points or exposed moving parts.	☐
Equipment is free of rust, rot, cracks, and splinters.	☐
Equipment is free of entrapments.	☐
Equipment is safely anchored.	☐

	In Good Condition	Needs Improvement	Notes
Hardware and chains are in good condition.			N/A
Swings are a safe distance from other playground			N/A

Swings	equipment.			
	Swings are 24 inches apart.			N/A
	Edges of seats are smooth and free from obstructions.			N/A
	Adequate depths of surfacing material extend out a minimum distance of twice the height of the swing.			N/A
Slides		In Good Condition	Needs Improvement	Notes
	Slides are free of obstructions and protrusions.	☐		
	Equipped with platforms to facilitate access to the sitting position.	☐		
	Platforms are equipped with guardrails or equivalent protective equipment.	☐		
	Exit regions are level.	☐		
Hand grips		In Good Condition	Needs Improvement	Notes
	Hand grips			

Climbing Equipment	are secured and do not rotate.	☐		
	Rope or chain ladders are anchored at both ends.	☐		
	Foot holds/ rungs are in good condition and adequately spaced.	☐		
Seesaws		In Good Condition	Needs Improvement	Notes
	Seesaws are free of cracks, corrosion, and other obvious structural defects.			N/A
	Equipment is provided with spring centering devices or cushioning material to prevent abrupt contact with the ground.			N/A
	Fulcrums/ pivot points are free of pinch or crush hazards.			N/A
	Handholds			

are
provided
at each
sitting
position.

N/A

Upload Images &
Documents

[17924188798420.jpeg](#)
[17924188798421.jpeg](#)
[17924188798422.jpeg](#)

Comments

Missing a few bolts and still needing to repair a broken stud

Inspector Name

Joe Villalon

Signature

A handwritten signature in black ink, appearing to read "Joe Villalon", written over a horizontal line.