

From: [Jotform](#)
To: tania@somethingmoremedia.com; [Joe Villalon](#); [Lorena Perez-Diaz](#); [Wayne Shaffer](#)
Subject: Re: Playground Safety Checklist - Joe Villalon
Date: Friday, May 22, 2026 12:28:19 PM
Attachments: [6552800354781450596_signature_13.png](#)



Playground Safety Checklist

Inspection ID 0156
 Name of Park Wilson Park
 Inspection Date 05-22-2026 09:25 AM

	In Good Condition	Needs Improvement	Notes
General Inspection	<input type="checkbox"/>		
Playground are is free of litter and debris	<input type="checkbox"/>		
Playground area is free of anthills/hazardous insects or toxic plants.	<input type="checkbox"/>		
Playground area is free of holes and other tripping hazards.		<input type="checkbox"/>	Holes in floor
Proper signage with rules, hours, and age-appropriate use is posted.	<input type="checkbox"/>		
Playground area is properly fenced			N/A
Self latching gate works as designed			N/A

	In Good Condition	Needs Improvement	Notes
Approved			

Surfacing

surfacing material is used (i.e. solid rubber, artificial grass or turf, play sand, pea gravel, wood chips, rubber mulch)



Holes need to be repaired

Surfacing material under and around equipment is adequate depth (6-12 inches)



Surfacing material is free of glass, debris, or other foreign objects.



Weeds

Surfacing material is not compacting or deteriorating.



Floor deteriorating

Rubber wear mats are used under high-traffic-use areas and covered by sufficient depth of surfacing material.

N/A

Proper drainage prevents water from forming puddles.



	In Good Condition	Needs Improvement	Notes
Equipment is			

Equipment Hazards

not damaged or vandalized.	<input type="checkbox"/>		
Equipment is free from sharp points, corners, or edges.		<input type="checkbox"/>	Sharp edges/ replace
Protective caps or plugs are not missing or damaged.	<input type="checkbox"/>		
Equipment is free of potential clothing entanglement hazards.	<input type="checkbox"/>		
Equipment is free of pinch and crush points or exposed moving parts.	<input type="checkbox"/>		
Equipment is free of rust, rot, cracks, and splinters.		<input type="checkbox"/>	Rust, rot/ replace
Equipment is free of entrapments.	<input type="checkbox"/>		
Equipment is safely anchored.	<input type="checkbox"/>		

	In Good Condition	Needs Improvement	Notes
Hardware and chains are in good condition.	<input type="checkbox"/>		
Swings are a safe distance from other playground equipment.	<input type="checkbox"/>		
Swings are			

Swings

24 inches apart.

Edges of seats are smooth and free from obstructions.

Adequate depths of surfacing material extend out a minimum distance of twice the height of the swing.

Slides

Slides are free of obstructions and protrusions.

Equipped with platforms to facilitate access to the sitting position.

Platforms are equipped with guardrails or equivalent protective equipment.

Exit regions are level.

Hand grips are secured and do not rotate.

In Good Condition

Needs Improvement

Notes

In Good Condition

Needs Improvement

Notes

Climbing Equipment

Rope or chain ladders are anchored at both ends.



Foot holds/ rungs are in good condition and adequately spaced.



Rust, rot/ replace

Seesaws

	In Good Condition	Needs Improvement	Notes
Seesaws are free of cracks, corrosion, and other obvious structural defects.			N/A
Equipment is provided with spring centering devices or cushioning material to prevent abrupt contact with the ground.			N/A
Fulcrums/ pivot points are free of pinch or crush hazards.			N/A
Handholds are provided at each sitting position.			N/A

Upload Images &
Documents

[17794613447850.jpg](#)

Inspector Name

Joe Villalon

Signature

A handwritten signature in black ink, appearing to read "Joe Villalon". The signature is written in a cursive style with a large initial "J" and "V".

You can [edit this submission](#) and [view all your submissions](#) easily.