

AGENDA 3

Port Lavaca Port Commission Monthly Inspection

Month: 3 AUGUST, 2021 Location: NLM / Smith Harbor

1. Gangway

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

2. Decking

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

3. Main Frame & Floats

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

4. Dock Boxes

Condition: Satisfactory Unsatisfactory Not Applicable

Comments: Dock A there are six dock boxes with broken hinges and
Three boxes missing.

5. Water Lines, Valves, Etc.

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

6. Electrical & Lights

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

7. Pilings, Guides & Rollers

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

8. Rub Rails & Fenders

Condition: Satisfactory Unsatisfactory Not Applicable

Comments: Dock A there are two 6' sections of rub rail damaged.

9. Cleats & Kevels

Condition: Satisfactory Unsatisfactory Not Applicable

Comments: Dock A 15 broken cleats, Dock B 2 broken cleats.

10. Gates & Locks

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

11. Dredging

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

DERRECK CONSTRUCTION WAS AWARDED BID BY CITY COUNCIL.
WILL START WORK 19 JULY,2021.

12. Cement Cap

Condition: Satisfactory Unsatisfactory Not Applicable


Comments:

13. Bulkhead

Condition: **Satisfactory** Unsatisfactory Not Applicable

Com

Harbor Master: _____

A handwritten signature in blue ink, appearing to read "J. S. Hunt", is written over a horizontal line.

Port Lavaca Port Commission Monthly Inspection

Month: 3 AUGUST, 2021 Location: Harbor of Refuge

1. Gangway

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

2. Railspur

Condition: Satisfactory Unsatisfactory Not Applicable

Comments: WILL BID REPAIRS IDENTIFIED IN QUARTERLY INSPECTION FROM DIAMOND K.

3. Main Frame & Floats

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

4. Environmental

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

5. Water Lines, Valves, Etc.

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

6. Electrical & Lights

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

7. PERMIT

Condition: **Satisfactory** Unsatisfactory Not Applicable

Comments:

8. Rub Rails & Fenders

Condition: Satisfactory **Unsatisfactory** Not Applicable

Comments: **5 APRIL 2021 FOUND SOME DAMMAGE TO THE VERTICAL
TIMBER AT THE OFFSET IN BULKHEAD " DESIGN PROBLEM" DAMMAGE WAS
DONE BEFORE INSTALLING FENDERS.**

9. Cleats & Kevels

Condition: **Satisfactory** Unsatisfactory Not Applicable

Comments:

10. Gates & Locks

Condition: **Satisfactory** Unsatisfactory Not Applicable

Comments:

11. Railing

Condition: Satisfactory Unsatisfactory **Not Applicable**

Comments:

12. Cement Cap

Condition: **Satisfactory** Unsatisfactory Not Applicable

Comments:

13. Bulkhead

Condition: **Satisfactory** Unsatisfactory Not Applicable

Comments:

Harbor Master: *[Signature]*

Port Lavaca Port Commission Monthly Inspection

Month: 3 AUGUST, 2021 Location: City Harbor

1. Bilge Reclamation Site

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

2. Decking

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

3. Main Frame & Floats

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

4. Dock Boxes

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

5. Water Lines, Valves, Etc.

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

6. Electrical & Lights

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

7. Pilings, Guides & Rollers

Condition: **Satisfactory** Unsatisfactory Not Applicable

Comments:

8. Rub Rails & Fenders

Condition: **Satisfactory** Unsatisfactory **Not Applicable**

Comments:

9. Cleats & Kevels

Condition: **Satisfactory** Unsatisfactory **Not Applicable**

Comments:

10. Gates & Locks

Condition: **Satisfactory** Unsatisfactory Not Applicable

Comments:

11. Railing

Condition: **Satisfactory** Unsatisfactory Not Applicable

Comments:

12. Cement Cap

Condition: **Satisfactory** Unsatisfactory Not Applicable

Comments:

13. Bulkhead

Condition: **Satisfactory** **Unsatisfactory** Not Applicable

Comments:

NEED TO FILL IN WASHED AREAS BEHIND BULKHEAD ON EAST SIDE CITY HARBOR AND BEHIND SCULLYS. Had Gonzales Construction look at

Washed out areas 14 January 2021.

Harbor Master: 

Port Lavaca Port Commission Monthly Building Inspection

Month: 3 AUGUST, 2021 Location: NLB

1. Doors:

Condition: Satisfactory Unsatisfactory Not Applicable

Comments: 16 April 2021 ordered three doors, six side lights and Three transom windows. Victor Fredrickson is going to write a scope of work to go out for bids.

2. Decking:

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

3. Flooring:

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

4. Windows:

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

5. Water Lines, Valves, Etc.

Condition: Satisfactory Unsatisfactory Not Applicable

6. Electrical & Lights

Condition: Satisfactory Unsatisfactory Not Applicable
Comments:

7. HVAC & Refrigeration:

Condition: Satisfactory Unsatisfactory Not Applicable
Comments:

8. Roof:

Condition: Satisfactory Unsatisfactory Not Applicable
Comments:

9. Parking:

Condition: Satisfactory Unsatisfactory Not Applicable
Comments: WORKING ON PLANS FOR THE FRONT PARKING LOT AND SIDEWALK.

10. Fire Extinguishers:

Condition: Satisfactory Unsatisfactory Not Applicable
Comments:

11. Hand Railing:

Condition: Satisfactory Unsatisfactory Not Applicable
Comments:

12. Stairs & Steps

Condition: Satisfactory Unsatisfactory Not Applicable
Comments:

