Port Lavaca Port Commission Monthly Building Inspection

Month: FEBRUARY 2025 Location: NLB

18 MARCH 2025

1. Building Maintenance:

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

2. Decking:

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

3. Flooring:

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

4. Windows:

Condition: Satisfactory Unsatisfactory Not Applicable Comments: 4 November 2024 Barefoot Construction started building new window covers out of the corrugated plastic.

5. Water Lines, Valves, Etc.

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

6. Electrical & Lights

Condition: Satisfactory Unsatisfactory Not Applicable

Comments: 15 November 2024 Jimmy Ramirez has 90% new lighting

Installed. 9 December 2024 completed bided project, but are adding a couple more light fixtures to the building. 4 March 2025 completed adding the additional light fixtures.

	Satisfactory	Unsatisfactory	Not Applicable
Comments: Wasted uprig	5 March 2025 I ght 4x4 steel c	Barefoot Construction	ction replaced ontal purling holding the cedar picket fence up
Parking: Condition: Comments:	Satisfactory	Unsatisfactory	Not Applicable
		Unsatisfactory	Not Applicable
·		Unsatisfactory	Not Applicable
Stairs & Steps Condition: Comments:		Unsatisfactory	Not Applicable
	Roof: Condition: Comments: Wasted uprigat the recycle Parking: Condition: Comments: Fire Extinguis Condition: Comments: Hand Railing Condition: Comments: Stairs & Steps Condition:	Condition: Satisfactory Comments: Roof: Condition: Satisfactory Comments: 5 March 2025 It Wasted upright 4x4 steel coat the recycle oil storage of Parking: Condition: Satisfactory Comments: Fire Extinguishers: Condition: Satisfactory Comments: Hand Railing: Condition: Satisfactory Comments: Stairs & Steps Condition: Satisfactory Comments:	Condition: Satisfactory Unsatisfactory Comments: Roof: Condition: Satisfactory Unsatisfactory Comments: 5 March 2025 Barefoot Construct Wasted upright 4x4 steel columns and horize at the recycle oil storage area, painted new Parking: Condition: Satisfactory Unsatisfactory Comments: Fire Extinguishers: Condition: Satisfactory Unsatisfactory Comments: Hand Railing: Condition: Satisfactory Unsatisfactory Comments: Stairs & Steps Condition: Satisfactory Unsatisfactory Unsatisfactory Comments:

Harbor Master: _____