

Inspection Checklist

Date:11/17/2025

Inspector:

Location:502 N San Antonio Trailer #3

Bradley Shaffer

	Pass	Fail	Violation/Deficiency	Location of violation
Roof properly maintained	X			
Improper Walls, partitions or other vertical supports		X		
Fireplaces or chimneys properly maintained		N/A		
Unsecure building: vacant and open.	X		Windows broken in several places	
Lack of required rails, stairs, steps and/or balconies		X	Stairs at front door sinking and broken	
Lack of or improper exterior wall coverings		X	Exterior wall coverings warping and coming off exposing paneling underneath	
Hazardous wiring			Unable to verify	
Hazardous plumbing	X			
Hazardous mechanical equipment			Unable to verify	
Sanitation:	X			
Lack of or improper connection to required sewage disposal			Unable to verify	
Lack of or improper garbage and rubbish storage		X	No rubbish storage	
Standing or stagnant water	X			
Improper Drainage	X			
Improper Occupancy	X			
Inadequate exits	X			
Improper Fireplace or Chimney	X			

Improper Ceiling or Ceiling supports	X			
Improper Flooring or floor supports		X	Floor coverings missing or damaged	
Improper Foundation	X			
Vermin/Insects		X	Evidence of rodents and vermin	
Dampness of habitable space	X			
Lack of electrical lighting		X	No electric	
Hot and Cold Water		X	No water	
Lack of or Improper Kitchen		X	No water or electric	
Lack of or Improper bathroom		X	No toilet or shower properly installed	
Dead trees, tree limbs, holes, excavations or other conditions reasonably capable of causing injury to a person.		X	Holes and other tripping hazards on property	

This inspection was completed in accordance with Sec. 12-287 of the City of Port Lavaca Code of Ordinances.

State Law reference— Authority to condemn dangerous buildings, V.T.C.A., Local Government Code § 342.012(b).

502 N San Antonio Trlr #3



