# Port Lavaca Port Commission Monthly Inspection

Month: 21 MARCH 2023 Location: Harbor of Refuge

#### 1. Road

Condition: Satisfactory Unsatisfactory Not Applicable Comments:

#### 2. Rail spur

Condition: Satisfactory Unsatisfactory Not Applicable Comments: 28 February 2023 quarterly track evaluation performed By Diamond K Services.

#### 3. Main Frame & Floats

Condition: Satisfactory Unsatisfactory Not Applicable Comments:

#### 4. Environmental

Condition: Satisfactory Unsatisfactory Not Applicable Comments:

#### 5. Water Lines, Valves, Etc.

Condition: Satisfactory Unsatisfactory Not Applicable Comments:

#### 6. Electrical & Lights

Condition: Satisfactory Unsatisfactory Not Applicable Comments:

#### 7. PERMIT

Condition: Satisfactory Unsatisfactory Not Applicable Comments: 2 March 2023 CRG picked up nine drums with dirt delivered to land fill.

#### 8. Rub Rails & Fenders

Condition: Satisfactory Unsatisfactory Not Applicable Comments:

#### 9. Cleats & Kevels

Condition: Satisfactory Unsatisfactory Not Applicable Comments:

#### 10. Gates & Locks

Condition: Satisfactory Unsatisfactory Not Applicable Comments:

## 11. Railing

Condition: Satisfactory Unsatisfactory Not Applicable Comments:

## 12. Cement Cap

Condition: Satisfactory Unsatisfactory Not Applicable Comments:

## 13. Bulkhead

Condition: Satisfactory Unsatisfactory Not Applicable Comments:

## 14. CLEAN UP

Condition: Satisfactory Unsatisfactory Not Applicable Comments: 16 February 2023 Gonzales Contracting completed Spreading material from LCI.

Harbor Master: \_\_\_\_\_