### 121 Massanet St.






9/10/24

District No. 5

## 121 Massanet St.



District No. 5

Correct all hazards			

## **EXTERIOR PROPERTY AREAS (CONT)**

	Yes	No	Condition/Type	Action	Quantity
605.1 Electrical equipment installation All equipment, wiring, appliances properly installed and safe 604.3 Electrical system hazards Correct all hazards			Unable to verify		

### IPMC INSPECTION CHECKLIST

# 121 Massanet EXTERIOR PROPERTY AREAS

	Yes	No	Condition/Type	Action	Quantity
302.1 Sanitation Clean and free from rubbish and garbage	Х				
302.2 Grading and Drainage Erosion of soil, ponding/stagnant water, water within structure	X				
302.3 Sidewalks and Driveways Proper repair, free from hazards (tripping, ice ponding)		Χ	Driveway Cracked and broken		
302.4 Weeds		Χ			
Noxious weeds, growth height 302.5 Rodents Evidence of presence? Harborage?  Weeds Rubbish Garbage Inoperable cars	X		Rat and mouse droppings visible through window		
302.6 Exhaust vents			Unable to verify		
Hazardous discharge/noise  302.7 Accessory structures Structurally sound/ good repair Structure type Garage Fence Wall Other		X	Only foundation left		
302.7 Motor vehicles  Inoperable Unlicensed		Χ			
302.8 Defacement of property Location	Х		Spray Paint on Back wall		
303.1 Pools, Spas and Hot Tubs Clean, sanitary, in good repair		Х	,		
303.1 Enclosure Depth of water > 24"? Barrier height at least 48"? Self latching gate?		X			
307.1 Accumulation of Rubbish/ Garbage Free of		Х			
307.2 and 307.3 Disposal of Rubbish/Garbage Approved containers 307.2.1 With covers 307.3.1 Garbage facilities Approved grinder, incinerator or leak proof covered container		Х	No Rubbish Cans		
507.1 Storm drainage No nuisance created	X				
Required occupied dwelling unit is provided with three wire service of at least 60 amps in compliance with ICC Electrical Code	X				
604.3 Electrical systems			Unable to Verify		

# IPMC INSPECTION CHECKLIST EXTERIOR STRUCTURE

	1	1	RIOR STRUCTURE		10
	Yes	No	Condition	Action	Quantity
304.1 General		Х	Foundation Damage		
Good repair, structurally sound, sanitary  304.2 Protective treatment (Paint)		X	-		
Is it pre 1978?		^			
If yes, order risk assessment		1			1
304.3 Premises identification	X	1			
(address numbers)	^				
304.4 Structural members		Х	Obvious Fire Damage		
Free from deterioration and capable of		**	Covidus I ii & Suinage		
support					
304.5 Foundation walls		X	Cracks and damage		
Plumb, free from cracks, no rodent entry					
304.6 Exterior walls		X	Fire Damage		
Sound, weatherproof, coated					
Square feet					
304.7 Roofs and Flashing	X				
0047 Deef desires		77	N. O. W.		
304.7 Roof drainage		X	No Gutters or Downspouts		
Gutters, downspouts, drains	-		N/A		
304.8 Decorative features 304.9 Overhand extensions			N/A		
Good repair, safe, anchored, coated					
304.10 Chimneys and Towers	+	1	N/A	-	
Safe, sound, good repair, coated			IVA		
304.13 Windows		X	Cracked and broken windows		
Sound, good repair, weather tight		A	Cracked and broken windows		
303.13.1 Glazing free of cracks and holes			-		
303.13.2 Openable and hold open					
hardware					
304.14 Insect screens					
304.18.2 Sash locking device within 6 feet					
of ground					
304.15 Doors		X	Hole in back Door		
Good condition, locks, security, egress					
(§702.3)					
304.13 Door frames Sound, good repair,					
weather tight					
			*	,	0
304.18 Security					
304.18.1 Egress			N/A		
304.16 Basement hatchways Prevents entrance of rodents, rain and			N/A		İ
drainage water					
diamage water	1				
<b>304.18.3</b> Security					
304.10 Stairways			N/A		
Structurally sound, good repair					
304.12 Handrails and guardrails					
Firm, good condition					
306.1 Handrails and guardrails					
With 4+risers	-	-	N/A	-	
304.10 Decks, Porches and Balconies Structurally sound, good repair			N/A		
304.12 Handrails and guardrails					
Firm, good condition	1				
306.1 Handrails and guardrails >30 inches					
in height					
304.17 Guards for basement windows			N/A		
Rodent shields			3000.505		
506 Sanitary drainage			N/A		
All fixtures connected to approved			ration and State State		
disposal	1	1			

506.2 Properly maintained			

# EXTERIOR STRUCTURE (CONT)

	Yes	No	Condition/Type	Action	Quantity
604.1 Electrical facilities Required occupied dwelling unit is provided with three wire service of at least 60 amps in compliance with ICC Electrical Code	Х				
604.3 Electrical system hazards Correct all hazards					
605.1 Electrical equipment installation All equipment, wiring, appliances properly installed and safe 604.3 Correct all hazards			Unable to verify		

## IPMC INSPECTION CHECKLIST

#### **FURNACE/WATER HEATER ROOM**

	Yes	No	Condition/Type	Action	Quantity
604.3 Electrical system hazards Correct all hazards			Unable To Verify-		
605.1 Electrical equipment installation All equipment, wiring, appliances properly installed and safe			Unable To Verify		
604.3 Correct all hazards					
605.3 Lighting fixtures At least one present			Unable To Verify		
603.1 Mechanical appliances Properly installed, safe working condition, capable of performing as intended			Unable to Verify		
603.2 Fuel burners connected to approved chimney or vent 603.3 Required clearance from combustibles is maintained 603.4 Safety controls in effective operation					
603.5 Combustion air Is supplied for combustion of fuel and ventilation of space containing fuel burning equipment			Unable to Verify		
603.6 Energy conservation devices Attached to fuel supply or vent and are labeled and properly approved			Unable To Verify		
607.1 Duct systems Free of obstructions and capable of performing required functions			Unable to Verify		
703.1 Fire resistance-rated assemblies Shall be maintained			Unable to Verify		