# Port Lavaca Port Commission Monthly Inspection

Month: 15 FEBRUARY 2022 Location: Harbor of Refuge

# 1. Gangway

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

# 2. Railspur

Condition: Satisfactory Unsatisfactory Not Applicable

Comments: 26 JANUARY 2022 DIAMOND K PERFORMED

QUARTLY INSPECTION OF THE RAIL SPUR ( GOOD SHAPE )

#### 3. Main Frame & Floats

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

#### 4. Environmental

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

#### 5. Water Lines, Valves, Etc.

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

#### 6. Electrical & Lights

Condition: Satisfactory Unsatisfactory Not Applicable

#### Comments:

#### 7. PERMIT

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

#### 8. Rub Rails & Fenders

Condition: Satisfactory Unsatisfactory Not Applicable

Comments: 5 APRIL 2021 FOUND SOME DAMMAGE TO THE VERTICAL

TIMBER AT THE OFFSET IN BULKHEAD "DESIGN PROBLEM" DAMMAGE WAS

DONE BEFORE INSTALLING FENDERS.

#### 9. Cleats & Kevels

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

#### 10. Gates & Locks

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

## 11. Railing

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

## 12. Cement Cap

Condition: Satisfactory Unsatisfactory Not Applicable

Comments:

#### 13. Bulkhead

Condition: Satisfactory Unsatisfactory Not Applicable

	_				
(	$\cap$	m	m	$\triangle$ r	nts:
$\sim$	$\smile$			$\sim$ 1	110.

# 14. Mulch Piles

Condition: 25 JANUARY 2022 GIS FLEW PILES BY DRONE AND CALCULATED 7303 CUBIC YARDS OF MULCH ON SITE.

Harbor Master:	
----------------	--