

Parks Quarterly Report from 10/1/25 to 12/31/25

Maintained all City Parks bathrooms and grounds.

Maintained BCC as needed after events.

Maintained all trashcans on piers and bird walk.

Maintain ball fields at Wilson Park, rake and weed control.

Complete Park inspections forms and do repairs as needed.

Pressure Pavilions at Bayfront, City and George Adams Parks.

Replaced light fixtures at George Adams pavilion.

Painted missing strips in parking lot; repaired and painted yellow curbs at BCC.

Replaced 3 Entrance door light fixtures at BBC and repaired 2 pole lights on front sidewalk.

Repaired water fountain and gate at Butterfly Park.

Repaired 1 flagpole at Bayfront veteran memorial and did maintenance on the other flag poles.

We started replacing landscape timbers with plastic borders and replacing sand at LHB volleyball court.

We replaced several GFCI and hung Christmas lights at City Hall and on Main Street.

Relocated desks and file cabinets from several offices for upcoming remodel at City Hall.

Streets Quarterly report

October - December 2025

Zip, grade, prime and seal coat Sanchez Ave

Clean the Corporation Ditch on Williams Street from W Main Street to W Austin Street.

Build Volleyball court at Light House Beach

Clean ditch on Broadway close to Tiney Browning Blvd

Clean ditch next to Sonic from 35 to Independence

Install billiards at Light House Beach

Cut grass around town as needed

Potholes on Saluria Pl, Del Mar Dr, LaSalle Blvd, Harbor Dr, Warehouse St, Border St, Central Ave, Stanley Lester St, Ann St, Benavides St, Travis St, Bowie St, Calhoun St, E Wilson St, Suncrest St, Linnville Dr, Seascape Dr, Royale Dr, Las Brisas St, Biscayne St, Biloxi St, Boston St, Harbor Dr E, Nueces St, Knipling St, N. San Antonio St.

Sweeper Log 10/01/25-12/31/25					
Date	Miles	Load Dumps	Area		
10/17/2025	18	1	Area 2 Brookhollow Estates		
10/21/2025	40	4	Area 2 Brookhollow Estates		
10/22/2025	36	4	Area 2 Brookhollow Estates and Brookhollow		
10/23/2025	43	4	Area 2 Brookhollow		
10/24/2025	48	4	Area 1 Claret Crossing		
10/27/2025	38	4	Area 4 Main thru Virginia		
10/28/2025	33	4	Area 4 Main thru Broadway		
10/29/2025	32	4	Area 4 Commerce thru Live Oak		
10/30/2025	31	4	Area 4 Live Oak & George/ Half League thru Virginia		
11/3/2025	26	4	Area 4 George thru Kipling		
11/4/2025	33	4	Area 2 Benavides & San Faubian		
11/5/2025	28	4	Area 2 San Antonio & Tilley		
11/6/2025	28	4	Area 4 Wilson & Benavides		
11/13/2025	1	0	Area 4 George St		
11/18/2025	29	4	Area 3/4 Oleander & Viola		
11/19/2025	22	3	Area 4 Ann & Leona		
12/8/2025	26	4	Area 4 Lavaca & Nueces		
12/9/2025	23	4	Area 4 Center & Juanita		
12/10/2025	35	4	Area 4 Center and Nueces		
12/11/2025	30	4	Area 4 Center & Ann		
12/15/2025	29	4	Area 4 Guadalupe & Alice Wilkens		
12/22/2025	30	4	Area 2/4 San Faubian & San Antonio		

Work Order Summary w/ Details

Date Printed: 01/05/2026

Page 1 of 4

Work Order #	WO Status	Origin	Priority	Work Type	Work Category	Site	Source Asset	Source Location	Assigned To	Originated	Expected	Completed	Cost \$	Hour(s)
Work requested														
Action Taken														
Comments														

WO001090	Completed	Non-PM	Medium	Reactive Maintenance	Other	Streets, Signs & Sidewalks			Jose Perez	12/22/2025		12/22/2025	0.00	0.00
----------	-----------	--------	--------	----------------------	-------	----------------------------	--	--	------------	------------	--	------------	------	------

water break patch

Tommy, roger and Michael prepped road, Frank, Alex and Oscar patched up

WO001089	Completed	Non-PM	Medium	Reactive Maintenance	Other	Streets, Signs & Sidewalks			Jose Perez	12/22/2025		12/22/2025	0.00	0.00
----------	-----------	--------	--------	----------------------	-------	----------------------------	--	--	------------	------------	--	------------	------	------

water break patch

Tommy, roger and Michael prepped road, Frank, Alex and Oscar patched up

WO001088	Completed	Non-PM	Medium	Reactive Maintenance	Other	Streets, Signs & Sidewalks			Jose Perez	12/22/2025		12/22/2025	0.00	0.00
----------	-----------	--------	--------	----------------------	-------	----------------------------	--	--	------------	------------	--	------------	------	------

Water break patch

Tommy, roger and Michael prepped road, Frank, Alex and Oscar patched up

WO001087	Completed	Non-PM	Medium	Reactive Maintenance	Other	Streets, Signs & Sidewalks			Jose Perez	12/22/2025		12/22/2025	0.00	0.00
----------	-----------	--------	--------	----------------------	-------	----------------------------	--	--	------------	------------	--	------------	------	------

Water break patch

Road Repair completed Tommy, roger and Michael prepped road, Frank, Alex and Oscar patched up

WO001086	Completed	Non-PM	Medium	Reactive Maintenance	Other	Streets, Signs & Sidewalks			Jose Perez	12/22/2025		12/22/2025	0.00	0.00
----------	-----------	--------	--------	----------------------	-------	----------------------------	--	--	------------	------------	--	------------	------	------

Water break patch

Tommy, roger and Michael prepped road, Frank, Alex and Oscar patched up

WO001085	Completed	Non-PM	Medium	Reactive Maintenance	Other	Streets, Signs & Sidewalks			Jose Perez	12/22/2025		12/22/2025	0.00	0.00
----------	-----------	--------	--------	----------------------	-------	----------------------------	--	--	------------	------------	--	------------	------	------

Work Order Summary w/ Details

Date Printed: 01/05/2026

Page 2 of 4

Work Order #	WO Status	Origin	Priority	Work Type	Work Category	Site	Source Asset	Source Location	Assigned To	Originated	Expected	Completed	Cost.\$	Hour(s)
Work requested														
Action Taken														
Comments														
Water break patch														
Tommy, roger and Michael prepped road, Frank, Alex and Oscar patched up														
WO001064	Completed	Non-PM	Medium		Other	Streets, Signs & Sidewalks			Jose Perez	12/03/2025		12/17/2025	0.00	0.00
lights														
Put up Christmas lights at Bayfront and hang the Christmas light and banners.														
WO001041	Completed	Non-PM	Medium	Reactive Maintenance	Other	Streets, Signs & Sidewalks			Jose Perez	11/03/2025	10/25/2025	10/27/2025	0.00	0.00
Customer called that the yield sign at 5th and Justice was down.														
Notify Jose about the sign that Monday and they got it fix														
WO001037	Completed	Non-PM		Reactive Maintenance	Other	Streets, Signs & Sidewalks			Jose Perez	10/19/2025		11/19/2025	0.00	0.00
Citizen requested to have the loose rock swept up out of this intersection. He almost fell down on his motorcycle from skating on the rocks.														
Was on State rd, Texdot cleaned it up														
WO001001	Completed	Non-PM	Medium	Reactive Maintenance	Pothole	Streets, Signs & Sidewalks			Jose Perez	09/23/2025		10/22/2025	0.00	0.00
Pot holes														
Potholes were cutout cleaned and filled with cold mix														
WO000999	Completed	Non-PM	Medium	Reactive Maintenance	Pothole	Streets, Signs & Sidewalks			Jose Perez	09/23/2025		10/22/2025	0.00	0.00
pot holes														
Potholes were cut out cleaned and filled with cold mix														

Work Order Summary w/ Details

Date Printed: 01/05/2026

Page 3 of 4

Work Order #	WO Status	Origin	Priority	Work Type	Work Category	Site	Source Asset	Source Location	Assigned To	Originated	Expected	Completed	Cost \$	Hour(s)
Work requested														
Action Taken														
Comments														

WO000939	Completed	Non-PM		Reactive Maintenance	Pothole	Streets, Signs & Sidewalks			Jose Perez	08/18/2025		10/06/2025	0.00	0.00
Sanchez Ave. is in desperate need of pot hole repair.														
Entire road was zip, graded, added limestone, primer and seal coated														

WO000866	Completed	Non-PM	Medium	Reactive Maintenance	Other	Streets, Signs & Sidewalks			Jose Perez	06/26/2025		10/21/2025	0.00	0.00
sink hole														
Filled with top soil														

WO000374	Completed	Non-PM		Reactive Maintenance	Pothole	Streets, Signs & Sidewalks			Jose Perez	03/17/2025		10/06/2025	0.00	0.00
The whole street is in desperate need of pothole repairs.														
Entire road was zip, graded, added limestone, primer and seal coated														

WO000315	Completed	Non-PM	Medium	Reactive Maintenance	Pothole	Streets, Signs & Sidewalks			Jose Perez	02/25/2025		11/19/2025	0.00	0.00
Fill pot holes														
Potholes were cut and filled with coldmix the week before the faire, city side was done but notice potholes in trailer property did not do														
Customer reported there are several pot holes along Henry Barber Way														

WO000254	Completed	Non-PM	Medium	Improvements	Other	Streets, Signs & Sidewalks			Jose Perez	01/23/2025		11/19/2025	0.00	0.00
Ditch cleaning														
Got water flowing, couldnt do to much do to shallow gas line.														

Work Order Summary w/ Details

Date Printed: 01/05/2026

Page 4 of 4

Work Order #	WO Status	Origin	Priority	Work Type	Work Category	Site	Source Asset	Source Location	Assigned To	Originated	Expected	Completed	Cost \$	Hour(s)
Work requested														
Action Taken														
Comments														

WO000143	Completed	Non-PM	Medium	Reactive Maintenance	Pothole	Streets, Signs & Sidewalks			Jose Perez	09/11/2024		10/06/2025	0.00	0.00
----------	-----------	--------	--------	----------------------	---------	----------------------------	--	--	------------	------------	--	------------	------	------

pot holes

Entire road was zip, graded, added limestone, primer and seal coated

There are multiple pot holes on Sanchez Ave that need to be filled

WO000018	Completed	Non-PM	Medium	Reactive Maintenance	Other	Streets, Signs & Sidewalks			Jose Perez	02/21/2024		11/19/2025	0.00	0.00
----------	-----------	--------	--------	----------------------	-------	----------------------------	--	--	------------	------------	--	------------	------	------

curb holds water

Nothing to do, the whole street is like that, slow draining of water.

Records Selected: 18

Total Cost \$ 0.00
Total Hrs 0.00

Report Parameters

Filter:

Search:

Advanced Filters: [Site] Equals 'Streets, Signs & Sidewalks' And [Site] Equals 'Streets, Signs & Sidewalks' And [Completed] Between '10/01/2025' And '12/31/2025'

Tags:

Utility Quarterly Report

For the month of October, the Utility Department did 3 Sewer Complaints, 1 Hydrant replacement, 2 hydrant repairs and 5 Main line repairs.

For the month of November, the Utility Department did 8 Sewer complaints, 1 Hydrant Replacement and 7 Main line repairs.

For the month of December, the Utility Department did 19 Sewer Complaints ,2 Sewer service line repairs, 5 Main line repairs, 1 Water service line repair, 3 Water taps and 2 Hydrant Replacements

Wastewater Quarterly Report

For the Month of October, the Wastewater Department did Daily Lab Operations, the Lift station Inspections, changed 3 electrical Breakers at Brooks Lift station and dipped the lift stations.

For the month of November, the Wastewater Department did Daily Lab Operations, the Lift stations Inspections, the Quarterly Bio Samples, Mowed the lift stations, Clean the Clarifier to get repair and dipped the lift stations.

For the Month of December, the Wastewater Department did Daily Lab Operations, the Lift stations Inspections and dipped the Lift stations.

October

DATE	Daily E-COCCI	Daily LOG	Daily pH	Daily D.O.	BOD MG/L	LOAD LBS.	TSS MG/L	LOAD LBS.	LOAD LBS.	NH3 MG/L	LOAD LBS.	FLOW MGD	Daily RAIN	COPPER mg/L	COPPER ug/L	LOAD LB/DAY	ZINC mg/L	ZINC ug/L	LOAD LB/DAY	
1	1.00	0.00										1.21	0.00							
2	1.00	0.00	6.7	6.7	2.2	21.0	2.7	26.5	0.041	0.397	1.16	0.00	0.00							
3	5.20	0.72										1.34	0.18							
4	2.00	0.30										1.16	0.00							
5	12.10	1.08										1.23	0.00							
6	6.00	0.78										1.20	0.00							
7	6.10	0.79	7.4	7.1	2.0	20.2	1.6	15.9	0.040	0.404	1.21	0.00	0.00	0.00739	7.39	0.0746	0.0266	26.60	0.2684	
8	7.20	0.86										1.19	0.00							
9	5.00	0.70		6.8	2.0	20.2	2.2	22.3	0.040	0.404	1.21	0.00	0.00							
10	7.10	0.85										1.15	0.00							
11	4.10	0.61										1.08	0.00							
12	3.00	0.48										1.15	0.00							
13	6.10	0.79										1.21	0.00							
14	1.00	0.00	7.6	6.9	3.0	29.0	2.7	26.5	0.040	0.387	1.16	0.00	0.00	0.00618	6.18	0.0598	0.0235	23.50	0.2273	
15	3.00	0.48										1.09	0.00							
16	2.00	0.30		6.8	2.0	19.2	1.6	15.2	0.040	0.384	1.15	0.00	0.00							
17	4.00	0.60										1.11	0.10							
18	6.10	0.79										1.14	0.00							
19	2.00	0.30										1.17	0.00							
20	4.10	0.61										1.17	0.00							
21	6.00	0.78	7.5	6.6	2.4	21.6	2.0	18.0	0.040	0.360	1.08	0.00	0.00	0.00597	5.97	0.0538	0.0188	18.80	0.1693	
22	3.00	0.48										1.19	0.00							
23	3.00	0.48		6.9	2.0	19.7	1.6	15.8	0.040	0.394	1.18	0.00	0.00							
24	1.00	0.00										1.45	0.96							
25	2.00	0.30										1.46	0.15							
26	1.00	0.00										1.28	0.00							
27	3.00	0.48										1.21	0.00							
28	2.00	0.30	7.6	6.7	3.0	32.2	3.1	33.5	0.041	0.445	1.30	0.18	0.00	0.00526	5.26	0.0570	0.0193	19.30	0.2093	
29	6.10	0.79										1.11	0.00							
30	3.00	0.48		7.7	2.0	17.8	2.1	18.8	0.066	0.589	1.07	0.00	0.00							
31	7.10	0.85										0.93	0.00							
TOTAL	1.0	15.95	30.0	62.2	20.5	200.9	19.7	192.6	0.388	3.8	36.75	1.57	0.02480	24.80	0.2452	0.0882	88.20	0.8744		
AVERAGE	3.9	0.50	7.5	6.9	2.3	22.3	2.2	21.4	0.043	0.4	1.19	0.05	0.00620	6.200	0.0613	0.0221	22.050	0.2186		
MAXIMUM	12.1	GEOMEAN	7.6	7.7	3.0	32.2	3.1	33.5	0.066	0.6	1.46	0.96	0.00739	7.390	0.0746	0.0266	26.600	0.2684		
MINIMUM	1.0	3.2	7.4	6.6	2.0	17.8	1.6	15.2	0.040	0.4	1.07	0.00	0.00526	5.26	0.0538	0.0188	18.80	0.1693		

November

DATE	Daily E-COCCI	Daily pH	Daily D.O.	BOD MG/L	LOAD LBS.	TSS MG/L	LOAD LBS.	NH3 MG/L	LOAD LBS.	FLOW MGD	Daily RAIN	COPPER mg/L	COPPER ug/L	LOAD LB/DAY	ZINC mg/L	ZINC ug/L	LOAD LB/DAY
1	15.80	7.20								1.15	0.15						
2	2.00	7.30								1.14	0.00						
3	1.00	7.50								1.13	0.00						
4	1.00	7.50	7.3	2.0	19.5	2.0	19.5	0.0	0.4	1.17	0.00	0.00488	4.88	0.0476	0.0191	19.10	0.1864
5	1.00	7.50								1.10	0.00						
6	1.00	7.50	6.8	2.4	21.8	2.1	19.2	0.1	0.6	1.09	0.00						
7	1.00	7.50								1.13	0.00						
8	1.00	7.50								1.09	0.00						
9	4.00	7.50								1.09	0.00						
10	2.00	7.50								1.02	0.00						
11	3.00	7.60	8.0	2.0	17.2	2.0	17.5	0.1	0.4	1.03	0.00	0.00514	5.14	0.0442	0.0202	20.20	0.1735
12	1.00	7.60								1.21	0.00						
13	3.10	7.60	7.3	2.5	23.6	1.9	17.8	0.1	0.5	1.13	0.00						
14	2.00	7.60								1.09	0.00						
15	32.70	7.60								1.12	0.00						
16	2.00	7.60								1.21	0.00						
17	1.00	7.60								1.21	0.00						
18	6.20	7.60	7.0	2.0	19.8	1.9	19.0	0.1	0.5	1.19	0.00	0.00499	4.99	0.0495	0.0212	21.20	0.2104
19	2.00	7.60								1.23	0.00						
20	1.00	7.60	6.9	2.8	28.2	2.2	21.9	0.1	1.0	1.19	0.00						
21	1.00	7.60								1.14	0.00						
22	2.00	7.60								1.09	0.00						
23	2.00	7.60								1.14	0.01						
24	3.00	7.60								1.23	0.16						
25	1.00	7.60	7.0	5.2	48.9	5.6	52.6	0.1	1.4	1.13	0.00	0.00468	4.68	0.0441	0.0215	21.50	0.2026
26	3.00	7.60	6.7	3.3	30.3	1.5	13.5	0.0	0.4	1.10	0.00						
27	2.00	7.60								0.95	0.00						
28	1.00	7.60								1.04	0.02						
29	4.00	7.60								1.01	0.09						
30	2.00	7.60								1.15	0.21						
TOTAL	1.0	30.3	57.1	22.2	208.3	19.2	181.0	0.55	5.24	33.70000	0.64	0.0197	19.6900	0.19	0.0820	82	0.772918
AVERAGE	3.5	7.6	7.1	2.8	26.2	2.4	22.6	0.07	0.65	1.12333	0.021	0.0049	4.9225	0.046	0.0205	20.5	0.193229
MAXIMUM	32.7	7.6	8.0	5.2	48.9	5.6	52.6	0.15	1.40	1.23000	0.210	0.0051	5.1400	0.050	0.0215	21.5	0.210402
MINIMUM	1.0	7.5	6.7	2.0	17.2	1.5	13.5	0.95	0.00	0.00468	4.68	0.0047	4.6800	0.04	0.0191	19.1	0.173522

Work Order Summary w/ Details

Date Printed: 01/05/2026

Page 1 of 7

Work Order #	WO Status	Origin	Priority	Work Type	Work Category	Site	Source Asset	Source Location	Assigned To	Originated	Expected	Completed	Cost \$	Hour(s)
Work requested														
Action Taken														
Comments														

WO001111	Completed	Non-PM	Medium	Reactive Maintenance	Water Leak	Water Distribution			Mario Garza	01/02/2026	12/29/2025	12/29/2025	0.00	0.00
----------	-----------	--------	--------	----------------------	------------	--------------------	--	--	-------------	------------	------------	------------	------	------

Customer called that there was water going down the street
pump the water out of the meter box to find out that the gasket on the customer side of the meter was leaking replace the gasket and turn the water back on

WO001106	Completed	Non-PM	Medium	Reactive Maintenance	Water Leak	Water Distribution			Mario Garza	01/02/2026	12/23/2025	12/23/2025	0.00	0.00
----------	-----------	--------	--------	----------------------	------------	--------------------	--	--	-------------	------------	------------	------------	------	------

check around the meter to see what's leaking
dug the grass up to find out that 3/4" poly was leaking at a coupling cut the poly out and replace 3 ft of poly used 2 couplings to reconnect the poly back backfill

WO001105	Closed	Non-PM	Medium	Reactive Maintenance	Water Leak	Water Distribution			Mario Garza	01/02/2026	12/22/2025	12/22/2025	0.00	0.00
----------	--------	--------	--------	----------------------	------------	--------------------	--	--	-------------	------------	------------	------------	------	------

meter tech. called that the ditch was full of water
Dug the grass up to find out that 6" ac main had a crack around it used a clamp 7 1/2"(7.05-7.45) to fix the problem backfill clean up needed

WO001104	In Progress	Non-PM	Medium	Reactive Maintenance	Water Leak	Water Distribution			Mario Garza	01/02/2026	12/20/2025	12/20/2025	0.00	0.00
----------	-------------	--------	--------	----------------------	------------	--------------------	--	--	-------------	------------	------------	------------	------	------

Customer called that there was water coming out of the road
Dug the street up to find out that 6" cast iron pipe had a crack next to a bell turn the water off a replace 3-ft of pipe with pvc used 2 dressers to reconnect the pipe Backfilled Road repair needed

WO001098	Closed	Non-PM	Medium	Reactive Maintenance	Water Leak	Water Distribution			Mario Garza	01/02/2026	12/16/2025	12/16/2025	0.00	0.00
----------	--------	--------	--------	----------------------	------------	--------------------	--	--	-------------	------------	------------	------------	------	------

Customer called that there was water going down the road
Dug the grass up to find out that the 6" cast iron main had a crack in between 2 clamps turn the water off and cut a 3 ft section of the main replace it with pvc used 2 dressers to reconnect the main turn the water back on and backfill clean up needed

WO001096	Closed	Non-PM	Medium	Reactive Maintenance	Water Leak	Water Distribution			Mario Garza	01/02/2026	12/13/2025	12/13/2025	0.00	0.00
----------	--------	--------	--------	----------------------	------------	--------------------	--	--	-------------	------------	------------	------------	------	------

Work Order Summary w/ Details

Date Printed: 01/05/2026

Page 2 of 7

Work Order #	WO Status	Origin	Priority	Work Type	Work Category	Site	Source Asset	Source Location	Assigned To	Originated	Expected	Completed	Cost \$	Hour(s)
Work requested														
Action Taken														
Comments														
customer called that there was a lot of water on the back of the property														
marked the area and called locates on it.dug the grass up to find out that 6" cast iron pipe had a clamp leaking. Turn the water off and replaced the clamp with a longer one. Backfill Clean up needed														
WO001092	Closed	Non-PM	Medium	Reactive Maintenance	Water Leak	Water Distribution			Mario Garza	12/31/2025	11/26/2025	11/26/2025	0.00	0.00
Customer called that there was water coming out of the grass														
Dug the grass up to find out that 4" cast iron pipe had a hole in it used a 7 1/2" (4.74-5.14) clamp to fix the problem. Backfill Clean up needed														
WO001084	Completed	Non-PM	Medium	Reactive Maintenance	Other	Water Distribution			Mario Garza	12/18/2025	12/18/2025	12/18/2025	0.00	0.00
Repair hydrant per fire department request leaking at bottom of upper barrel														
Repair broken hydrant														
WO001078	Closed	Non-PM	Medium	Reactive Maintenance	Water Leak	Water Distribution			Mario Garza	12/05/2025	11/26/2025	11/26/2025	0.00	0.00
Customer called that there was water on the front yard														
Dug the grass up to find out that 4" cast iron pipe had a crack around it used a 7 1/2" (4.74-5.14) clamp to fix the problem backfill clean up needed														
WO001073	Closed	Non-PM	Medium	Improvements	Other	Water Distribution			Mario Garza	12/05/2025		12/23/2025	0.00	0.00
Replace broken hydrant														
dug the grass up to clear the hydrant out. Turn the water off and replace the hydrant backfill clean up needed														
WO001072	Closed	Non-PM	Medium	Improvements	Other	Water Distribution			Mario Garza	12/05/2025		12/15/2025	0.00	0.00
Replace broken hydrant														
dug the grass up to expose the hydrant. Turn the water off and replace the hydrant backfill clean up needed														

Work Order Summary w/ Details

Date Printed: 01/05/2026

Page 3 of 7

Work Order #	WO Status	Origin	Priority	Work Type	Work Category	Site	Source Asset	Source Location	Assigned To	Originated	Expected	Completed	Cost \$	Hour(s)
WO001071	Closed	Non-PM	Medium	Reactive Maintenance	Water Leak	Water Distribution			Mario Garza	12/05/2025		12/12/2025	0.00	0.00
Work requested,														
Action Taken														
Comments														
Customer called that there's water on his front yard														
hydro excavate the area to find out that 6" ac main was leaking at a clamp. Turn the water of and replace the clamp. Backfill clean up needed														
WO001070	Closed	Non-PM	Medium	Improvements	Water Tap	Water Distribution			Mario Garza	12/03/2025	12/03/2025	12/05/2025	0.00	0.00
Install new water taps for Speedy Stop														
install new water taps for speedy stop 2" water tap for the building, 2" water tap for the carwash and 1" irrigation backfill clean up needed														
WO001069	Closed	Non-PM	Medium	Reactive Maintenance	Water Leak	Water Distribution			Mario Garza	12/03/2025	12/01/2025	12/08/2025	0.00	0.00
Customer called that there's water on her yard														
dug the grass up to find out that 6" ac main had a crack around the pipe used a 6" clamp (7.05-7.45) to fix the problem. Backfill clean up needed														
WO001067	In Progress	Non-PM	Medium	Reactive Maintenance	Water Leak	Water Distribution			Mario Garza	12/03/2025	11/26/2025	11/26/2025	0.00	0.00
Customer called that there was water on the ditch														
Dug the side of the ditch up to find out that 2" pvc male adapter was broken at the tee Turn the water off and replace the male adapter reconnect it with a dresser backfill clean up needed road repair needed														
WO001066	Closed	Non-PM	Medium	Reactive Maintenance	Water Leak	Water Distribution			Mario Garza	12/03/2025	11/25/2025	11/25/2025	0.00	0.00
Customer called that there was water on the yard														
Dug the grass up to find out that 3/4" poly had a pin hole in it used 2 coupling and 2 ft of poly to fix the problem backfill clean up needed														
WO001065	Completed	Non-PM	Medium	Reactive Maintenance	Water Leak	Water Distribution			Mario Garza	12/03/2025	11/24/2025	11/24/2025	0.00	0.00
Customer called that there was water on the ditch														

Work Order Summary w/ Details

Date Printed: 01/05/2026

Page 4 of 7

Work Order #	WO Status	Origin	Priority	Work Type	Work Category	Site	Source Asset	Source Location	Assigned To	Originated	Expected	Completed	Cost \$	Hour(s)
Work requested														
Action Taken														
Comments														
Dug the side of ditch up to find out that 3/4" poly was leaking at the corporation turn the water off and replace 3 ft of poly used a coupling to reconnect the service line back. backfillclean up neededroad repair neededRoad Repair completedTommy, roger and Michael preped road, Frank, Alex and oscar patched up														
WO001063	Closed	Non-PM	Medium	Reactive Maintenance	Water Leak	Water Distribution			Mario Garza	12/02/2025	11/19/2025	11/19/2025	0.00	0.00
Customer called that there was a lot of water on the front yard														
Dug the grass up to find out that 3/4" poly was leaking at the corporation turn the water off and replace the poly from the main to the meter. used a new curbstop to reconnect the line backBackfillClean up needed														
WO001062	Closed	Non-PM	Medium	Reactive Maintenance	Water Leak	Water Distribution			Mario Garza	12/02/2025	11/18/2025	11/18/2025	0.00	0.00
Customer called that there was water going down the street														
Dug the grass up to find out that 2" ac main had a crack around the pipe used a 7 1/2" (2.97-3.25) clamp to fix the problem.backfillclean up needed														
WO001061	Closed	Non-PM	Medium	Reactive Maintenance	Water Leak	Water Distribution			Mario Garza	12/02/2025	11/18/2025	11/18/2025	0.00	0.00
Customer called that there was water going down the ditch														
Dug the grass up to find out that 8" pvc water main had a leaking clamp replace the clamp to fix the problem. backfillclean up needed														
WO001060	Completed	Non-PM	Medium	Reactive Maintenance	Other	Water Distribution			Mario Garza	12/01/2025	11/28/2025	11/28/2025	0.00	0.00
Customer called that the water was yellow and has a smell														
took a sample on the outside faucet closer to the meter didn't find no smell or color to it notify the customer that the problem will be inside the house														
WO001057	Closed	Non-PM	Medium	Reactive Maintenance	Water Leak	Water Distribution			Mario Garza	12/01/2025	11/21/2025	11/21/2025	0.00	0.00
Customer called that there was water coming out of the ground														
dug the grass up to find out that 4" cast iron main had a crack around the pipe used a 7 1/2" clamp (4.74-5.14) to fix the problem backfill clean up needed														

Work Order Summary w/ Details

Date Printed: 01/05/2026

Page 5 of 7

Work Order #	WO Status	Origin	Priority	Work Type	Work Category	Site	Source Asset	Source Location	Assigned To	Originated	Expected	Completed	Cost \$	Hour(s)
WO001056	Closed	Non-PM	Medium	Reactive Maintenance	Water Leak	Water Distribution			Mario Garza	12/01/2025	11/20/2025	11/20/2025	0.00	0.00
<p>Work requested</p> <p>Action Taken</p> <p>Comments</p> <p>Customer called that there was water coming out of the grass</p> <p>Dug the grass up to find that 2" pvc main had a leaking dresser and was not lining up expose 20 ft to find a good area to reconnect.reconnect the main using 2 dressers backfillclean up needed</p>														
WO001054	Completed	Non-PM	Medium	Reactive Maintenance	Water Leak	Water Distribution			Mario Garza	11/25/2025	11/12/2025	11/12/2025	0.00	0.00
<p>Customer called that there was water going down the road</p> <p>Dug the road up to find out that 6" cast iron main blew out 3 ft of pipe turn the water off and replace 6 ft of pipe because we found a clamp further up used 2 dressers to reconnect the pipe back turn the water back on Backfill</p>														
WO001051	Completed	Non-PM	Medium	Reactive Maintenance	Water Leak	Water Distribution			Mario Garza	11/25/2025	10/17/2025	10/17/2025	0.00	0.00
<p>Contractor broke the water main by accident</p> <p>Dug the rest of the area where they had hit the line to expose it.Rreplace 4 ft of 6" ac line with pvc used 2 dressers to reconnect it back backfill</p>														
WO001050	Completed	Non-PM	Medium	Reactive Maintenance	Water Leak	Water Distribution			Mario Garza	11/25/2025	10/19/2025	10/19/2025	0.00	0.00
<p>Customer called that there was water going down the street</p> <p>Dug up the limestone driveway to find out that 2" cast iron pipe had a hole in it expose it and the pipe crack further back 5 ft cut the pipe out and replace it with pvc used 2 dressers to reconnect it back Backfilled the hole</p>														
WO001047	Completed	Non-PM	Medium	Reactive Maintenance	Water Leak	Water Distribution			Mario Garza	11/18/2025	11/02/2025	11/02/2025	0.00	0.00
<p>Customer called that he had no water pressure</p> <p>Check around the meter area and find out that the service line was broken at a tee replace the tee and reconnect the service to fix the problem</p>														
WO001046	Closed	Non-PM	Medium	Reactive Maintenance	Water Leak	Water Distribution			Mario Garza	11/18/2025	10/31/2025	11/01/2025	0.00	0.00

Work Order Summary w/ Details

Date Printed: 01/05/2026

Page 6 of 7

Work Order #	WO Status	Origin	Priority	Work Type	Work Category	Site	Source Asset	Source Location	Assigned To	Originated	Expected	Completed	Cost \$	Hour(s)
Work requested														
Action Taken														
Comments														
Alamo concrete called that there was a leak on the back of their property														
Dug the grass up to find out that 8" ac main had a crack around the pipe used a 8" clamp 7 1/2 " (9.27-9.67) to fix the problem.Backfill clean up needed														
WO001044	Completed	Non-PM	Medium	Reactive Maintenance	Water Leak	Water Distribution			Mario Garza	11/05/2025	10/27/2025	10/27/2025	0.00	0.00
Customer called that they had no water pressure inside the house														
Check the pressure outside the house it was good notify customer about the problem being inside the house														
WO001040	Closed	Non-PM	Medium	Reactive Maintenance	Water Leak	Water Distribution			Mario Garza	11/03/2025	10/21/2025	10/23/2025	0.00	0.00
Check the area for leak under the driveway														
Dug under the driveway to find out that 3/4" copper line had a crack close to the corporation turn the water off and replace 3 ft of copper line with poly use a (cts x cts) coupling to reconnect the service line back. BackfillClean up needed														
WO001038	Completed	Non-PM		Reactive Maintenance	Water Leak	Water Distribution			Mario Garza	10/20/2025	10/27/2025	10/27/2025	0.00	0.00
Observed water rising from the ground Saturday, October 18, 2025. I called the city of Port Lavaca Dispatch to inform them I believe there was a water leak. The water has continued to rise in part of my and the neighbors behind me backyard.														
Dug the back yard to find out that 1" poly had a crack in it used 2 (cts x cts) couplings to fix the problem backfill														
WO001029	Completed	Non-PM	Medium	Reactive Maintenance	Water Leak	Water Distribution			Mario Garza	10/16/2025	10/12/2025	10/12/2025	0.00	0.00
Customer called that there was water going down the street														
Follow the water back to his meter pump the water out to find out that the meter was leaking at the customer side turn the water off and replace the gasket turn it back on and no more leaks notify the customer of what the problem was.														
WO001026	Closed	Non-PM	Medium	Reactive Maintenance	Water Leak	Water Distribution			Mario Garza	10/16/2025	10/09/2025	10/09/2025	0.00	0.00
Repair Water main														

Work Order Summary w/ Details

Date Printed: 01/05/2026

Page 7 of 7

Work Order #	WO Status	Origin	Priority	Work Type	Work Category	Site	Source Asset	Source Location	Assigned To	Originated	Expected	Completed	Cost \$	Hour(s)
Work requested														
Action Taken														
Comments														

Dug the grass up to find out that 2" ac main had a crack around it used a 7 1/2" clamp (2.97-3.27) to fix the problem. backfillClean up needed

WO001005	Completed	Non-PM	Medium	Reactive Maintenance	Dress up (utility)	Water Distribution			Mario Garza	09/23/2025		10/14/2025	0.00	0.00
The driveway needs to be repaired, and a clean-up needs to be done.														
clean the area and add top soil														

WO000996	Closed	Non-PM	Medium	Reactive Maintenance	Other	Water Distribution			Mario Garza	09/23/2025		10/14/2025	0.00	0.00
Customer says there is a sink hole in the back yard where the utility lines run.														

WO000236	Completed	Non-PM	Medium	Reactive Maintenance	Water Leak	Water Distribution			Ryan Chapman	01/15/2025	12/20/2024	12/23/2025	0.00	0.00
Customer call that there was a wet spot on the side of the road														
Dug up the road to find out that tap saddle was leaking turn the water off and replace the saddle reconnect the serviceBackfill Road repair needed														

Records Selected: 36

Total Cost \$ 0.00
Total Hrs 0.00

Report Parameters

Filter:

Search:

Advanced Filters: [Site] Equals 'Water Distribution' And [Site] Equals 'Water Distribution' And [Completed] Between '10/01/2025' And '12/31/2025'

Tags:

Work Order Summary w/ Details

Date Printed: 01/05/2026

Page 1 of 7

Work Order #	WO Status	Origin	Priority	Work Type	Work Category	Site	Source Asset	Source Location	Assigned To	Originated	Expected	Completed	Cost \$	Hour(s)
WO001114	Completed	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	01/02/2026	12/31/2025	12/31/2025	0.00	0.00
<p>Work requested</p> <p>Action Taken</p> <p>Comments</p> <p>Customer call that she was having issues with the sewer</p> <p>Run the sewer tape thru the cityside clean out 60 ft to clear the line</p>														
WO001113	Completed	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	01/02/2026	12/31/2025	12/31/2025	0.00	0.00
<p>Customer called that she was having issues with her sewer</p> <p>Check the cityside clean out it was empty notify the customer that the problem was on her side</p>														
WO001112	Completed	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	01/02/2026	12/30/2025	12/30/2025	0.00	0.00
<p>Customer called that there was sewer draining down his driveway</p> <p>Started checking clean outs going north of the address to find out where the problem was found the manhole at Austin and Guadalupe was holding water try to run the line towards Leona couldn't run it took the gravers to find out that rainwater cover had fallen in the manhole and cover the drainpipe and prevent it from flowing pull it out and it began to flow</p>														
WO001110	Completed	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	01/02/2026	12/28/2025	12/28/2025	0.00	0.00
<p>Customer called that the manhole on MLK and Juanita was overflowing</p> <p>Run the sewer jet hose thru the manhole in front of 623 s Juanita towards Austin 480 ft to clear the line</p>														
WO001109	Completed	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	01/02/2026	12/28/2025	12/28/2025	0.00	0.00
<p>Customer called that the clean out next to the house was overflowing</p> <p>Run the cityside clean out 45 ft to clear the line</p>														
WO001108	Completed	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	01/02/2026	12/27/2025	12/27/2025	0.00	0.00

Work Order Summary w/ Details

Date Printed: 01/05/2026

Page 2 of 7

Work Order #	WO Status	Origin	Priority	Work Type	Work Category	Site	Source Asset	Source Location	Assigned To	Originated	Expected	Completed	Cost \$	Hour(s)
Work requested														
Action Taken														
Comments														
Customer called that she had issues with the sewer														
run the sewer tape thru the cityside clean out 50 ft to clear the line														
WO001107	Completed	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	01/02/2026	12/21/2025	12/21/2025	0.00	0.00
Customer called that they were having issues with their sewer														
Run the sewer jet hose thru the dead end clean out 35 ft to clear the main														
WO001103	New Work Order	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	01/02/2026	12/29/2025	12/29/2025	0.00	0.00
Customer called that she was having issues with sewer														
Run the sewer tape through the customers clean out 70 ft to clear the line														
WO001102	New Work Order	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	01/02/2026	12/19/2025	12/19/2025	0.00	0.00
Customer called that he was having issues with the sewer														
Run the sewer tape thru the customer clean out 70 ft to clear the line 12/23/25 run the camera through the clean out found a separation on the line marked the area and called locates to dig up the area														
WO001101	Completed	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	01/02/2026	12/18/2025	12/18/2025	0.00	0.00
Customer called that they were having issues with the sewer														
Check the clean out outside it was empty notify the customer that the problem was on her side														
WO001100	Completed	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	01/02/2026	12/17/2025	12/17/2025	0.00	0.00
Customer called that he was having issues with the sewer														
checked the cityside clean out it was empty notify the customer that the problem was on his side														

Work Order Summary w/ Details

Date Printed: 01/05/2026

Page 3 of 7

Work Order #	WO Status	Origin	Priority	Work Type	Work Category	Site	Source Asset	Source Location	Assigned To	Originated	Expected	Completed	Cost \$	Hour(s)
Work requested														
Action Taken														
Comments														

WO001099	Completed	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	01/02/2026	12/15/2025	12/15/2025	0.00	0.00
Customer called that there was sewer in the front yard														
Run the cityside clean out 15 ft to clear the line														

WO001097	Closed	Non-PM	Medium	Reactive Maintenance	Sewer Tap	Wastewater Collection			Mario Garza	01/02/2026	12/10/2025	12/10/2025	0.00	0.00
Port Lavaca Plumbing called that the sewer was collapse														
Dug the back yard to find that 4" clay service was complete broken at the main cut a 3 ft section of the main. redid the tap used 2 boots (6") (clay by pvc) to reconnect the main backfill clean up needed														

WO001094	Completed	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	01/02/2026	12/09/2025	12/09/2025	0.00	0.00
Customer called that there was water around the clean out														
Run the cityside clean out 80 ft to clear the line														

WO001093	Completed	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	01/02/2026	12/09/2025	12/09/2025	0.00	0.00
Customer called that the sewer was backing up inside the house														
Run the sewer tape thru the cityside clean out 30 ft to clear the line														

WO001077	Completed	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	12/05/2025	11/24/2025	11/24/2025	0.00	0.00
Customer called that she had sewer issues														
Check the cityside clean out it was empty notify customer that the problem is on her side														

Work Order Summary w/ Details

Date Printed: 01/05/2026

Page 4 of 7

Work Order #	WO Status	Origin	Priority	Work Type	Work Category	Site	Source Asset	Source Location	Assigned To	Originated	Expected	Completed	Cost \$	Hour(s)
WO001076	Completed	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	12/05/2025	11/25/2025	11/25/2025	0.00	0.00
Customer called that they were having issues with their sewer														
Run the sewer jet hose thru the cityside clean out 35 ft to clear the line														
WO001075	Completed	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	12/05/2025	12/02/2025	12/02/2025	0.00	0.00
Green Iguana called that they were having sewer issues														
Run the sewer jet hose thru their cleanout 30 ft to clear the line														
WO001074	Completed	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	12/05/2025	12/01/2025	12/01/2025	0.00	0.00
Daycare called that they were having sewer issues														
Run the sewer tape thru the customers clean out 45 ft to clear the line														
WO001068	Completed	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	12/03/2025	11/28/2025	11/28/2025	0.00	0.00
Customer called that she was having sewer issues														
Run the sewer tape 35 ft thru the cityside clean out to clear the line														
WO001059	Completed	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	12/01/2025	11/27/2025	11/27/2025	0.00	0.00
Customer called that he was having sewer issues														
Run the sewer tape 70 ft thru the customer's clean out to clear the line														
WO001058	Completed	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	12/01/2025	11/23/2025	11/23/2025	0.00	0.00

Work Order Summary w/ Details

Date Printed: 01/05/2026

Page 5 of 7

Work Order #	WO-Status	Origin	Priority	Work Type	Work Category	Site	Source Asset	Source Location	Assigned To	Originated	Expected	Completed	Cost \$	Hour(s)
WO01055	Completed	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	12/01/2025	11/16/2025	11/16/2025	0.00	0.00
<p>Work requested</p> <p>Action Taken</p> <p>Comments</p> <p>Customer called that he had sewer issues</p> <p>Check the cityside clean out it was empty notify customer that the problem was on his side</p>														
WO01053	Completed	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	11/25/2025	11/11/2025	11/11/2025	0.00	0.00
<p>Customer called that the restrooms at the park were backed up</p> <p>Check both of the restrooms they were draining good</p>														
WO01052	Completed	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	11/25/2025	11/11/2025	11/11/2025	0.00	0.00
<p>Monterrey Cafe called that they had sewer issue</p> <p>Checked the clean outs behind the building there were empty notify them that problem was inside the building</p>														
WO01049	Closed	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	11/25/2025	10/29/2025	10/29/2025	0.00	0.00
<p>Customer called that she was having sewer problems</p> <p>Run the sewer tape thru the customers clean out 80 ft to clear the line 11/5/25 run the camera thru the customers clean out found a problem with the pipe 50 ft away from it marked and called locate on the area 11/10/25 dug up the area and replace 10 ft of pipe used a coupling and a boot (pvc x pvc) to reconnect it backfill clean up needed</p>														
WO01045	Completed	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	11/18/2025	11/07/2025	11/07/2025	0.00	0.00
<p>Mexico Tipico called that they were having sewer issues</p> <p>Run the sewer tape thru the cityside clean out 40 ft to clear the line</p>														

Work Order Summary w/ Details

Date Printed: 01/05/2026

Page 6 of 7

Work Order #	WO Status	Origin	Priority	Work Type	Work Category	Site	Source Asset	Source Location	Assigned To	Originated	Expected	Completed	Cost \$	Hour(s)
Work requested														
Action Taken														
Comments														

WO001043	Closed	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	11/04/2025	11/04/2025	11/04/2025	0.00	0.00
----------	--------	--------	--------	----------------------	--------------	-----------------------	--	--	-------------	------------	------------	------------	------	------

Customer called that the sewer was back up
 Run sewer tape thru cityside clean out 3 ft to clear the line. Line needs to be camered 11/05/2025 Camared the service line found a problem 2 ft away from the cleanout marked the property and called locates to dig it up 11/7/25 dug the grass up to find out that 4" pipe had shifted and was below the 90 going down to the main Cut the pipe out and lower the line down used to 45 pvc couplings to reconnect the service back Clean up needed

WO001028	Completed	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	10/16/2025	10/12/2025	10/12/2025	0.00	0.00
----------	-----------	--------	--------	----------------------	--------------	-----------------------	--	--	-------------	------------	------------	------------	------	------

Mexico Tipico called that their sewer was backed up
 Run sewer tape thru the customers clean out 40 ft to clear the line found a lot of grease

WO001027	Completed	Non-PM	Medium	Reactive Maintenance	Sewer Backup	Wastewater Collection			Mario Garza	10/16/2025	10/11/2025	10/11/2025	0.00	0.00
----------	-----------	--------	--------	----------------------	--------------	-----------------------	--	--	-------------	------------	------------	------------	------	------

Customer called that the sewer was backing up
 try to run the sewer tape thru the customers clean out tape only went 10 feet notify customer that he had to find his line further up on the property in order for us to use our equipment

WO000998	Completed	Non-PM	Medium	Reactive Maintenance	Other	Wastewater Collection			Mario Garza	09/23/2025		10/23/2025	0.00	0.00
----------	-----------	--------	--------	----------------------	-------	-----------------------	--	--	-------------	------------	--	------------	------	------

Clean out cap is missing
 the cap that was missing on the customer's side

Records Selected: 31

Total Cost \$ 0.00
 Total Hrs 0.00

Report Parameters

Filter:

Work Order Summary w/ Details

Date Printed: 01/05/2026

Page 7 of 7

Work Order #	WO Status	Origin	Priority	Work Type	Work Category	Site	Source Asset	Source Location	Assigned To	Originated	Expected	Completed	Cost \$	Hour(s)
Work requested														
Action Taken														
Comments														

Search:

Advanced Filters: [Site] Equals 'Wastewater Collection' And [Site] Equals 'Wastewater Collection' And [Completed] Between '10/01/2025' And '12/31/2025'

Tags: