

From: [Jose Villalon](#)
To: [Lorena Perez-Diaz](#); [Wayne Shaffer](#); [Joe Villalon](#); [sara@portlavacaevents.com](#); [Edward Tyler](#)
Subject: Re: Playground Safety Checklist - Jose Villalon
Date: Tuesday, August 19, 2025 12:42:25 PM



Playground Safety Checklist

Inspection ID 0034
Name of Park Lighthouse Beach Park Splashpad
Inspection Date 08-19-2025 08:55 AM

General Inspection

| | In Good Condition | Needs Improvement | Notes |
|--|-------------------------------------|-------------------|-------|
| Playground are is free of litter and debris | <input checked="" type="checkbox"/> | - | - |
| Playground area is free of anthills/hazardous insects or toxic plants. | <input checked="" type="checkbox"/> | - | - |
| Playground area is free of holes and other tripping hazards. | <input checked="" type="checkbox"/> | - | - |
| Proper signage with rules, hours, and age-appropriate use is posted. | <input checked="" type="checkbox"/> | - | - |
| Playground area is properly fenced | - | - | N/A |
| Self latching gate works as designed | - | - | N/A |

Surfacing

| | In Good Condition | Needs Improvement | Notes |
|---|-------------------------------------|-------------------|-------|
| Approved surfacing material is used (i.e. solid rubber, artificial graass or turf, play sand, pea gravel, wood chips, rubber mulch) | <input checked="" type="checkbox"/> | - | - |
| Surfacing material under and around equipment is adequate depth (6-12 inches) | <input checked="" type="checkbox"/> | - | - |
| Surfacing material is free of glass, debris, or other foreign objects. | <input checked="" type="checkbox"/> | - | - |
| Surfacing material is not compacting or deteriorating. | <input checked="" type="checkbox"/> | - | - |
| Rubber wear mats are used under high-traffic-use areas and covered by sufficient depth of surfacing material. | - | - | N/A |
| Proper drainage prevents water from forming puddles. | <input checked="" type="checkbox"/> | - | - |

Equipment Hazards

| | In Good Condition | Needs Improvement | Notes |
|--|-------------------------------------|-------------------------------------|--------------------------|
| Equipment is not damaged or vandalized. | <input checked="" type="checkbox"/> | - | - |
| Equipment is free from sharp points, corners, or edges. | <input checked="" type="checkbox"/> | - | - |
| Protective caps or plugs are not missing or damaged. | <input checked="" type="checkbox"/> | - | - |
| Equipment is free of potential clothing entanglement hazards. | <input checked="" type="checkbox"/> | - | - |
| Equipment is free of pinch and crush points or exposed moving parts. | <input checked="" type="checkbox"/> | - | - |
| Equipment is free of rust, rot, cracks, and splinters. | - | <input checked="" type="checkbox"/> | Rust/ resurface, repaint |
| Equipment is free of entrapments. | <input checked="" type="checkbox"/> | - | - |
| Equipment is safely anchored. | <input checked="" type="checkbox"/> | - | - |

Swings

| | In Good Condition | Needs Improvement | Notes |
|---|-------------------|-------------------|-------|
| Hardware and chains are in good condition. | - | - | N/A |
| Swings are a safe distance from other playground equipment. | - | - | N/A |
| Swings are 24 inches apart. | - | - | N/A |
| Edges of seats are smooth and free from obstructions. | - | - | N/A |
| Adequate depths of surfacing material extend out a minimum distance of twice the height of the swing. | - | - | N/A |

Slides

| | In Good Condition | Needs Improvement | Notes |
|--|-------------------|-------------------|-------|
| Slides are free of obstructions and protrusions. | - | - | N/A |
| Equipped with platforms to facilitate access to the sitting position. | - | - | N/A |
| Platforms are equipped with guardrails or equivalent protective equipment. | - | - | N/A |
| Exit regions are level. | - | - | N/A |

Climbing Equipment

| | In Good Condition | Needs Improvement | Notes |
|--|-------------------------------------|-------------------|-------|
| Hand grips are secured and do not rotate. | <input checked="" type="checkbox"/> | - | - |
| Rope or chain ladders are anchored at both ends. | - | - | NA |
| Foot holds/ rungs are in good condition and adequately spaced. | <input checked="" type="checkbox"/> | - | - |

Seesaws

| | In Good Condition | Needs Improvement | Notes |
|---|-------------------|-------------------|-------|
| Seesaws are free of cracks, corrosion, and other obvious structural defects. | - | - | N/A |
| Equipment is provided with spring centering devices or cushioning material to prevent abrupt contact with the ground. | - | - | N/A |
| Fulcrums/ pivot points are free of pinch or crush hazards. | - | - | N/A |
| Handholds are provided at each sitting position. | - | - | N/A |

Inspector Name Jose Villalon

Signature



You can [edit this submission](#) and [view all your submissions](#) easily.