

From: [Jose Villalon](#)
To: [Lorena Perez-Diaz](#); [Wayne Shaffer](#); [Joe Villalon](#); [sara@portlavacaevents.com](#); [Edward Tyler](#)
Subject: Re: Playground Safety Checklist - Jose Villalon
Date: Friday, July 18, 2025 11:29:19 AM



Playground Safety Checklist

Inspection ID 0026
Name of Park George Adams JKF Jr. Dr.
Inspection Date 07-18-2025 10:35 AM

General Inspection

	In Good Condition	Needs Improvement	Notes
Playground are is free of litter and debris	☒	-	-
Playground area is free of anthills/hazardous insects or toxic plants.	☒	-	-
Playground area is free of holes and other tripping hazards.	☒	-	-
Proper signage with rules, hours, and age-appropriate use is posted.	☒	-	-
Playground area is properly fenced	-	-	N/A
Self latching gate works as designed	-	-	N/A

Surfacing

	In Good Condition	Needs Improvement	Notes
Approved surfacing material is used (i.e. solid rubber, artificial graass or turf, play sand, pea gravel, wood chips, rubber mulch)	☒	-	-
Surfacing material under and around equipment is adequate depth (6-12 inches)	☒	-	-
Surfacing material is free of glass, debris, or other foreign objects.	☒	-	-
Surfacing material is not compacting or deteriorating.	☒	-	-
Rubber wear mats are used under high-traffic-use areas and covered by sufficient depth of surfacing material.	☒	-	-
Proper drainage prevents water from forming puddles.	☒	-	-

Equipment Hazards

	In Good Condition	Needs Improvement	Notes
Equipment is not damaged or vandalized.	☒	-	-
Equipment is free from sharp points, corners, or edges.	-	☒	Sharp edges/ resurface,repaint or replace
Protective caps or plugs are not missing or damaged.	☒	-	-
Equipment is free of potential clothing entanglement hazards.	☒	-	-
Equipment is free of pinch and crush points or exposed moving parts.	☒	-	-
Equipment is free of rust, rot, cracks, and splinters.	-	☒	Rust,rot/ resurface,replace
Equipment is free of entrapments.	☒	-	-
Equipment is safely anchored.	-	☒	Broken chain/ replace chain

Swings

	In Good Condition	Needs Improvement	Notes
Hardware and chains are in good condition.	☒	-	-
Swings are a safe distance from other playground equipment.	☒	-	-
Swings are 24 inches apart.	☒	-	-
Edges of seats are smooth and free from obstructions.	☒	-	-
Adequate depths of surfacing material extend out a minimum distance of twice the height of the swing.	☒	-	-

Slides

	In Good Condition	Needs Improvement	Notes
Slides are free of obstructions and protrusions.	-	☒	Hole in slide/ replace slide
Equipped with platforms to facilitate access to the sitting position.	☒	-	-

Platforms are equipped with guardrails or equivalent protective equipment.	☒	-	-
Exit regions are level.	☒	-	-

Climbing Equipment

	In Good Condition	Needs Improvement	Notes
Hand grips are secured and do not rotate.	☒	-	-
Rope or chain ladders are anchored at both ends.	-	☒	Chain is loose/ repair chain
Foot holds/ rungs are in good condition and adequately spaced.	☒	-	-

Seesaws

	In Good Condition	Needs Improvement	Notes
Seesaws are free of cracks, corrosion, and other obvious structural defects.	-	☒	Bad paint,dirt/ pressure was,repaint
Equipment is provided with spring centering devices or cushioning material to prevent abrupt contact with the ground.	☒	-	-
Fulcrums/ pivot points are free of pinch or crush hazards.	☒	-	-
Handholds are provided at each sitting position.	☒	-	-

Inspector Name

Jose Villalon

Signature



You can [edit this submission](#) and [view all your submissions](#) easily.