

Lorena Perez-Diaz

From: Jose Villalon <noreply@jotform.com>
Sent: Tuesday, June 17, 2025 12:07 PM
To: Lorena Perez-Diaz; Wayne Shaffer; Joe Villalon; sara@portlavacaevents.com; Edward Tyler
Subject: Re: Playground Safety Checklist - Jose Villalon



Playground Safety Checklist



Inspection ID 0004
Name of Park George Adams Center St.
Inspection Date 06-17-2025 10:35 AM

General Inspection








	In Good Condition	Needs Improvement	Notes
Playground are is free of litter and debris		-	-
Playground area is free of anthills/hazardous insects or toxic plants.		-	-
Playground area is free of holes and other tripping hazards.		-	-
Proper signage with rules, hours, and age-appropriate use is posted.		-	-
Playground area is properly fenced	-	-	N/A
Self latching gate works as designed	-	-	N/A

Surfacing






	In Good Condition	Needs Improvement	Notes
Approved surfacing material is used (i.e. solid rubber, artificial graass or turf, play sand, pea gravel, wood chips, rubber mulch)	-		Needs new material
Surfacing material under and around equipment is adequate depth (6-12 inches)		-	-
Surfacing material is free of glass, debris, or other foreign objects.	-		Weeds/ needs mowing
Surfacing material is not compacting or deteriorating.	-		Material is gone needs to be redone

Rubber wear mats are used under high-traffic-use areas and covered by sufficient depth of surfacing material.	-		N/A
Proper drainage prevents water from forming puddles.		-	-

Equipment Hazards

	In Good Condition	Needs Improvement	Notes
Equipment is not damaged or vandalized.		-	-
Equipment is free from sharp points, corners, or edges.		-	-
Protective caps or plugs are not missing or damaged.	-	-	N/A
Equipment is free of potential clothing entanglement hazards.		-	-
Equipment is free of pinch and crush points or exposed moving parts.		-	-
Equipment is free of rust, rot, cracks, and splinters.	-		Rust, cracks/ repaint
Equipment is free of entrapments.		-	-
Equipment is safely anchored.		-	-




Swings

	In Good Condition	Needs Improvement	Notes
Hardware and chains are in good condition.		-	-
Swings are a safe distance from other playground equipment.		-	-
Swings are 24 inches apart.		-	-
Edges of seats are smooth and free from obstructions.		-	-
Adequate depths of surfacing material extend out a minimum distance of twice the height of the swing.		-	-

Slides

	In Good Condition	Needs Improvement	Notes
Slides are free of obstructions and protrusions.	-	-	N/A
Equipped with platforms to facilitate access to the sitting position.	-	-	N/A
Platforms are equipped with guardrails or equivalent protective equipment.	-	-	N/A
Exit regions are level.	-	-	N/A

Climbing Equipment

	In Good Condition	Needs Improvement	Notes
Hand grips are secured and do not rotate.		-	-
Rope or chain ladders are anchored at both ends.		-	-
Foot holds/ rungs are in good condition and adequately spaced.		-	-

Seesaws

In Good Condition	Needs Improvement	Notes
-------------------	-------------------	-------

