

Lorena Perez-Diaz

From: Jose Villalon <noreply@jotform.com>
Sent: Tuesday, June 17, 2025 12:07 PM
To: Lorena Perez-Diaz; Wayne Shaffer; Joe Villalon; sara@portlavacaevents.com; Edward Tyler
Subject: Re: Playground Safety Checklist - Jose Villalon



Playground Safety Checklist

Inspection ID 0006
Name of Park Wilson Park
Inspection Date 06-17-2025 11:10 AM









General Inspection

	In Good Condition	Needs Improvement	Notes
Playground are is free of litter and debris		-	-
Playground area is free of anthills/hazardous insects or toxic plants.		-	-
Playground area is free of holes and other tripping hazards.	-		Hole in floor/ Repair hole
Proper signage with rules, hours, and age-appropriate use is posted.		-	-
Playground area is properly fenced	-	-	N/A
Self latching gate works as designed	-	-	N/A






Surfacing

	In Good Condition	Needs Improvement	Notes
Approved surfacing material is used (i.e. solid rubber, artificial graass or turf, play sand, pea gravel, wood chips, rubber mulch)	-		Hole in floor/ repair hole
Surfacing material under and around equipment is adequate depth (6-12 inches)		-	-
Surfacing material is free of glass, debris, or other foreign objects.		-	-
Surfacing material is not compacting or deteriorating.		-	-
Rubber wear mats are used under high-traffic-use areas and covered by sufficient depth of surfacing material.	-		-
Proper drainage prevents water from forming puddles.		-	-





Equipment Hazards

	In Good Condition	Needs Improvement	Notes
Equipment is not damaged or vandalized.		-	-
Equipment is free from sharp points, corners, or edges.	-		Sharp edges-rust/ Replace
Protective caps or plugs are not missing or damaged.		-	-
Equipment is free of potential clothing entanglement hazards.		-	-
Equipment is free of pinch and crush points or exposed moving parts.		-	-
Equipment is free of rust, rot, cracks, and splinters.	-		Rust/ Replace
Equipment is free of entrapments.		-	-
Equipment is safely anchored.		-	-




Swings

	In Good Condition	Needs Improvement	Notes
Hardware and chains are in good condition.		-	-
Swings are a safe distance from other playground equipment.		-	-
Swings are 24 inches apart.		-	-
Edges of seats are smooth and free from obstructions.		-	-
Adequate depths of surfacing material extend out a minimum distance of twice the height of the swing.		-	-

Slides

	In Good Condition	Needs Improvement	Notes
Slides are free of obstructions and protrusions.		-	-
Equipped with platforms to facilitate access to the sitting position.		-	-
Platforms are equipped with guardrails or equivalent protective equipment.		-	-
Exit regions are level.		-	-

Climbing Equipment

	In Good Condition	Needs Improvement	Notes
Hand grips are secured and do not rotate.		-	-
Rope or chain ladders are anchored at both ends.		-	-
Foot holds/ rungs are in good condition and adequately spaced.	-		Rust-holes/ replace-repair

Seesaws

	In Good Condition	Needs Improvement	Notes
Seesaws are free of cracks, corrosion, and other obvious structural defects.	-	-	N/A
Equipment is provided with spring centering devices or cushioning material to prevent abrupt contact with the ground.	-	-	N/A

Fulcrums/ pivot points are free of pinch or crush hazards.	-	-	N/A
Handholds are provided at each sitting position.	-	-	N/A

Inspector Name

Jose Villalon

Signature



You can [edit this submission](#) and [view all your submissions](#) easily.