

The south red X indicator represents the approximate location of the partial pipe collapse. The north X indicator represents an in-depth repair due to line and drain box failure that was made by PW earlier in the year.

