

# Invoice 10906

Date: March 7, 2025

2601 Forest Creek Dr. Round Rock, TX 78665 512-246-1400 www.crossroadsus.com

#### **Bill To:**

City of Rollingwood 403 Nixon Avenue Rollingwood, TX 78746

		Feb-25
		perations & aintenance
DESCRIPTION	AMOL	JNT
Basic Service	\$	14,915.00
Lift Station	\$	1,604.43
Water Distribution	\$	3,762.32
Wastewater Collection	\$	5,541.51
Grinder Pump Issues	\$	4,140.25
Administrative	\$	-
Total	\$	29,963.51

# BILLED - SERVICE ORDER SUMMARY BILLING CYCLE: FEBRUARY 2025 CITY OF ROLLINGWOOD

S/O#	SVC DATE	COMP	ADDRESS	NOTES	LABOR	EQUIP	MAT'L	SUBCON	TOTAL
BASIC SERVICE	ERVICE								
455462A	02/26/25	02/26/25	403 NIXON AVENUE	BASIC SERVICE	0.00	0.00	14,915.00	0.00	14,915.00
						BASIC SEI	BASIC SERVICE SUBTOTAL	۲	14,915.00
GRINDE	GRINDER PUMP ISSUES	SUES							
450072A	01/13/25	02/20/25	14 TREEMONT DR	GRINDER PUMP PROBLEM. PUMPED OUT TANK UNDERNEATH HOUSE. 1/13/2025 HYDRO SOURCE: CERTIFIED TECHNICIAN SERVICE CALL.	1,895.93	687.07	1,025.81	0.00	3,608.81
450924A	01/17/25	02/25/25	6 ROCK WAY COVE	GRINDER PUMP PROBLEM. PICKED UP 2 SEWER BARRELS. DUMPED THEM INTO TANK AND WAITED FOR TANK TO PUMP DOWN THEN HAULED OFF BARRELS TO SEWER PLANT.	370.13	152.68	8.63	0.00	531.44
					GR	INDER PUMP IS	GRINDER PUMP ISSUES SUBTOTAL	۲	4,140.25
LIFT STATION	TION								
451494A	01/23/25	02/05/25	CORW - LS1 - DELLANA LN	DIESEL TECH WORK COMPLETED. INSTALLED ANTI-GEL IN DIESEL	85.95	131.94	31.74	0.00	249.63
451709A	01/20/25	02/11/25	CORW - LS2 - HATLEY DR	LS CALLING OUT FOR POWER FAILURE. MONITORED UNTIL CLEAR. SENT TO OPERATOR TO INVESTIGATE DURING NORMAL OPERATIONS.	150.00	0.00	0.00	0.00	150.00
451752A	01/04/25	02/24/25	CORW - LS2 - HATLEY DR	LS IN AND OUT OF ALARM. SENT DAY TIME OPERATOR TO INVESTIGATE.	150.00	0.00	0.00	0.00	150.00
454936A	02/21/25	02/25/25	CORW - LS7 - NIXON DRIVE	RESPONDED TO PUMP1 FAIL. RESET DIALER AND ALARM, WW-NORMAL, RESPONDED TO PUMP1 FAIL. RESET DIALER AND ALARM, WW-NORMAL,	282.92	124.95	0.00	0.00	407.87

# BILLED - SERVICE ORDER SUMMARY BILLING CYCLE: FEBRUARY 2025 CITY OF ROLLINGWOOD

S/O #	SVC DATE	COMP	ADDRESS	NOTES	LABOR	EQUIP	MAT'L	SUBCON	TOTAL
LIFT STATION	TION								
454940A	02/22/25	02/25/25	CORW - LS2 - HATLEY DR	CALLED OUT TO CHECK DIALER ISSUE.  WW-NORMAL. POWER-NORMAL. PUMP-1  NORMAL. CHECKED DIALER-NORMAL.	83.21	36.75	0.00	0.00	119.96
454974A	02/22/25	02/24/25	CORW - LS7 - NIXON DRIVE	COMPLETED WORK ON PUMP TROUBLESHOOT. PULLED AND REMOVED RAGS FROM PUMP 1. PUMP WAS PULLING 24 AMPS BEFORE. PUMP PULLS 13 AMPS NOW.	357.49	169.48	0.00	0.00	526.97
WATER [	WATER DISTRIBUTION	ON				LIFT ST/	LIFT STATION SUBTOTAL	۴	1,604.43
444730A	11/15/24	02/12/25	2505 BETTIS BLVD	CHECKED FOR HIGH USAGE. FIXED A MAIN LINE LEAK THAT WAS POURING OUT OF ASPHALT HAD TO CUT OUT ASPHALT AND DIG OUT THE DIRT, LINE WAS NOT IN SERVICE BECAUSE IT WAS AN OLD LINE.	1,262.24	762.06	148.32	0.00	2,172.62
445039A	11/18/24	02/10/25	1 PLEASANT CV	COMPLETE WORK ON FIRE HYDRANT. REPLACED WITH MAIN VALVE GASKET AND O-RING. GREASED AND EXERCISED.	299.53	76.34	1,154.03	0.00	1,529.90
453799A	02/13/25	02/13/25	IN DISTRICT ROLLINGWOOD	TOTAL COLIFORM SAMPLES.	0.00	0.00	0.00	59.80	59.80
WASTEW	WASTEWATER COLLECTION	LECTION			W	ATER DISTRIBL	WATER DISTRIBUTION SUBTOTAL	F	3,762.32
444943A	11/03/24	02/10/25	14 TREEMONT DR	MET WITH CUSTOMER SANITARY SEWER - GRINDER ISSUE, AGREEMENT SIGNED, SENT TO MAINT DUE TO HIGH LEVEL.	75.00	0.00	0.00	0.00	75.00
446238A	12/02/24	02/12/25	5013 TIMBERLINE DRIVE	CUSTOMER PROBLEM-DISTRICT LINES	333.17	152.68	13.80	0.00	499.65

03/07/25 04:04:45 PM

Page 2 of 3

# BILLED - SERVICE ORDER SUMMARY

# BILLING CYCLE: FEBRUARY 2025 CITY OF ROLLINGWOOD

ILLECTION  CLEAR. CAMERA'D LINE AND FOUND ROOT BUILD UP AT DISTRICT "WYE" MARKED THE AREA IN PAINT, AND WILL NEED TO BE REPAIRED.  EXCANATED & REPAIRED SANITARY LINE. SINGLE WYE, HAND DUG STT DEEP AND EXPOSED DAMAGED LINE. THEN CUT OUT AND REPAIRED THE DAMAGED SECTION, AND BACK FILLED HOLE.  CUSTOMER CALLED ABOUT OVERFLOWING GRINDER. SIGNED AGREEMENT. SENT TO MAINTENANCE.  WASTEWATER COLLECTION SUBTOTAL  LABOR EQUIP MAT'L SUBCON TOTAL  LABOR EQUIP MAT'L SUBCON TOTAL  SUBCON TOTAL  LABOR EQUIP MAT'L SUBCON TOTAL  LABOR EQUIP MAT'L SUBCON TOTAL  SUBCON TOTAL  SUBCON TOTAL  SUBCON TOTAL  LABOR EQUIP MAT'L SUBCON TOTAL  SUBCON TOTAL  LABOR EQUIP MAT'L SUBCON TOTAL  SUBCON		938.88	17,789.72	4,267.67	6,967.24	LABOR/EQUIPMENT/MATERIAL/SUBCON TOTALS	LABOR			
ADDRESS  NOTES  LABOR  LABOR  EQUIP  MAT'L  SUBCON  1  CLEAR. CAMERA'D LINE AND FOUND ROOT BUILD UP AT DISTRICT "WYE"  MARKED THE AREA IN PAINT, AND WILL NEED TO BE REPAIRED.  5013 TIMBERLINE DRIVE  EXCAVATED & REPAIRED SANITARY LINE. SINGLE WYE, HAND DUG 3FT DEEP AND EXPOSED DAMAGED LINE, THEN CUT OUT AND REPAIRED THE DAMAGED SECTION, AND BACK FILLED HOLE.  7 INWOOD CIR  CUSTOMER CALLED ABOUT OVERFLOWING GRINDER. SIGNED AGREEMENT. SENT TO MAINTENANCE.	5,541.51	1	CTION SUBTOTA	WATER COLLE	WASTE					
ADDRESS  NOTES  LABOR EQUIP MAT'L SUBCON 1  CLEAR. CAMERA'D LINE AND FOUND ROOT BUILD UP AT DISTRICT "WYE" MARKED THE AREA IN PAINT, AND WILL NEED TO BE REPAIRED.  5013 TIMBERLINE DRIVE  EXCAVATED & REPAIRED SANITARY LINE. SINGLE WYE, HAND DUG 3FT DEEP AND EXPOSED DAMAGED LINE, THEN CUT OUT AND REPAIRED THE DAMAGED SECTION, AND BACK FILLED HOLE.	75.00	0.00	0.00	0.00	75.00	CUSTOMER CALLED ABOUT OVERFLOWING GRINDER. SIGNED AGREEMENT. SENT TO MAINTENANCE.	7 INWOOD CIR		01/22/25	451770A
ADDRESS NOTES LABOR EQUIP MAT'L SUBCON TO SUBCON THE AREA IN PAINT, AND WILL NEED TO BE REPAIRED.	4,891.86	879.08	492.39	1,973.72	1,546.67	EXCAVATED & REPAIRED SANITARY LINE. SINGLE WYE, HAND DUG 3FT DEEP AND EXPOSED DAMAGED LINE, THEN CUT OUT AND REPAIRED THE DAMAGED SECTION, AND BACK FILLED HOLE.	5013 TIMBERLINE DRIVE		12/03/24	446305A
ADDRESS NOTES LABOR EQUIP MAT'L SUBCON 1						CLEAR. CAMERA'D LINE AND FOUND ROOT BUILD UP AT DISTRICT "WYE" MARKED THE AREA IN PAINT, AND WILL NEED TO BE REPAIRED.				
COMP ADDRESS NOTES LABOR EQUIP MAT'L SUBCON 1								LECTION	WASTEWATER COLLECTION	WASTEW
	TOTAL	SUBCON	MAT'L	EQUIP	LABOR	NOTES	ADDRESS	II .	SVC DATE	S/O #

**GRAND TOTAL** 

29,963.51



2601 Forest Creek Dr Round Rock, TX 78665-1232

Statement #:

10906

Page 1

# **Statement**

Month:

FEBRUARY 2025

Client:

CITY OF ROLLINGWOOD

Statement Date: 03/07/25

Work Category	A	mount
BASIC SERVICE	\$14,	915.00
GRINDER PUMP ISSUES	\$4,	140.25
LIFT STATION	\$1,	604.43
WATER DISTRIBUTION	\$3,	762.32
WASTEWATER COLLECTION	\$5,	541.51
	Total This Statement: \$29,	963.51

### **Invoice for Basic Service**

### Crossroads Utility Services

2601 Forest Creek Dr. Round Rock, TX 78665 Phone: 281-620-3986

Fax:

Client:
CITY OF ROLLINGWOOD

**Billing Cycle:** FEBRUARY

Operations Fee - Wastewater System

\$8,165.00

Operations Fee - Water System

\$6,750.00

**Total BASIC SERVICE** 

\$14,915.00

**Inv #** 10906-2

**BCycle** FEBRUARY 2025

**Invoice Date:** 

03/07/25

**Department:** SANITARY

SvrOrd# 450072

District:

CITY OF ROLLINGWOOD

Page # 1

Location:

14 TREEMONT DR

Reported By:

**DEASON DAVID** 

**Telephone Number:** 

GRINDER PUMP ISSUES

Date Completed: 02/20/25

**Description of Work Performed:** 

GRINDER PUMP PROBLEM. PUMPED OUT TANK UNDERNEATH HOUSE. 1/13/2025 HYDRO

SOURCE: CERTIFIED TECHNICIAN SERVICE CALL.

	Description		Qty	Price	Amount
Material					
	HYDRO SOURCE 10039		1.00	1,009.1250	1,009.13
	GLOVES 425006		1.00	8.0500	8.05
	RAGS 509267		1.00	4.0250	4.03
	GLOVES 425006		1.00	4.6000	4.60
		Material			1,025.81
			Service O	rder Total:	1.025.81

#### Hydro Source Services, Inc.

14 Applegate Cir Round Rock, TX 78665 US +15125726188 accounting@hydrosourcetx.com



450072

# **INVOICE**

**BILL TO** 

CROSSROADS UTILITY SERVICES, LLC 2601 FOREST CREEK DRIVE ROUND ROCK, TX 78665 (512) 246-1400 **SHIP TO** 

CROSSROADS UTILITY SERVICES, LLC 2601 FOREST CREEK DRIVE ROUND ROCK, TX 78665 (512) 246-1400 INVOICE # 10039 DATE 01/22/2025

#### PO

39657 - 14 Treemont Dr, Austin

ITEM	DESCRIPTION		QTY	EACH	EXTENDED	
LABOR SERVICE CALL	CERTIFIED TECHNICIAN SERVICE CAL	L	1	607.50	607.50T	
LABOR SERVICE CALL	CERTIFIED TECHNICIAN SERVICE CAL	.L	2	135.00	270.00T	
	eemont Dr, Austin, TX 78746PO: 39657 CALLOUT	SUBTOTAL		**************	877.50	
Work Order Number: 10		TAX			0.00	
Work Order Description 1/13/25	: emailed crossroads asking for a PO. B.Salas.	TOTAL			877.50	
1/13/23		BALANCE DUE			\$877.50	

10906-4 Inv #

**BCycle** FEBRUARY 2025

**Invoice Date:** 

03/07/25

**Department:** DIESEL TECH

SvrOrd# 451494

Page # 1

District:

CITY OF ROLLINGWOOD

Location:

CORW - LS1 - DELLANA LN

**Telephone Number:** 

Reported By:

Date Completed: 02/05/25

LIFT STATION

**Description of Work Performed:** 

DIESEL TECH WORK COMPLETED. INSTALLED ANTI-GEL IN DIESEL

	Description		Qty	Price	Amount
Material	FUEL STABILIZER		1.00	31.7400	24.74
	TOLL STABILIZER		1.00	31.7400	31.74
		Material			31.74
			Service Ord	ler Total:	31.74

**Inv #** 10906-5

**BCycle** FEBRUARY 2025

**Invoice Date:** 

03/07/25

**Department: LEAKS** 

SvrOrd# 444730

Page # 1

District:

CITY OF ROLLINGWOOD

Location:

2505 BETTIS BLVD

Reported By:

HAMILTON WILLIAM

**Telephone Number:** 

Date Completed: 02/12/25

WATER DISTRIBUTION

**Description of Work Performed:** 

CHECKED FOR HIGH USAGE. FIXED A MAIN LINE LEAK THAT WAS POURING OUT OF ASPHALT HAD TO CUT OUT ASPHALT AND DIG OUT THE DIRT, LINE WAS NOT IN SERVICE

BECAUSE IT WAS AN OLD LINE.

	Description		Qty	Price	Amount
Material		3000			
	2" FULL CIRCLE CLAMP 226023812		1.00	144.2905	144.29
	RAGS 509367		1.00	4.0250	4.03
		Material			148.32
			Service Or	der Total:	148.32

Inv # 10906-6

**BCycle** FEBRUARY 2025

**Invoice Date:** 

Reported By:

03/07/25

**Department: HYDRANTS** 

SvrOrd# 445039

District:

CITY OF ROLLINGWOOD

Page # 1

Location:

1 PLEASANT CV

I PLEASANT CV

MCCOLLUM DAVID

**Telephone Number:** 

WATER DISTRIBUTION

Date Completed: 02/10/25

**Description of Work Performed:** 

COMPLETE WORK ON FIRE HYDRANT. REPLACED WITH MAIN VALVE GASKET AND O-RING.

GREASED AND EXERCISED.

	Description	Qty	Price	Amount
Material				
	MAIN VALVE GASKET 61AD54843502	1.00	1,028.4680	1,028.47
	O-RINGS 51843615012	1.00	111.5960	111.60
	GREASE 61HYDGREASEFM222	1.00	13.9610	13.96
	Material			1,154.03
		Service O	der Total:	1,154.03

**Inv #** 10906-7

BCycle FEBRUARY 2025

Invoice Date:

03/07/25

**Department:** SUB-OPER

**SvrOrd#** 453799

District:

CITY OF ROLLINGWOOD

Page # 1

Location:

IN DISTRICT ROLLINGWOOD

Reported By:

**Telephone Number:** 

WATER DISTRIBUTION

Date Completed: 02/13/25

**Description of Work Performed:** 

TOTAL COLIFORM SAMPLES.

Description		Qty	Price	Amount
Subcontract				
AQUA TECH 75492		1.00	59.8000	59.80
	Subcontract			59.80
		Service Ord	ler Total:	59.80



635 Phil Gramm Blvd., Bryan TX 77807 P: (979)778-3707, F: (979)778-3193 email: accounting@aqua-techlabs.com

# Invoice

Invoice Number: 75492 Invoice Date: 1/31/2025

Bill To:	Comments:
Crossroads Utility Service 2601 Forest Creek Dr. ROUND ROCK, TX 78665-1232	December 2024 Analysis Rollingwood

Customer ID	Customer PO	Payment Terms	Due Date Discount
Crossroads Utility Service	*	NET 30 Days	3/2/2025

Quantity	Item ID & Matrix	Description (see key below)	Unit Price	Amount
2	A Total Coliform DW	Total Coliform SM 9223 [NEL]	26.00	52.00
	,			
			*	

Location: A-Austin Laboratory Parameter (all others through Bryan Laboratory)

Matrix Codes: NP-Non Potable Water, DW-Drinking Water, SL-Solid

NEL-NELAC Accredited, SUB-Subcontracted, INF-Informational (not certified) DWP-Accredited through the TCEQ DW Commercial Lab Approval Program ANR-Accreditation Not Required

Total Invoice Amount	\$52.00
Payments/Credits Applied	\$0.00
TOTAL	\$52.00

Empty sample containers, which may contain site references, will be bagged and disposed via municipal waste collection.

Go paperless! If you prefer to have your invoices e-mailed, please send a request to accounting@aqua-techlabs.com and we will make the change for you.

Thank you for your business!

**Inv #** 10906-9

**BCycle** FEBRUARY 2025

**Invoice Date:** 

03/07/25

**Department: EXCAVATIONS** 

SvrOrd# 446305

District:

CITY OF ROLLINGWOOD

Location:

**5013 TIMBERLINE DRIVE** 

Page # 1

Reported By:

CONNOR, GREG

**Telephone Number:** 

WASTEWATER COLLECTION

Date Completed: 02/17/25

**Description of Work Performed:** 

EXCAVATED & REPAIRED SANITARY LINE. SINGLE WYE, HAND DUG 3FT DEEP AND EXPOSED DAMAGED LINE, THEN CUT OUT AND REPAIRED THE DAMAGED SECTION, AND BACK FILLED

HOLE.

	Description		Qty	Price	Amount
Material	\				T T
	CORE & MAIN W108992		1.00	383.9850	383.99
	GLOVES 425006		1.00	20.7000	20.70
	RAGS 509267		1.00	13.8000	13.80
	YD OF PEA GRAVEL 124444		1.00	73.8990	73.90
		Material			492.39
Subcon	tract				
	WWTS 11131176		1.00	879.0830	879.08
		Subcontract			879.08
			Service Or	der Total:	1,371.47



DUPLICATE

### INVOICE

1830 Craig Park Court St. Louis, MO 63146

Invoice # Invoice Date Account # Sales Rep Phone # Branch #160

W108992 12/04/24 194286 MATTHEW DULOCK 512-990-8470

Total Amount Due

Pflugerville, TX \$333.90

Remit To: CORE & MAIN LP PO BOX 28330 ST LOUIS, MO

CUSTOMER PICK-UP

63146

CROSSROADS UTILITY SVCS LLC 2601 FOREST CREEK DR ROUND ROCK TX 78665 1232

CUSTOMER JOB- 5013 TIMBERLINE

Shipped To:

Thank you for the opportunity to serve you! We appreciate your prompt payment.

Date Ordered Date Shipped Customer PO # Job Name 12/03/24

12/03/24

38939

5013 TIMBERLINE

Job # Bill of Lading Shipped Via

WILL CALL

Invoice# W108992

		Quantity						
Product Code	Description	Ordered	Shipped	B/0	Price	UM	Extended	Price
2704SGR26	4 HW SWR SDR26 REP CPLG GXG	1	1		32.30000	EA		32.30
27044GS26	4 HW SWR SDR26 45 GXSP	3	3		27.06000	EA		81.18
2706CO	6 SDR35 CLEANOUT ADPT HXF L/PI	1	1		34.57000	EA		34.57
2706PM	6 PVC SWR CLEANOUT PLUG MIPT	1	1		22.35000	EA		22.35
2706W06GG26	6X6 HW SWR SDR26 WYE GXG	1	1		107.71000	EA	1	107.71
2704I06GS26	4X6 HW SDR26 INCREASER GXSP	1	1		55.79000	EA		55.79

Freight Delivery Handling Restock Misc Subtotal: 333.90 .00 Other: .00 Tax: Terms: NET 30 Ordered By: ADRIAN Invoice Total: \$333.90





826 Linger Ln Austin TX 78721 (512) 973-8484

#### Bill To:

Crossroads Utility Services 2601 Forest Creek Drive Round Rock TX 78665 United States

#### **Service Location:**

5013 Timberline Drive Austin TX 78746 United States

Terms	Due Date		PO #	Sales Rep	
Net 60	2/15/2025		39322	House	
Service Date	Manifest	Quantity	Item	Rate	Amount
12/2/2024	MC/GR	3	Hours Unit 2013 - Bobtail Vacuum Truck: Emergency service for hydro-jetting gravity line to clear a blockage causing a backup. (11:15 AM - 2:15 PM)	\$225.00	\$675.00
		1	Environmental & Energy Recovery Fee		\$62.44
		1	Fuel Surcharge		\$26.98

#### Pay your bill online at:

www.wastewaterts.com Customer ID: 137411

Remit To: 826 Linger Ln, Austin, TX 78721

For more information on fees and surcharges click here.

Invoice Total \$764.42 Invoice Balance \$764.42

Thank you for doing business with us! We know the world is full of choices. Thanks for choosing us!

