

# Invoice 10190

Date: June 7, 2024

2601 Forest Creek Dr. Round Rock, TX 78665 512-246-1400 www.crossroadsus.com

### **Bill To:**

City of Rollingwood 403 Nixon Avenue Rollingwood, TX 78746

		May-24
		erations & aintenance
DESCRIPTION	AMOU	JNT
Basic Service	\$	14,915.00
Lift Station	\$	1,172.33
Water Distribution	\$	15,256.26
Wastewater Collection	\$	911.43
Grinder Pump Issues	\$	1,701.74
Total	\$	33,956.76

# BILLED - SERVICE ORDER SUMMARY

# BILLING CYCLE: MAY 2024 CITY OF ROLLINGWOOD

S/O #	SVC DATE	COMP	ADDRESS	NOTES	LABOR	EQUIP	MAT'L	SUBCON	TOTAL
BASIC SERVICE	ERVICE								
424932A	05/29/24	05/29/24	403 NIXON AVENUE	BASIC SERVICE	0.00	0.00	14,915.00	0.00	14,915.00
						BASIC SE	BASIC SERVICE SUBTOTAL	AL	14,915.00
GRINDER	GRINDER PUMP ISSUES	SUES							
4.19626A	04/12/24	05/22/24	408 WALLIS DR	PUMP WILL ONLY RUN WHEN HIGH LEVEL ALARM GOES OFF. SENT TO HYDRO SOURCE. 4/12 HS: STATION AT MOTOR HOUSING ON ARRIVAL WITH BREAKERS ON, BUT PUMP NOT RUNNING. CONTINUITY TEST SHOW PUMP SHUTTING TO GROUND ON GROUND ON BRONW AND BLACK WIRE, EQUALIZER HOSE DISCONNECTED. SUPPLY. REPLACED BAD INSERT WITH NEW INSERT. PULLED PUMP FOR REPAIR & DROPPED IN ROLLING WOOD SPARE AND TESTED.	108.41	76.34	8.22	1,508.77	1,701.74
					GRIN	NDER PUMP IS	GRINDER PUMP ISSUES SUBTOTAL	AL.	1,701.74
LIFT STATION	TION								
417400A	03/18/24	05/11/24	CORW - LS3 - ALMARION WAY	NEED TECHNICIAN - DIALER NOT ABLE TO ANSWER - ATT SUBMITTED	11.09	7.35	0.00	0.00	18.44
420208A	04/17/24	05/21/24	CORW-LS2-HATLEY DR	FACILITY WORK COMPLETED -C LEANED GREASE OFF OF FLOATS - TESTED HIGH LEVEL ALARM	13.78	7.35	0.00	0.00	21.13
420213A	04/17/24	05/21/24	CORW - LS3 - ALMARION WAY	FACILITY WORK COMPLETED - CLEANED GREASE OFF OF FLOATS AND TESTED HIGH LEVEL ALARM	13.78	7.35	0.00	0.00	21.13
420215A	04/17/24	05/21/24	CORW - LS6 - PLEASANT COVE	FACILITY WORK COMPLETED - CLEANED	13.78	7.35	0.00	0.00	21.13

06/07/24 03:25:56 PM

Page 1 of 5

# BILLED - SERVICE ORDER SUMMARY

# BILLING CYCLE: MAY 2024 CITY OF ROLLINGWOOD

S/O #	SVC DATE	COMP	ADDRESS	NOTES	LABOR	EQUIP	MAT'L	SUBCON	TOTAL
LIFT STATION	TION								
	:			GREASE OFF OF FLOATS AND TESTED HIGH FLOAT ALARM					
420217A	04/17/24	05/21/24	CORW - LS7 - NIXON DRIVE	FACILITY WORK COMPLETED - CLEANED GREASE OFF OF FLOATS - RESET SITE PRO SYSTEM WITH CALLER FROM ROLLINGWOOD	27.57	14.70	0.00	0.00	42.27
421271A	04/28/24	05/02/24	CORW - LS2 - HATLEY DR	WENT ON SITE HOOKED PHONE TO DIALER AND THE DIALER HAS LAZY SIGNAL. CHECKED AT&T BOX, AT&T IS GOOD. SENT TO FACILITIES.	124.04	44.10	0.00	0.00	168.14
421840A	05/01/24	05/07/24	CORW - LS7 - NIXON DRIVE	WET WELL HIGH LEVEL. GENERATOR WAS RUNNING, PHASE FAILURE. BOTH PUMPS. TURNS 1 PUMP ON AT ONE TIME. PROBLEM, RESOLVES. CONTACTED AUSTIN ENERGY.	227.40	80.85	0.00	0.00	308.25
421861A	05/01/24	05/06/24	CORW - LS4 - ROCKWAY COVE	RMS REPORTS PROBLEM. HIGH LEVEL ALARM DURING THE BAD STORMS. RYAN WENT OUT. PUMP TRIPPED OUT DOWN A LINE ON POWER. CALLED AUSTIN ENERGY TO FIX POWER. PUMPED WET WELL DOWN.	75.00	0.00	0.00	0.00	75.00
422635A	05/08/24	05/13/24	CORW - LS1 - DELLANA LN	RMS REPORTED RESET VFD 1 ALARM. FACILITY IS OPERATING NORMALLY.	41.35	14.70	0.00	0.00	56.05
422687A	05/07/24	05/15/24	CORW - LS2 - HATLEY DR	ELEC TECH WORK COMPLETED. DIALER HAD A LOOSE CONNECTION, REFITTED THE CONNECTION AND TESTED THE DIALER FOR CALL OUT.	262.23	131.94	0.00	0.00	394.17
422761A	05/10/24	05/17/24	CORW - LS1 - DELLANA LN	REPLACED PUCK LOCK FOR CONTROL ROOM DOORS.	27.57	14.70	4.35	0.00	46.62

# BILLING CYCLE: MAY 2024

1						LIFT ST	LIFT STATION SUBTOTAL		1,172.33
417114A	03/18/24	05/07/24	IN DISTRICT ROLLINGWOOD	REFER TO MAINT. CORRELATED WITH THE CITY OF ROLLINGWOOD TO MONITOR HIGH AND LOW PRESSURE POINTS AFTER WE REPLACED CRD ON THE PRV. MADE ADJUSTMENTS TO BRING THE LOWEST PRESSURE IN THE LOWER 40'S AND THE HIGHEST PRESSURE TO THE 90 PSI. BEE CAVE WOOD MASTER METER.	1,022.91	410.88	0.00	0.00	1,433.79
418491A	03/27/24	05/12/24	4900 TIMBERLINE DRIVE	TOOK SPECIAL SAMPLE AND TURNED IN TO LAB	44.37	29.40	0.00	0.00	73.77
418492A	03/27/24	05/12/24	4708 TIMBERLINE DRIVE	TOOK SPECIAL SAMPLE TURNED IN TO LAB	55.46	36.75	0.00	0.00	92.21
418820A	04/01/24	05/12/24	403 NIXON AVENUE	TOOK SPECIAL SAMPLE - TOOK 2 BAC T SAMPLES BOTH PASSED - DROPPED OFF AT AQUA TECH	82.70	44.10	0.00	0.00	126.80
420132A	04/16/24	05/21/24	IN DISTRICT ROLLINGWOOD	TOOK SPECIAL SAMPLE - TOOK 4 SAMPLES FOR BWN BECAUSE OF CITY SHUT DOWN OF WATER	137.83	73.50	0.00	0.00	211.33
420274A	04/17/24	05/21/24	IN DISTRICT ROLLINGWOOD	TOOK SPECIAL SAMPLE - DUE TO CONSTRUCTION FLUSHED HYDRANT AND PROCEEDED WITH SOP FOR SAMPLING	82.70	44.10	0.00	0.00	126.80
420939A	04/26/24	05/10/24	2810 ROLLINGWOOD DRIVE	EXPOSED MAIN LINE VALVE. EXCAVATED AND EXPOSED 8" GATE VALVE, ISOLATED MAIN AND CUT AND REPLACED 8" GATE VALVE. TESTED AND FLUSHED HYDRANT. BACK FILLED AND CLEANED AREA.	2,448.89	2,887.02	1,774.65	0.00	7,110.56
421448A	04/29/24	05/01/24	IN DISTRICT ROLLINGWOOD	BAC-T SAMPLES	0.00	0.00	0.00	478.40	478.40
421677A	04/30/24	05/02/24	IN DISTRICT ROLLINGWOOD	TOOK SPECIAL SAMPLE. CONSTRUCTION SAMPLES. INWOOD CV HYDRANT AND	165.39	88.20	0.00	0.00	253.59

# BILLED - SERVICE ORDER SUMMARY

# BILLING CYCLE: MAY 2024 CITY OF ROLLINGWOOD

423211A	422609A	422154A	422088A	421835A	WA	S/O #
05/14/24	05/08/24	05/02/24	05/03/24	05/01/24	WATER DIVINIBUTION	SVC DATE
05/16/24	05/13/24	05/22/24	05/22/24	05/08/24	C	E COMP
2800 HATLEY DR	IN DISTRICT ROLLINGWOOD	IN DISTRICT ROLLINGWOOD	4814 ROLLINGWOOD DRIVE	4905 TIMBERLINE DRIVE		ADDRESS
DUE TO WATER LINE TIE-IN A SPECIAL SAMPLE WAS NEEDED; HAD TO DIRECT DIRECTIONAL FLUSHING TO ENURE	TOOK CONSTRUCTION SAMPLE. AND TOOK TO AQUA TECH HAD TO FLUSH HYDRANT AND INSTALL SAMPLE RISER.	WATER SYSTEM WORK COMPLETE. PICKED UP DATA LOGGERS AND ROLL DATA FOR ROLLINGWOOD.	REPLACED CONCRETE AFTER REPAIRS. 5/3/2024 ARRIVED TO PROVIDED ADDRESS. DUG OUT AREA BY HAND TO A GRADE OF 6" IN DEPTH. CLEANED AREA AND POURED CONCRETE. 5/6/2024 ARRIVED TO PROVIDED ADDRESS. DUG OUT AREA BY HAND, TO A GRADE OF 6". CLEANED AREA AND POURED CONCRETE.	INVESTIGATED POSSIBLE LEAK. 4/29/2024 CONTRACTORS HIT 1" SERVICE LINE. REPAIRED WITH 2 COUPLINGS/2FT POLY. CITY IS AWARE OF CONTRACTOR CONTACT INFORMATION. 5/01/2024ARRIVED TO PROVIDED ADDRESS, OBSERVED LEAKING STRAIGHT STOP. REMOVED WATER BY HAND EXPOSED SERVICE, CRIMPED LINE AND REPLACED STRAIGHT STOP. PRESSURE TESTED ADDRESS. BACK FILLED AND LANDSCAPED AROUND METER BOX.	TIMBERLINE RIDGE HYDRANT.	NOTES
82.70	82.70	146.13	1,156.35	483.99		LABOR
44.10	44.10	76.34	763.40	419.02		EQUIP
0.00	0.00	0.00	1,797.60	168.05		MAT'L
0.00	0.00	0.00	0.00	0.00		SUBCON
126.80	126.80	222.47	3,717.35	1,071.06		TOTAL

# BILLED - SERVICE ORDER SUMMARY

# **BILLING CYCLE: MAY 2024** CITY OF ROLLINGWOOD

33,956.76		GRAND TOTAL	ତ୍ର						
	1,987.17	18,667.87	5,646.94	7,654.78	LABOR/EQUIPMENT/MATERIAL/SUBCON TOTALS	LABOR/E			
911.43	AL	WASTEWATER COLLECTION SUBTOTAL	EWATER COLLE	WASTI					
911.43	0.00	0.00	249.90	661.53	SANITARY SYSTEM WORK COMPLETE - DISCONNECT GASOLINE INSIDE OF NIXON AND LOCKWAY LIFTSTATION - NOTIFIED SUPERVISOR AND SHUT FACILITIES DOWN - FIRE DEPARTMENT ON SITE ALONG WITH HAZMAT FOR CLEANUP AND DISPOSAL - COORDINATED OPERATIONS WITH IZZY, JORGE, AND SERGIO	IN DISTRICT ROLLINGWOOD	05/15/24	04/15/24	419975A
							LECTION	WASTEWATER COLLECTION	WASTEW
15,256.26	AL	WATER DISTRIBUTION SUBTOTAL	WATER DISTRIE						
84.53	0.00	0.00	29.40	55.13	DUE TO CONSTRUCTION PROJECT A CONSTRUCTION SAMPLE WAS NEEDED.	4703 TIMBERLINE DRIVE	05/16/24	05/14/24	423219A
					GOOD SAMPLING PROCEDURE.				
							ON	WATER DISTRIBUTION	WATER (
TOTAL	SUBCON	MAT'L	EQUIP	LABOR	NOTES	ADDRESS	COMP	SVC DATE	S/O #



2601 Forest Creek Dr Round Rock, TX 78665-1232

Statement #: 10190

Page 1

# **Statement**

Month:

MAY 2024

Client:

CITY OF ROLLINGWOOD

Statement Date: 06/07/24

	\$14,915.00
	\$1,701.74
	\$1,172.33
	\$15,256.26
	\$911.43
Total This Statement:	\$33,956.76
	Total This Statement:

### **Invoice for Basic Service**

## Crossroads Utility Services

2601 Forest Creek Dr. Round Rock, TX 78665 Phone: 281-620-3986

Fax:

Client:

CITY OF ROLLINGWOOD

Billing Cycle:

MAY 2024

Operations Fee - Wastewater System

\$8,165.00

Operations Fee - Water System

\$6,750.00

**Total BASIC SERVICE** 

\$14,915.00

Inv # 10190-2

BCycle MAY 2024

**Invoice Date:** 

06/07/24

**Department: SANITARY** 

**SvrOrd#** 419626

Page # 1

District:

CITY OF ROLLINGWOOD

Location:

408 WALLIS DR

Reported By:

GOYAL, MOHIT

**Telephone Number:** 

**GRINDER PUMP ISSUES** 

Description of Work Performed:

Date Completed: 05/22/24

PUMP WILL ONLY RUN WHEN HIGH LEVEL ALARM GOES OFF. SENT TO HYDRO SOURCE. 4/12 HS: STATION AT MOTOR HOUSING ON ARRIVAL WITH BREAKERS ON, BUT PUMP NOT RUNNING. CONTINUITY TEST SHOW PUMP SHUTTING TO GROUND ON GROUND ON BRONW AND BLACK WIRE, EQUALIZER HOSE DISCONNECTED. SUPPLY. REPLACED BAD INSERT WITH NEW INSERT. PULLED PUMP FOR REPAIR & DROPPED IN ROLLING WOOD SPARE AND

TESTED.

	Description		Qty	Price	Amount
Material					
	GLOVES 425006		1.00	4.4850	4.49
	RAGS 509267		1.00	3.7260	3.73
		Material			8.22
Subcont	tract				
	HYDRO SOURCE 8617		1.00	1,508.7655	1,508.77
		Subcontract			1,508.77
			Service O	rder Total:	1,516.99

Hydro Source Services, Inc.

14 Applegate Cir

Round Rock, TX 78665 US

+15125726188

accounting@hydrosourcetx.com



# **INVOICE**

**BILL TO** 

CROSSROADS UTILITY

SERVICES, LLC

2601 FOREST CREEK DRIVE

ROUND ROCK, TX 78665

(512) 246-1400

SHIP TO

**ROLLINGWOOD-408 Wallis** 

Dr, Austin, TX 78746 PO#

34608 OUT: WH877282 IN:

GH583491

**INVOICE #** 8617

**DATE** 05/21/2024

**TERMS** Net 30

PO

34608

REPRESENTATIVE

MX8776

ITEM	DESCRIPTION	QTY	EACH	EXTENDED	
LABOR SERVICE CALL	Peter N. 04/12/2024, 12:48 PM Station was at motor housing on arrival with breakers on but pump not running 245v 0.0amps equalizer is good, continuity test show pinp shiting to ground on brown and black wire, and equalizer hose was disconnected, supply side insert tested bad replaced with new insert, pulled pump for repair and dropped in a rolling wood spare and tested 245v 5.8	1	607.50	607.50T	
SHOP SERVICE	SHOP SERVICE	2	135.00	270.00T	
RETURN VISIT	Dallas 5/20/24 at 12:12 PM Pop and swap completed.	1	135.00	135.00T	
PARTS	REPLACEMENT PARTS7094 - EQD INSERT, FEMALE (SIX PIN) 1 unit \$28.30 3212 - CORD GRIP, 1/2 INCH NPT W/ O-RING 1 unit \$16.76 7290 - PRESSURE SWITCH, ON/OFF W/ O-RINGS 1 unit \$73.12 7291 - PRESSURE SWITCH, ALARM W/ O-RINGS 1 unit \$73.12 7115 - FLG TERMINAL, 18 GA 4 units \$1.24 6203 - SEAL, LEVEL SENSING HOUSING, EXTREME 1 unit \$4.16 8203 - STATOR/LINER ASSY, EXTREME 1 unit \$99.05 Parts Cost \$299.47	1	299.47	299.47T	

Thank you for your business. Please contact us with any questions or concerns.

SUBTOTAL TAX TOTAL BALANCE DUE 1,311.97 0.00 1,311.97

\$1,311.97

Inv # 10190-3

BCycle MAY 2024

**Invoice Date:** 

06/07/24

**Department: FACILITIES** 

SvrOrd# 422761

Page # 1

District:

CITY OF ROLLINGWOOD

Location:

CORW - LS1 - DELLANA LN

Reported By:

**Telephone Number:** 

LIFT STATION

Date Completed: 05/17/24

**Description of Work Performed:** 

REPLACED PUCK LOCK FOR CONTROL ROOM DOORS.

	Description		Qty	Price	Amount
Material					
	LOWE'S 93234		1.00	4.3470	4.35
		Material			4.35
			Service Ord	er Total:	4.35





### LEARN MORE AT LOWES.COM/NYLOWESREWARDS

LOVE'S HOME CENTERS, LLC 12611 SJIFE 100 SHOPS FRWY BEE CAVE, TX 78738 (512) 634-4432

### - SALE -

SALES#: \$1948\$C1 5005296 TRANS#: 553734285 05-10-24

138277 FINE THROHEX NUTS 3/8IN-2 1.42

0.75 DISCOUNT EACH -0.04

2 @ 0.71 63343 3/8-1N X 3-IN Z CARRG BCL

4 0 0.59

0.62 DISCOUNT EACH -0.03

SUBTOTAL: 3.78 TOTAL TAX: 0.00 INVOICE 93234 (OTAL: 3.78

LAR:

TOTAL SAVINGS THIS TRIP:

LAF: XXXXXXXXXXXX6689 AMOUNT: 3.78 AUTHOD: 000823

KEYED REFID:932340 05/10/24 10:36:13

LAR PO: 35122

ACCOUNT NAME: CROSSROADS UTILITY SERVICE

AUTH BUYER: MANSEY HAYDEN

**Inv #** 10190-4

BCycle MAY 2024

**Invoice Date:** 

06/07/24

**Department: EXCAVATIONS** 

SvrOrd# 420939

Page # 1

District: Location: CITY OF ROLLINGWOOD

2810 ROLLINGWOOD DRIVE

Reported By:

REED DAVID & CINDY

**Telephone Number:** 

WATER DISTRIBUTION

Date Completed: 05/10/24

**Description of Work Performed:** 

EXPOSED MAIN LINE VALVE. EXCAVATED AND EXPOSED 8" GATE VALVE, ISOLATED MAIN AND CUT AND REPLACED 8" GATE VALVE. TESTED AND FLUSHED HYDRANT. BACK FILLED

AND CLEANED AREA.

	Description		Qty	Price	Amount
Material					
	C & M U787322 U781675		1.00	1,293.9455	1,293.95
	BED ROCK 2-1486		1.00	480.7000	480.70
		Material			1,774.65
			Service O	rder Total:	1,774.65



## INVOICE



1830 Craig Park Court St. Louis, MO 63146

Invoice # **Invoice Date** Account # Sales Rep Phone # Branch # 160 **Total Amount Due** 

U787322 4/26/24 194286 MATTHEW DULOCK 512-990-8470 Pflugerville, TX \$174.35

Remit To: **CORE & MAIN LP** PO BOX 28330 **ST LOUIS, MO 63146** 

1407 1 MB 0.571 E0062X 10099 D12755757518 S2 P10261266 0001:0002

### իրթախվեն հենգրդ վիրակիրկին հերգորեր ԱՄՈւթերե

CROSSROADS UTILITY SVCS LLC 2601 FOREST CREEK DR ROUND ROCK TX 78665-1232

Shipped to:

CUSTOMER PICK-UP -

Thank you for the opportunity to serve you! We appreciate your prompt payment.

Invoice # Date Ordered Date Shipped **Customer PO # Job Name** Job# Bill of Lading Shipped Via 4/25/24 4/25/24 SEE BELOW WILL CALL U787322

			Quantity				
Product Code	Description	Ordered	Shipped	B/O	Price	UM	Extended Price
	CUSTOMER PO#- 2810 ROLLINGWOOD DI	R					
59VBC5	C5 AUSTIN VALVE BOX BASE ONLY CITY OF AUSTIN SPEC IMPORT	1	1		108.32000	EA	108.32
59VPRC6	C6 AUSTIN VLV BOX PAVING RING CITY OF AUSTIN SPEC IMPORT	1	1		40.80000	EA	40.80
59VLC7IMP	C7 AUSTIN VALVE BOX WATER LID CITY OF AUSTIN SPEC IMPORT	1	1		25.23000	EA	25.23



- Manage billing online Reprint invoices
- Retrieve proof of deliveries


Be suspicious of emails requesting wire transfers or payments to Core & Main using updated remittance information. For tips about how to identify bad actors, visit coreandmain.com/identifying-fraud.

Subtotal: 174.35 **Freight** Delivery Handling Restock Misc. Other: 0.00 Tax: 0.00 Terms: NET 30 **Invoice Total:** \$174.35 Ordered By: EASTON



## INVOICE





Invoice #
Invoice Date
Account #
Sales Rep
Phone #
Branch # 160
Total Amount Due

U781675 4/25/24 194286 MATTHEW DULOCK 512-990-8470 Pflugerville, TX \$950.82

Remit To: CORE & MAIN LP PO BOX 28330 ST LOUIS, MO 63146

743 1 MB 0.571 E0289 I0435 D12750992976 S2 P10259140 0005:0005

### լիրունաին Մենագիրգիրը Միլուինալի մինիերի վի

34530

4/24/24

CROSSROADS UTILITY SVCS LLC 2601 FOREST CREEK DR ROUND ROCK TX 78665-1232 Shipped to:

**CUSTOMER PICK-UP-**

Thank you for the opportunity to serve you! We appreciate your prompt payment.

**Date Ordered** Date Shipped

4/24/24

Customer PO # Job Name

Job#

Bill of Lading

**Shipped Via** 

Invoice #

WILL CALL U781675

		Qu	antity				
Product Code	Description	Ordered Sh	ipped	B/O	Price	UM	Extended Price
7442108540985031	421-08540985-031 8X8 CPLG EPXY 304SS B&N 8.54-9.85 OD	2	2		379.67000	EA	759.34
21IAMF708EZPVCP	8 SIP EZ GRIP PVC REST W/ACC	2	2		95.74000	EA	191.48



- Manage billing online
- Reprint invoices
- Retrieve proof of deliveries

Be suspicious of emails requesting wire transfers or payments to Core & Main using updated remittance information. For tips about how to identify bad actors, visit **coreandmain.com/identifying-fraud.** 

Freight

Delivery

Handling

Restock

Misc.

Subtotal: Other:

950.82

Tax:

0.00

Invoice Total:

\$950.82

Terms: NET 30
Ordered By: EASTON

This transaction is governed by and subject to CORE & MAIN's standard terms and conditions, which are incorporated by reference and accepted.

To review these terms and conditions, please visit: http://tandc.coreandmain.com/.



ROCK III 13652 HWY 71 W Bee Cave TX 78738 Tel: 512-263-2288

austinrockyard.com bedrockpictures@gmail.com

The same of the sa Date: 4/25/2024 2.33:35 PM INVOICE NO: 2-1486

PO Number: 4814 ROLLINGWOOD DRIVE

cashier: ROCK3

Customer: CROSSROAD UTILITY SERVICE

CROSSROAD UTILITY SERVICE

Price	Ext.Price
(D)	and make name (i.e., the tag have now and had him the
\$79.00	\$158.00T
\$65.00	\$260.00T
	\$418.00
	(D) \$79.00 (D) (YD)

and the property of the proper

TAX 8.25%: \$34.49

Total: \$452.49

Tendered:

\$452.49 Visa:

Card #: \*\*\*\*\*\*\*\*\*4027 Element Trans1D: 799940082 and an internal was to the control of the control o

BAG & PALLET DEPOSITS ARE ELIGIBLE FOR A FULL REFUND WITHIN 30 DAYS WITH PROOF OF PURCHASE.

AFTER 30 DAYS, A STORE CREDIT (NOT INCLUDING TAXES) WILL BE ISSUED TOWARDS A NEW PURCHASE, WITH MANAGER APPROVAL.

ALL OTHER SALES ARE FINAL. NATURAL STONE IS A PRODUCT OF MOTHER NATURE AND WILL ALWAYS VARY IN COLOR, TEXTURE AND PHYSICAL PROPERTIES.

SIGNATURE:

SO# 420939A Po#

Inv # 10190-5

BCycle MAY 2024

**Invoice Date:** 

06/07/24

Department: SUB-OPER

**SvrOrd#** 421448

Page # 1

District:

CITY OF ROLLINGWOOD

Location:

IN DISTRICT ROLLINGWOOD

Reported By:

**Telephone Number:** 

WATER DISTRIBUTION

Date Completed: 05/01/24

**Description of Work Performed:** 

**BAC-T SAMPLES** 

Description		Qty	Price	Amount
Subcontract				
AQUA TECH 70662		1.00	478.4000	478.40
	Subcontract			478.40
		Service Or	der Total:	478.40



635 Phil Gramm Blvd., Bryan TX 77807 P: (979)778-3707, F: (979)778-3193 email: accounting@aqua-techlabs.com

# Invoice

Invoice Number: 70662 Invoice Date: 4/26/2024

BIII To:	Comments:
Crossroads Utility Service 2601 Forest Creek Dr. ROUND ROCK, TX 78665-1232	March 2024 Analysis Rollingwood

Customer ID	Customer PO	Payment Terms	Due Date	Discount
Crossroads Utility Service	*	NET 30 Days	5/26/2024	

Quantity	Item ID & Matrix	Description (see key below)	Unit Price	Amount
9	A Total Coliform DW A Weekend Work	Total Coliform SM 9223 [NEL] Weekend Work Fee	26.00 182.00	234.00 182.00

Location: A-Austin Laboratory Parameter (all others through Bryan Laboratory)

Matrix Codes: NP-Non Potable Water, DW-Drinking Water, SL-Solid

NEL-NELAC Accredited, SUB-Subcontracted, INF-Informational (not certified) DWP-Accredited through the TCEQ DW Commercial Lab Approval Program ANR-Accreditation Not Required

Total Invoice Amount	\$416.00
Payments/Credits Applied	\$0.00

Empty sample containers, which may contain site references, will be bagged and disposed via municipal waste collection.

Go paperless! If you prefer to have your invoices e-mailed, please send a request to accounting@aqua-techlabs.com and we will make the change for you.

Thank you for your business!

Inv # 10190-6

BCycle MAY 2024

**Invoice Date:** 

06/07/24

**Department: LEAKS** 

**SvrOrd#** 421835

Page # 1

District:

CITY OF ROLLINGWOOD

Location:

4905 TIMBERLINE DRIVE

Reported By:

**ELLIOTT PAUL & DE** 

**Telephone Number:** 

WATER DISTRIBUTION

Date Completed: 05/08/24

**Description of Work Performed:** 

INVESTIGATED POSSIBLE LEAK. 4/29/2024 CONTRACTORS HIT 1" SERVICE LINE. REPAIRED WITH 2 COUPLINGS/2FT POLY. CITY IS AWARE OF CONTRACTOR CONTACT INFORMATION.

5/01/2024ARRIVED TO PROVIDED ADDRESS, OBSERVED LEAKING STRAIGHT STOP.

REMOVED WATER BY HAND EXPOSED SERVICE, CRIMPED LINE AND REPLACED STRAIGHT STOP. PRESSURE TESTED ADDRESS. BACK FILLED AND LANDSCAPED AROUND METER

BOX.

	Description	Qty	Price	Amount
Material				
	1" X 3/4" STRAIGHT STOP 3707BA23342WNL	1.00	92.0920	92.09
	1" INSERT 3910152	1.00	2.7715	2.77
	3/4" METER GASKET 61141675	1.00	0.3450	0.35
	1" COMPRESSION (BRASS) C44-44-6-NL	1.00	71.0010	71.00
	2FT 1" BLACK POLY 0910E200C1	1.00	1.8400	1.84
	Material			168.05
		Service Ord	ler Total:	168.05

**Inv #** 10190-7

BCycle MAY 2024

**Invoice Date:** 

06/07/24

**Department: CONCRETE** 

SvrOrd# 422088

District: Location: CITY OF ROLLINGWOOD

4814 ROLLINGWOOD DRIVE

Page # 1

Reported By:

MULHERN, LYNDA

**Telephone Number:** 

WATER DISTRIBUTION

Date Completed: 05/22/24

**Description of Work Performed:** 

REPLACED CONCRETE AFTER REPAIRS. 5/3/2024 ARRIVED TO PROVIDED ADDRESS. DUG OUT AREA BY HAND TO A GRADE OF 6" IN DEPTH. CLEANED AREA AND POURED CONCRETE. 5/6/2024 ARRIVED TO PROVIDED ADDRESS. DUG OUT AREA BY HAND, TO A GRADE OF 6".

CLEANED AREA AND POURED CONCRETE.

	Description		Qty	Price	Amount
Material					
	H&H CONCRETE 11292		1.00	1,797.5995	1,797.60
		Material			1,797.60
			Service O	rder Total:	1,797.60

4220884

**H&H Concrete on Demand Austin LLC** 

31840 Ranch Road 12 Dripping Springs, TX 78620 512.893.3000 accounting@hhconcreteatx.com



# **INVOICE**

**BILL TO** 

Crossroads Utility Services United States

**SHIP TO** 

4814 Rollingwood Dr, Rollingwood, TX 78746 INVOICE # 11292

**DATE** 05/06/2024 **DUE DATE** 05/21/2024

**TERMS** Net 15

PO

4814 Rollingwood Dr, Rollingwoo

Fast Setting HHG55NA  Delivery Fee	DESCRIPTION  Ticket #46607 - FAST SETTING FLOWABLE FILL - 6 yard minimum (HHG55NA)	QTY 6	169.00	AMOUNT 1,014.00T	
HHG55NA	FLOWABLE FILL - 6 yard minimum (HHG55NA)	6	169.00	1,014.00T	
Delivery Fee	Deliner, Fee				
	Delivery Fee	1	250.00	250.00T	
Standing Time	Standing Time - 60 minutes over the allotted ONE hour per truck. Truck #8627 arrived at 11 & departed at 1pm	60	3.00	180.00T	
	SUBTOTAL TAX TOTAL BALANCE DUE		\$1	1,444.00 119.13 1,563.13	
	Standing Time	allotted ONE hour per truck. Truck #8627 arrived at 11 & departed at 1pm  SUBTOTAL TAX TOTAL	allotted ONE hour per truck. Truck #8627 arrived at 11 & departed at 1pm  SUBTOTAL TAX TOTAL	allotted ONE hour per truck. Truck #8627 arrived at 11 & departed at 1pm  SUBTOTAL TAX TOTAL	allotted ONE hour per truck. Truck #8627 arrived at 11 & departed at 1pm  SUBTOTAL 1,444.00 TAX 119.13 TOTAL 1,563.13