



Distribution System -- 4th Quarter - October, November, and December 2023

Street Valves and Hydrant Valves Installed (including water main projects and others)

| Location | Date Installed | Size ("), Jt | Installed By | Type |
|--|----------------|--------------|--------------|-------|
| 72 Park Ave - Filter Plant Suction Well Area | 10/15/2023 | 20" LJ | SWU | B/F-N |

Total Valves Installed = 1

Street Valves and Hydrant Valves Removed

| Location | Installed | Abandoned | Type |
|----------|-----------|-----------|------|
|----------|-----------|-----------|------|

Total Valves Removed = 0

Street Valves and Hydrant Valves Abandoned

| Location | Installed | Abandoned |
|--|------------|------------|
| 72A Park Ave. on N. discharge (north of pump sta.) | 1908-1928? | 10/15/2023 |

Total Valves Abandoned = 1

Street Valves and Hydrant Valves Maintained

| Location | Maintained | Size | By |
|----------|------------|------|----|
|----------|------------|------|----|

Total Valves Maintained = 0

Hydrants Installed (including water main projects and others)

| Location | Installed | Tr Size | Valve | By |
|----------|-----------|---------|-------|----|
|----------|-----------|---------|-------|----|

Total Hydrants Installed = 0

Hydrants Removed (including water main projects and others)

| Location | Installed | Removed | Hyd Valve? |
|----------|-----------|---------|------------|
|----------|-----------|---------|------------|

Total Hydrants Removed = 0

Hydrants Abandoned (including water main projects and others)

| Location | Installed | Abandoned | Tr Size | Hyd Valve? |
|----------|-----------|-----------|---------|------------|
|----------|-----------|-----------|---------|------------|

Total Hydrants Abandoned = 0

Hydrants Maintained/Moved (including water main projects and others)

| Location | Installed | Maintained |
|----------|-----------|------------|
|----------|-----------|------------|

Total Hydrants Maintained/Moved = 0

Water Main Breaks

| Location | Date | Size |
|--------------------|------------|------|
| 2411 Ontario Ave | 11/30/2023 | 6" |
| 813 S. 16th street | 12/7/2023 | 6" |

Number of Water Main Breaks=2

SUMMARY

| | | |
|---|------|------------|
| Number of feet of 4 inch water main installed | 0.0 | water main |
| Number of feet of 6 inch hydrant lead installed | 0.0 | |
| Number of feet of 6 inch water main installed | 0.0 | |
| Number of feet of 8 inch water main installed | 0.0 | |
| Number of feet of 12 inch water main installed | 36.5 | |
| Number of feet of 16 inch water main installed | 0.0 | |
| Number of feet of 20 inch water main installed | 0.0 | |
| Number of feet of 24 inch water main installed | 0.0 | |
| Number of feet of water main abandoned or removed | 0.0 | |
| Number of water main breaks repaired | 2 | |
| Number of hydrants installed | 0 | hydrants |
| Number of hydrants removed or abandoned | 0 | |
| Number of hydrants maintained or moved | 0 | |
| Number of street valves installed | 1 | valves |
| Number of hydrant valves installed | 0 | |
| Number of street valves removed or abandoned | 1 | |
| Number of hydrant valves removed or abandoned | 0 | |
| Number of valves maintained | 4 | |
| Number of water connections installed | 10 | |



WATER MAIN AND APPURTENANCES INSTALLATION -- 4th Quarter -October, November, & December 2023

Water Main Projects (including installation or abandonment of more than 3' of pipe by utility or contractors)

| Location: 12" Water Main | Installed | New Valves | New Hyd. | New Hyd Valves | Aband. Valves | Aband. Hyd. | Remove Hyd. | Size " | Feet Installed | New Hyd Lead | Size Aband. | Feet. Aband. | Feet. Rem. | By |
|--------------------------|-----------|------------|----------|----------------|---------------|-------------|-------------|--------|----------------|--------------|-------------|--------------|------------|-----|
| Gateway Dr North Tie in | 10/2/2023 | 0 | 0 | 0 | 0 | 0 | 0 | 12 | 36.5 | 0 | | 0 | 0 | SWU |
| Totals: | | 0 | 0 | 0 | 0 | 0 | 0 | | 36.5 | 0 | | 0 | 0 | |