



MONTHLY DISTRIBUTION DEPARTMENT REPORT

February 2024

Distribution System Maintenance:

- Repaired water main breaks throughout the city.
- Completed hydrant checks.
- Replaced fire hydrant that was damaged in auto collision.

Building/Grounds Maintenance:

- Aided Operations in cap replacement of Filters #3 and #4.
- Continued rebuild of meter shop office and main office remodels
- Power supply for garage and shop area was upgraded.

Engineering:

- Bids were received for the Lincoln Ave/Swift Ave, S 11th Street, and Dillingham Avenue LSL projects.
- Updates continued in preparation to meet the WDNR LSL inventory requirement.
- Initial assessment of watermain infrastructure needs for Poth Development.
- Monthly map and database updates.



Distribution System -- February 2024

Street Valves and Hydrant Valves Installed (including water main projects and others)

Location	Date Installed	Size ("), Jt	Installed By	Type
----------	----------------	--------------	--------------	------

Total Valves Installed = 0

Street Valves and Hydrant Valves Removed

Location	Installed	Abandoned	Type
----------	-----------	-----------	------

Total Valves Removed = 0

Street Valves and Hydrant Valves Abandoned

Location	Installed	Abandoned
----------	-----------	-----------

Total Valves Abandoned = 0

Street Valves and Hydrant Valves Maintained

Location	Maintained	Size	By
----------	------------	------	----

Total Valves Maintained = 0

Hydrants Installed (including water main projects and others)

Location	Installed	Tr Size	Valve	By
N. 18th St. at Ontario Ave. (East)	2/22/2024	7'	n	SWU

Total Hydrants Installed = 1

Hydrants Removed (including water main projects and others)

Location	Installed	Removed	Hyd Valve?
N. 18th St. at Ontario Ave. (E)		2/22/2024	n

Total Hydrants Removed = 1

Hydrants Abandoned (including water main projects and others)

Location	Installed	Abandoned	Tr Size	Hyd Valve?
----------	-----------	-----------	---------	------------

Total Hydrants Abandoned = 0

Hydrants Maintained/Moved (including water main projects and others)

Location	Installed	Maintained
----------	-----------	------------

Total Hydrants Maintained/Moved = 0

Water Main Breaks

Location	Date	Size
3112 S. 9th St.	2/2/2024	6"
2004 N. 4th St.	2/9/2024	6"
2506 S. 16th St.	2/12/2024	6"

Number of Water Main Breaks= 3

SUMMARY

Number of feet of 4 inch water main installed	0.0	water main
Number of feet of 6 inch hydrant lead installed	0.0	
Number of feet of 6 inch water main installed	0.0	
Number of feet of 8 inch water main installed	0.0	
Number of feet of 12 inch water main installed	0.0	
Number of feet of 16 inch water main installed	0.0	
Number of feet of 20 inch water main installed	0.0	
Number of feet of 24 inch water main installed	0.0	
Number of feet of water main abandoned or removed	0.0	
Number of water main breaks repaired	3	hydrants
Number of hydrants installed	1	
Number of hydrants removed or abandoned	1	
Number of hydrants maintained or moved	0	valves
Number of street valves installed	0	
Number of hydrant valves installed	0	
Number of street valves removed or abandoned	0	
Number of hydrant valves removed or abandoned	0	
Number of valves maintained	0	
Number of water connections installed	0	

