

MONTHLY CONSTRUCTION-MAINTENANCE DEPARTMENT REPORT

June 2022

Distribution System Maintenance:

- Worked with Operations to isolate the transmission line running through the RWI site.
- Completed cut and cap on St. Clair Avenue in preparation for the water main installation in July.
- Replaced/moved three fire hydrants on North Avenue. This work was to accommodate new ADA ramps that the city is installing.
- Moved one hydrant on North Avenue. This work was to accommodate new ADA ramps that the city is installing.
- Completed leak correlation in Stonebrook Subdivision. There is some concern with street settling. No leaks found on the piping.
- Continued pouring permanent service repair holes for the season.
- Hauled in fill to replenish stock.
- Constructed, disinfected, tested, and installed temporary water service to the homes on the 1200 block of St. Clair Avenue ahead of the water main replacement project.
- Adjusted valve boxes ahead of the city's resurfacing of Moenning Road north of Weeden Creek.

Building/Grounds Maintenance:

- General shop maintenance and cleaning.
- Grading at Georgia Avenue site in preparation for grass seeding.
- Worked with Operations to install a hydrant-to-hydrant connection to aid in supplying generator feed water during a power outage.

Water Quality:

- Monitored and adjusted auto flushers in the system.
- Continued weekly/monthly dead end hydrant flushing.

Taps:

- 1" tap at 2211 S 12th St. Lead Service was removed from the system.
- 1" tap at 2212 S 12th St. Lead Service was removed from the system.

Equipment Maintenance:

- Performed routine maintenance and repairs on construction equipment and vehicle fleet.
- Replaced fuel pump on our Vac Trailer.



Distribution System -- June 2022

Street Valves and Hydrant Valves Installed (including water main projects and others)

| Location | | Data Installed | Size ("), Jt | Installed By | Tumo |
|----------|--|----------------|--------------|--------------|------|
| Location | | Date Installed | Size (), Jt | Histalieu Dy | Type |

 $Total\ Valves\ Installed = 0$

Street Valves and Hydrant Valves Removed

|--|

Total Valves Removed = 0

Street Valves and Hydrant Valves Abandoned

| Location Installed Abandoned |
|------------------------------|
|------------------------------|

 $Total\ Valves\ Abandoned = 0$

Street Valves and Hydrant Valves Maintained

| Location | Maintained | Size | By |
|----------|------------|------|----|

Total Valves Maintained = 0

Hydrants Installed (including water main projects and others)

| Location | Installed | Tr Size | Valve | Ву |
|-------------------------------|-----------|---------|-------|------|
| North Ave and N. 27th St (NW) | 6/15/2022 | 7'0" | n | SWU |
| North Ave and N. 26th St (NW) | 6/15/2022 | 6'0" | n | SWU |
| North Ave and N 28th St (SE) | 6/22/2022 | 6'6" | n | SWII |

 $Total\ Hydrants\ Installed=3$

Hydrants Removed (including water main projects and others)

| Location | Installed | Removed | Hyd Valve? |
|--------------------------------|-----------|-----------|------------|
| N. 27th St. at North Ave. (NW) | 12/1/1952 | 6/15/2022 | n |
| N. 26th St. at North Ave. (NW) | 7/1/1955 | 6/15/2022 | n |
| North Ave. at N. 28th St. (SE) | 7/1/1921 | 6/22/2022 | n |

Total Hydrants Removed = 3

Hydrants Abandoned (including water main projects and others)

| Location | Installed | Abandoned | Tr Size | Hvd Valve? | i |
|----------|-----------|-----------|---------|------------|---|
| | | | | | |

 $Total\ Hydrants\ Abandoned=0$

Hydrants Maintained/Moved (including water main projects and others)

| Location | | Installed | Maintained |
|------------------------------|--|-----------|------------|
| North Ave at N. 25th St (SW) | | 7/20/2016 | 6/15/2022 |

Total Hydrants Maintained/Moved = 1

Water Main Breaks

| Location | Date | Size |
|----------|------|------|

Number of Water Main Breaks= 0

SUMMARY

| BUNINAKI | | |
|---|-----|------------|
| Number of feet of 4 inch water main installed | 0.0 | water main |
| Number of feet of 6 inch hydrant lead installed | 0.0 | |
| Number of feet of 6 inch water main installed | 0.0 | |
| Number of feet of 8 inch water main installed | 0.0 | |
| Number of feet of 12 inch water main installed | 0.0 | |
| Number of feet of 16 inch water main installed | 0.0 | |
| Number of feet of 20 inch water main installed | 0.0 | |
| Number of feet of 24 inch water main installed | 0.0 | |
| Number of feet of water main abandoned or removed | 0 | |
| Number of water main breaks repaired | 0 | |
| Number of hydrants installed | 3 | hydrants |
| Number of hydrants removed or abandoned | 3 | |
| Number of hydrants maintained or moved | 1 | |
| Number of street valves installed | 0 | valves |
| Number of hydrant valves installed | 0 | |
| Number of street valves removed or abandoned | 0 | |
| Number of hydrant valves removed or abandoned | 0 | |
| Number of valves maintained | 0 | |
| Number of water connections installed | 2 | |