



MONTHLY DISTRIBUTION DEPARTMENT REPORT

March 2024

Distribution System Maintenance:

- Started Service hole repair in the intersection of Bluff Ave and N 4th Street.
- Inspected hydrants ahead of annual painting.
- Turned valves in the distribution system as part of annual maintenance.

Building/Grounds Maintenance:

- Worked on conference room and office updates.
- Aided Operations in the installing filter media.

Equipment Maintenance:

- Performed routine maintenance and repairs on construction equipment and vehicle fleet.

Engineering:

- Inspection for S 11th Street LSL Project.
- Monthly map and database updates.



Distribution System -- March 2024

Street Valves and Hydrant Valves Installed (including water main projects and others)

Location	Date Installed	Size ("), Jt	Installed By	Type
----------	----------------	--------------	--------------	------

Total Valves Installed = 0

Street Valves and Hydrant Valves Removed

Location	Installed	Abandoned	Type
----------	-----------	-----------	------

Total Valves Removed = 0

Street Valves and Hydrant Valves Abandoned

Location	Installed	Abandoned
----------	-----------	-----------

Total Valves Abandoned = 0

Street Valves and Hydrant Valves Maintained

Location	Maintained	Size	By
----------	------------	------	----

Total Valves Maintained = 0

Hydrants Installed (including water main projects and others)

Location	Installed	Tr Size	Valve	By
Kentucky Ave. at S. 11th St. (SE)	3/19/2024	6'6"	n	SWU

Total Hydrants Installed = 1

Hydrants Removed (including water main projects and others)

Location	Installed	Removed	Hyd Valve?
Kentucky Ave. at S. 11th St. (SE)	10/14/1994	3/19/2024	n

Total Hydrants Removed = 1

Hydrants Abandoned (including water main projects and others)

Location	Installed	Abandoned	Tr Size	Hyd Valve?
----------	-----------	-----------	---------	------------

Total Hydrants Abandoned = 0

Hydrants Maintained/Moved (including water main projects and others)

Location	Installed	Maintained
----------	-----------	------------

Total Hydrants Maintained/Moved = 0

Water Main Breaks

Location	Date	Size
----------	------	------

Number of Water Main Breaks= 0


SUMMARY

Number of feet of 4 inch water main installed	0.0	water main
Number of feet of 6 inch hydrant lead installed	0.0	
Number of feet of 6 inch water main installed	0.0	
Number of feet of 8 inch water main installed	0.0	
Number of feet of 12 inch water main installed	0.0	
Number of feet of 16 inch water main installed	0.0	
Number of feet of 20 inch water main installed	0.0	
Number of feet of 24 inch water main installed	0.0	
Number of feet of water main abandoned or removed	0.0	
Number of water main breaks repaired	0	
Number of hydrants installed	1	hydrants
Number of hydrants removed or abandoned	1	
Number of hydrants maintained or moved	0	
Number of street valves installed	0	valves
Number of hydrant valves installed	0	
Number of street valves removed or abandoned	0	
Number of hydrant valves removed or abandoned	0	
Number of valves maintained	117	
Number of water connections installed	3	

Lead Service Line Dashboard (Board)



2024 Replacements



Lead Service Lines

5,658

Total

2024 Replacements

20.8%

to Target Goal

Replaced Lead Service Lines

21

This Month

Target Replacements

250

2024