

R. O. No. 49 - 22 - 23. By CITY CLERK. August 1, 2022.

Submitting a claim from Brandon L. Parker for alleged damages to his vehicle when a City of Sheboygan tree fell on it.

CITY CLERK

DATE RECEIVED

07/12/2022

RECEIVED BY

MKC

JUL 19 2022

CLAIM NO.

11-22

CITY OF SHEBOYGAN NOTICE OF DAMAGE OR INJURY

INSTRUCTIONS: TYPE OR PRINT IN BLACK INK

1. Notice of death, injury to persons or to property must be filed not later than 120 days after the occurrence.
2. Attach and sign additional supportive sheets, if necessary.
3. This notice form must be signed and filed with the Office of the City Clerk.

4. **TWO ESTIMATES MUST BE ATTACHED IF YOU ARE CLAIMING DAMAGE TO A VEHICLE.**

1. Name of Claimant: Brandon L Parker
2. Home address of Claimant: 1028 A Superior Ave, Sheboygan WI 53081
3. Home phone number: 920-627-5113
4. Business address and phone number of Claimant: (920) 627-5113, 1028 A Superior Ave, Sheboygan WI 53081
5. When did damage or injury occur? (date, time of day) 07/11/2022 8:30 PM
6. Where did damage or injury occur? (give full description) Driver side Head light Driver side Fender
7. How did damage or injury occur? (give full description) A City tree Fell on top of the car
8. If the basis of liability is alleged to be an act or omission of a City officer or employee, complete the following:
 - (a) Name of such officer or employee, if known: Mitchell Leckie
 - (b) Claimant's statement of the basis of such liability: City tree Fell on top of my car
9. If the basis of liability is alleged to be a dangerous condition of public property, complete the following:
 - (a) Public property alleged to be dangerous: City tree
 - (b) Claimant's statement of basis for such liability: every big storm the tree falls a part

10. Give a description of the injury, property damage or loss, so far as is known at this time. (If there were no injuries, state "NO INJURIES").

Driver side Fender, hood, headlight

11. Name and address of any other person injured:

NO ONE WAS INJURED

12. Damage estimate: (You are not bound by the amounts provided here.)

Auto:

\$ ~~2,678.35~~ BP 4,084.89

Property:

\$ _____

Personal injury:

\$ _____

Other: (Specify below)

\$ _____

TOTAL

\$ ~~2,678.35~~ BP 4,084.89


Damaged vehicle (if applicable)

Make: PONTIAC Model: GRANDAM Year: 1996 Mileage: 89,899

Names and addresses of witnesses, doctors and hospitals: Morgan Parker
1028 A Superior Ave, Sheboygan WI, 53081

FOR ALL ACCIDENT NOTICES, COMPLETE THE FOLLOWING DIAGRAM IN DETAIL. BE SURE TO INCLUDE NAMES OF ALL STREETS, HOUSE NUMBERS, LOCATION OF VEHICLES, INDICATING WHICH IS CITY VEHICLE (IF APPLICABLE), WHICH IS CLAIMANT VEHICLE, LOCATION OF INDIVIDUALS, ETC.

NOTE: If diagrams below do not fit the situation, attach proper diagram and sign.



SIGNATURE OF CLAIMANT

Brendon Parker

DATE

07/11/2022

DATE RECEIVED _____

RECEIVED BY _____

CLAIM NO. _____

CLAIM

Claimant's Name:

Brandon L Parker

Auto

\$

4,084.89

Claimant's Address:

~~1028~~ 1028 A Superior Ave, Sheboygan WI 53081

Property

\$

Personal Injury

\$

Claimant's Phone No.

(920) 627-5113

Other (Specify below) \$

TOTAL

\$

4,084.89

PLEASE INCLUDE COPIES OF ALL BILLS, INVOICES, ESTIMATES, ETC.

WARNING: IT IS A CRIMINAL OFFENSE TO FILE A FALSE CLAIM.
(WISCONSIN STATUTES 943.395)

The undersigned hereby makes a claim against the City of Sheboygan arising out of the circumstances described in the Notice of Damage or Injury. The claim is for relief in the form of money damages in the total amount of \$ ~~6,767.27~~ 4,084.89

SIGNED

Brandon Parker

DATE:

07/19/2022

ADDRESS:

1028 A Superior Ave, Sheboygan WI 53081

MAIL TO: CLERK'S OFFICE
828 CENTER AVE #100
SHEBOYGAN WI 53081

**SHEBOYGAN CHEVROLET BUICK
GMC CADILLAC**

3400 S BUSINESS DR, SHEBOYGAN, WI 53081
Phone: (920) 459-6855
FAX: (920) 459-6286

Workfile ID: 40d39e7c
PartsShare: 6S3BhD
Federal ID: 83-0747810

Preliminary Estimate

Customer: PARKER, BRANDON

Job Number:

Written By: Scott Stolper

Insured: PARKER, BRANDON
Type of Loss:
Point of Impact: 16 Non-Collision

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:

PARKER, BRANDON

1028 A SUPERIOR AVE
SHEBOYGAN, WI 53081
(920) 627-5113 Cell

Inspection Location:

SHEBOYGAN CHEVROLET BUICK GMC
CADILLAC
3400 S BUSINESS DR
SHEBOYGAN, WI 53081
Repair Facility
(920) 459-6855 Business

Insurance Company:

VEHICLE

1996 PONT Grand Am SE 2D CPE 4-2.4L Gasoline SFI PURPLE

VIN: 1G2NE12T6TM562961
License: AJW6700
State: WI

Interior Color:
Exterior Color: PURPLE
Production Date: 5/1996

Mileage In: 90,204
Mileage Out:
Condition:
Vehicle Out:
Job #:

TRANSMISSION

Overdrive
5 Speed Transmission

POWER

Power Steering
Power Brakes
Power Locks

DECOR

Dual Mirrors

Body Side Moldings

Tinted Glass
Console/Storage
Overhead Console

RADIO

AM Radio
FM Radio
Stereo
Search/Seek

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)

SEATS

Cloth Seats
Bucket Seats
Reclining/Lounge Seats

WHEELS

Wheel Covers

PAINT

Clear Coat Paint

OTHER

Fog Lamps
Power Trunk/Liftgate

Get live updates at www.carwise.com/e/4hZBRL

Preliminary Estimate

Customer: PARKER, BRANDON

Job Number:

1996 PONT Grand Am SE 2D CPE 4-2.4L Gasoline SFI PURPLE

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		FRONT BUMPER					
2	*	R&I R&I bumper assy				0.7	
		Note: DROP LT SIDE OF FASCIA					
3		FRONT LAMPS					
open	Repl	LT Headlamp assy	16524657	1	149.65	0.6	
5		Aim headlamps				0.5	
6	R&I	RT Headlamp assy				0.6	
7		HOOD					
open	Repl	Hood	22591596	1	673.33	1.0	3.2
9		Add for Clear Coat					1.3
10		Add for Underside(Complete)					1.6
11		FENDER					
open	Repl	LT Fender	22659559	1	190.95	2.5	2.5
13		Overlap Major Adj. Panel					-0.4
14		Add for Clear Coat					0.4
15		Add for Edging					0.5
16		Add for Clear Coat					0.1
17		Deduct for Overlap				-0.4	
18	R&I	LT Lower molding SE				0.3	
19	*	Rpr RT Fender				2.0	2.5
20		Overlap Major Adj. Panel					-0.4
21		Add for Clear Coat					0.4
22		DOOR					
23	*	Rpr RT Outer panel				2.0	2.3
24		Overlap Major Adj. Panel					-0.4
25		Add for Clear Coat					0.4
26	*	Rpr LT Outer panel				2.0	2.3
27		Overlap Major Adj. Panel					-0.4
28	*	Add for Clear Coat					0.4
29	R&I	RT Body side mldg SE				0.3	
30	R&I	LT Body side mldg SE				0.3	
31	R&I	RT Mirror assy manual SE				0.3	
32	R&I	LT Mirror assy manual SE				0.3	
33	*	R&I RT Run channel				0.2	
34	*	R&I LT Run channel				0.2	
35	R&I	RT Door glass GM				0.6	
36	R&I	LT Door glass GM				0.6	
37	R&I	RT Handle, outside				0.3	
38	R&I	LT Handle, outside				0.3	
39	R&I	RT Door trim panel				0.6	
40	R&I	LT Door trim panel				0.6	
41		MISCELLANEOUS OPERATIONS					

Preliminary Estimate

Customer: PARKER, BRANDON

Job Number:

1996 PONT Grand Am SE 2D CPE 4-2.4L Gasoline SFI PURPLE

42	#	Subl	Hazardous waste removal	1	3.00 T		
43	#		Clean & re-tape mldg(s)	1		0.5	
44	#	Repl	Cover Car	1	5.00 T		
45	#	Repl	PIN STRIPES	1	45.00	1.0	
SUBTOTALS					1,066.93	17.9	16.3

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts				1,058.93
Body Labor	17.9 hrs	@	\$ 62.00 /hr	1,109.80
Paint Labor	16.3 hrs	@	\$ 62.00 /hr	1,010.60
Paint Supplies	16.3 hrs	@	\$ 42.00 /hr	684.60
Miscellaneous				8.00
Subtotal				3,871.93
Sales Tax	\$ 3,871.93	@	5.5000 %	212.96
Grand Total				4,084.89
Deductible				0.00
CUSTOMER PAY				0.00
INSURANCE PAY				4,084.89

MyPriceLink Estimate ID / Quote ID:

978697756208013312 / 108822083

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATPC 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.

Preliminary Estimate

Customer: PARKER, BRANDON

Job Number:

1996 PONT Grand Am SE 2D CPE 4-2.4L Gasoline SFI PURPLE

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DE1FQ92, CCC Data Date 07/18/2022, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinishing operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2022 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Preliminary Estimate

Customer: PARKER, BRANDON

Job Number:

1996 PONT Grand Am SE 2D CPE 4-2.4L Gasoline SFI PURPLE

ALTERNATE PARTS USAGE

1996 PONT Grand Am SE 2D CPE 4-2.4L Gasoline SFI PURPLE

VIN: 1G2NE12T6TM562961 Interior Color: Mileage In: 90,204 Vehicle Out:
License: AJW6700 Exterior Color: PURPLE Mileage Out:
State: WI Production Date: 5/1996 Condition: Job #:

Alternate Part Type	Selection Method	# Of Times Notified Of Available Parts	# Of Parts Selected
Aftermarket	Automatically List	0	0
Optional OEM	Manually List	0	0
Reconditioned	Manually List	0	0
Recycled	N/A	0	0

GEORGIA AVENUE BODY SHOP, INC.
1819 GEORGIA AVENUE
SHEBOYGAN, WI 53081
PHONE: (920)458-3272 FAX: (920)458-3284

*** PRELIMINARY ESTIMATE ***

07/12/2022 01:36 PM

Owner

Owner: Brandon Parker
Address: 1028A Superior Avenue
City State Zip: Sheboygan, WI 53081

Work/Day: (920)627-5113
FAX:

Inspection

Inspection Date: 07/12/2022 01:36 PM
Primary Impact: Left Front Side

Inspection Type:
Secondary Impact: Right Side

Contact: James Miller

Repairer

Repairer: Georgia Ave Body Shop
Address: 1819 Georgia ave
City State Zip: Sheboygan, WI 53081
Email: gabs@gabsinc.biz

Contact: GEORGIA AVENUE
Work/Day: (920)458-3272
FAX: (920)458-3284
Work/Day:

Target Complete Date/Time:

Days To Repair: 8

Vehicle

OEM Part Price Quote ID: ****

1996 Pontiac Grand Am SE 2 DR Coupe
4cyl Gasoline 2.4
4 Speed Automatic

Lic.Plate: AJW-6750
Lic Expire:
Veh Insp# :
Condition: Good
Ext. Color: Violet
Ext. Refinish: Two-Stage

Lic State: WI
VIN: 1G2NEI2T6TM562961
Mileage Type: Actual
Code: W3312A
Int. Color:
Int. Refinish: Two-Stage

Options

AM/FM Stereo
Center Console
Lighted Entry System
Power Door Locks
Tachometer

Anti-Lock Brakes
Dual Airbags
Overhead Console
Power Steering
Tinted Glass

Bucket Seats
Fog Lights
Power Brakes
Rem Trunk-L/Gate Release
Velour/Cloth Seats

Damages

Line Op	Guide	MC Description	MFR.Part No.	Price	ADJ% B%	Hours	R
---------	-------	----------------	--------------	-------	---------	-------	---

Stripes And Mouldings

1	RI	269	Mldg,Front Door Side RT	R & I Assembly		0.3	SM
---	----	-----	-------------------------	----------------	--	-----	----

Front End Panel And Lamps

2	E	41	02	Headlamp Assy,Halogen LT	16524657 GM Part	\$149.65	INC	SM
3	N	973		Headlamps Aim	Additional Labor		0.4	SM

Front Body And Windshield

4	I	83		Panel,Hood	Repair		4.0*	SM
5	L	83	13	Panel,Hood	Refinish		4.2	RF
					3.0 Surface			
					0.6 Two-stage setup			
					0.6 Two-stage			
6	RI	83		Hood Panel R & I	R & I Assembly		0.7	SM
7	E	103	02	Fender,Front LT	22659559 GM Part	\$190.95	2.1	SM
8	L	103		Fender,Front LT	Refinish		2.9	RF
					1.9 Surface			
					0.5 Edge			
					0.5 Two-stage			

Front Doors

9	RI	208		Front Door R&I RT	R & I Assembly		1.2	SM
10	I	208		Door Shell,Front RT	Repair		3.0*	SM
11	L	208		Door Shell,Front RT	Refinish		2.8	RF
					2.3 Surface			
					0.5 Two-stage			
12	RI	232		Pnl,Inner Door Trim RT	R & I Assembly		INC	SM
13	RI	230		Mirror,Outer Standard RT	R & I Assembly		0.3	SM
14	RI	228		Handle,Front Door Otr RT	R & I Assembly		1.5	SM

Manual Entries

15	L	M14		Corrosion Protection	Refinish	\$25.00*	1.0*	RF
				>> MULTIPLE AREAS				
16	N	M30		Collision Repair Material	Additional Labor	\$48.00*		SM
17	N	M60		Hazardous Waste Removal	Additional Labor	\$5.25*		SM
18	RI			BELT MOLDING	R & I Assembly		0.5*	SM*
18	Items							

MC Message

02	PART NO. DISCONTINUED, CALL DEALER FOR EXACT PART NO.
13	INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

OEM Parts		\$340.60	
Other Parts		\$78.25	
Paint & Materials	10.9 Hours @ \$46.00	\$501.40	
Parts & Material Total			\$920.25
Tax on Parts & Material	@ 5.500%		\$50.61

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$65.00	6.6	7.4	14.0	\$910.00
Mech/Elec (ME)	\$90.00				
Frame (FR)	\$80.00				
Refinish (RF)	\$65.00	10.9		10.9	\$708.50

Labor Total	24.9 Hours	\$1,618.50
-------------	------------	------------

Tax on Labor	@ 5.500%	\$89.02	
Gross Total			\$2,678.38
Net Total			\$2,678.38

Alternate Parts Y/00/00/00/00/00 Cumulative 00/00/00/00/00 Zip Code: 53081 Default
OEM Part Prices DT 07/12/2022 01:36 PM EstimateID 976191425634902016 QuoteID ****
Recycled Parts NOT REQUESTED
Rate Name Default

Audatex Estimating 8.1.325 Update 7 ES 07/12/2022 01:42 PM REL 8.1.325 Update 7 DT 05/01/2022 DB 07/08/2022
State Disclosure:WI
© 2022 Audatex North America, Inc.

2.2 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

Op Codes

* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = Replace OEM
NG = Replace NAGS	EC = Replace Economy	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = Replace PXN
EU = Replace Recycled	TE = Partial Replace Price	PM = Replace PXN Reman/Reblt
UM = Replace Reman/Rebuilt	L = Refinish	PC = Replace PXN Reconditioned
UC = Replace Reconditioned	TT = Two-Tone	SB = Sublet Repair
N = Additional Labor	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG = Chipguard	RI = R & I Assembly
P = Check	AA = Appearance Allowance	RP = Related Prior Damage



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2022 Audatex North America, Inc.
AUDATEX is a trademark owned by Audatex
North America, Inc. All rights reserved.

