

## **MONTHLY CONSTRUCTION-MAINTENANCE DEPARTMENT REPORT**

**February 2022**

### **Distribution System Maintenance:**

- Repaired a hydrant that was struck by an automobile.
- Repaired multiple main breaks throughout the city.
- Repaired a problematic light outside of the office.
- Fabricated new hydrant barrels on the milling machine.
- Fabricated hydrant boxes for bulk water sales.
- Poured and maintained service holes throughout the city.
- Hauled in fill to replenish stock.
- Worked on refurbishing salvaged hydrants.

### **Building/Grounds Maintenance:**

- General shop maintenance and cleaning.
- Snow removal at all Water Utility sites.
- General cleanup and organization in the Johnson Shed.

### **Equipment Maintenance:**

- Performed routine maintenance and repairs on construction equipment and vehicle fleet.

### **Training:**

- Attended Wisconsin AWWA Distribution Conference in Wisconsin Dells.
- Josh S. passed his CDL test.

## Distribution System -- February 2022

### Street Valves and Hydrant Valves Installed (including water main projects and others)

Location	Date Installed	Size ("), Jt	Installed By	Type
----------	----------------	--------------	--------------	------

Total Valves Installed = 0

### Street Valves and Hydrant Valves Removed

Location	Installed	Abandoned	Type
----------	-----------	-----------	------

Total Valves Removed = 0

### Street Valves and Hydrant Valves Abandoned

Location	Installed	Abandoned
----------	-----------	-----------

Total Valves Abandoned = 0

### Street Valves and Hydrant Valves Maintained

Location	Maintained	Size
----------	------------	------

Total Valves Maintained = 0

### Hydrants Installed (including water main projects and others)

Location	Installed	Tr Size	Valve	By
----------	-----------	---------	-------	----

N 4th Street and St. Clair Avenue

Total Hydrants Installed = 0

### Hydrants Removed (including water main projects and others)

Location	Installed	Removed	Hyd Valve?
----------	-----------	---------	------------

Total Hydrants Removed = 0

### Hydrants Abandoned (including water main projects and others)

Location	Installed	Abandoned	Tr Size	Hyd Valve?
----------	-----------	-----------	---------	------------

Total Hydrants Abandoned = 0

### Hydrants Maintained/Moved (including water main projects and others)

Location	Installed	Maintained
----------	-----------	------------

Total Hydrants Maintained/Moved = 0

### Water Main Breaks

Location	Date	Size
2125 S. Memorial Place	2/12/2022	6"
N.28th St. and Michigan Ave	2/15/2022	6"
N. 6th St. and Michigan Ave	2/17/2022	6"
S.22nd St 150' North of Georgia Ave	2/17/2022	12"
S.12th St and Washington Ave	2/22/2022	10"
S.19th St. south of Union Ave	2/23/2022	6"
1736 Marvin Ct	2/24/2022	6"
N.12th St. + Superior Ave	2/25/2022	6"

Total Water Main Breaks = 8

### SUMMARY

Number of feet of 4 inch water main installed	0.0	water main
Number of feet of 6 inch hydrant lead installed	0.0	
Number of feet of 6 inch water main installed	0.0	
Number of feet of 8 inch water main installed	0.0	
Number of feet of 12 inch water main installed	0.0	
Number of feet of 16 inch water main installed	0.0	
Number of feet of 20 inch water main installed	0.0	
Number of feet of 24 inch water main installed	0.0	
Number of feet of water main abandoned or removed	0	hydrants
Number of water main breaks repaired	8	
Number of hydrants installed	0	
Number of hydrants removed or abandoned	0	valves
Number of hydrants maintained or moved	0	
Number of street valves installed	0	
Number of hydrant valves installed	0	
Number of street valves removed or abandoned	0	
Number of hydrant valves removed or abandoned	0	
Number of valves maintained	0	
Number of water connections installed	0	